

FACILITY CONDITION ASSESSMENT

HMC Architects JURUPA UNIFIED SCHOOL DISTRICT 3546 Concours Street Ontario, California 91764



INA ARBUCKLE ELEMENTARY SCHOOL 3600 Packard Street Jurupa Valley, CA 92509

PREPARED BY:

EMG | A Bureau Veritas Company 10461 Mill Run Circle, Suite 1100 Owings Mills, Maryland 21117 800.733.0660 www.emgcorp.com

EMG CONTACT:

Mark Surdam Program Manager 800.733.0660 x6251 msurdam@emgcorp.com

EMG PROJECT #:

139069.19R000-006.354

DATE OF REPORT:

November 26, 2019

ON SITE DATE:

October 3, 2019





TABLE OF CONTENTS

Executive Summary	2
Campus Overview and Assessment Details	2
Buildings	2
Plan Types	5
Key Findings	
System Expenditure Forecast	10
Building C,D,E,F & G Systems Summary	
Building H Sytems Summary	15
Portable Classrooms Systems Summary	
·	
Definitions	25
	System Expenditure Forecast Building A-B Systems Summary

1. Executive Summary

Campus Overview and Assessment Details

General Information	
Main Address	3600 Packard Street, Jurupa Valley, CA 92509
Site Developed	1956 Renovated 2018
Property Type	Elementary School
Current Occupants	1300
Building Area	88,000 SF
Number of Buildings	8
Date(s) of Visit	10/3/2019
Management Point of Contact	Jurupa Unified School District Robin Griffin, Director, Planning & Development T 951.361.6571 robin_griffin@jusd.k12.ca.us
On-site Point of Contact (POC)	NA
Assessment and Report Prepared By	Mark Surdam
Reviewed By	Kathleen Sullivan, Technical Report Reviewer for Mark Surdam Program Manager msurdam@emgcorp.com 800.733.0660 x6251

Buildings

Building Summary			
Building	Use	Constructed	Area(SF)
Building A-B	Administration, Library & Cafeteria	2018	8504
Building C	Classrooms	2018	4180
Building D	Classrooms	2018	3790
Building E	Classrooms	2018	3790
Building F	Classrooms	2018	3790

Building Summary			
Building	Use	Constructed	Area(SF)
Building G	Classrooms	2018	3790
Building H	Classrooms	2018	7183
Portable P21	Classrooms	Unknown	882
Portable P22	Classrooms	Unknown	882
Portable P23	Classrooms	Unknown	882
Portable P24	Classrooms	Unknown	882
Portable P25	Classrooms	Unknown	882
Portable P26	Classrooms	Unknown	882
Portable P27	Classrooms	Unknown	882
Portable P28	Classrooms	Unknown	882
Portable P29	Classrooms	Unknown	882
Portable P30	Classrooms	Unknown	882
Portable P31	Classrooms	Unknown	882
Portable P32	Classrooms	Unknown	882
Portable P33	Classrooms	Unknown	882
Portable P34	Classrooms	Unknown	1253
Portable P35	Classrooms	Unknown	1253
Portable P36	Classrooms	Unknown	1253
Portable P37	Classrooms	Unknown	882
Portable P38	Classrooms	Unknown	882
Portable P39	Classrooms	Unknown	882
Portable P40	Classrooms	Unknown	882
Portable P41	Classrooms	Unknown	882
Portable Restrooms	Classrooms	Unknown	600
TOTAL			55,262

Unit Allocation

All of the property is occupied by the Jurupa Unified School District programs. There are no tenants leasing buildings or rooms at the school.

Areas Observed

The interior spaces were observed in order to gain a clear understanding of the property's overall condition. Other areas accessed included the site within the property boundaries, the exterior of the property, and the roofs.

Key Spaces Not Observed


All key areas of the property were accessible and observed with the exception of the roof and RTUs due to safety concerns related to roof slope, slick type of coating and moisture.

Plan Types

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the "why" part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the "best" fit, typically the one with the greatest significance.

Plan Type Descriptio	ns
Safety	An observed or reported unsafe condition that if left unaddressed could result in injury; a system or component that presents potential liability risk.
Performance/Integrity	Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses risk to overall system stability.
Accessibility	■ Does not meet ADA, UFAS, and/or other handicap accessibility requirements.
Environmental	Improvements to air or water quality, including removal of hazardous materials from the building or site.
Retrofit/Adaptation	Components, systems, or spaces recommended for upgrades in in order to meet current standards, facility usage, or client/occupant needs.
Lifecycle/Renewal	Any component or system that is not currently deficient or problematic but for which future replacement or repair is anticipated and budgeted.

Plan Type Distribution (by Cost)



10-YEAR TOTAL: \$952,800

Campus Findings and Deficiencies

Historical Summary

Ina Arbuckle Elementary School was originally constructed in the mid 1950s. The buildings on the site were all completely remodeled, and one new administration building added in 2018.

Architectural

The original buildings were completely renovated at the time of Building H construction, including the exterior and interior finishes, all fixtures as well as complete roof, door and window replacements. For all the buildings, only typical lifecycle interior finish, exterior finish, and roof membrane replacements are budgeted and anticipated.

Mechanical, Electrical, Plumbing and Fire (MEPF)

Most MEPF systems and components are less than year old and appear well-maintained. Some HVAC and plumbing components such as RTUs and terminal units have required isolated replacements and are nearing the end of their anticipated lifecycles. The MEPF infrastructure itself is generally in good working condition with few expenditures anticipated in the short term.

Site

The parking lots and sidewalks have been repaved and sectionally replaced as-needed over the years. The exterior sports courts and open asphalt walk ways are in fair to poor condition and require resurfacing in some places. One larger playground structure was set on fire and vandalized therefore needing immediate replacement as well as the surrounding rubber ground surface.

Recommended Additional Studies

No additional studies recommended at this time.

Facility Condition Index (FCI)

One of the major goals of the FCA is to calculate each building's Facility Condition Index (FCI), which provides a theoretical objective indication of a building's overall condition. By definition, the FCI is defined as the ratio of the cost of current needs divided by current replacement value (CRV) of the facility. The chart below presents the industry standard ranges and cutoff points.

FCI Ranges and	FCI Ranges and Description				
0 – 5%	In new or well-maintained condition, with little or no visual evidence of wear or other deficiencies.				
5 – 10%	Subjected to wear but is still in a serviceable and functioning condition.				
10 – 30%	Subjected to hard or long-term wear. Nearing the end of its useful or serviceable life.				
30% and above	Has reached the end of its useful or serviceable life. Renewal is now necessary.				

The deficiencies and lifecycle needs identified in this assessment provide the basis for a portfolio-wide capital improvement funding strategy. In addition to the current FCI, extended FCI's have been developed to provide owners the intelligence needed to plan and budget for the "keep-up costs" for their facilities. As such the 3-year, 5-year, and 10-year FCI's are calculated by dividing the anticipated needs of those respective time periods by current replacement value. As a final point, the FCI's ultimately provide more value when used to relatively compare facilities across a portfolio instead of being overanalyzed and scrutinized as stand-alone values. The table below summarizes the individual findings for this FCA:

Facility (year built)	Cost/SF	Total SF	Replaceme nt Value	Current	3-Year	5-Year	10-Year
Building A-B (2018)	\$450	8,504	\$3,826,800	0.0%	0.0%	0.0%	2.3%
Building C (2018)	\$450	4,180	\$1,881,000	0.0%	0.0%	0.0%	3.3%
Building D (2018)	\$450	3,790	\$1,705,500	0.0%	0.0%	0.0%	3.8%
Building E (2018)	\$450	3,790	\$1,705,500	0.0%	0.0%	0.0%	3.8%
Building F (2018)	\$450	3,790	\$1,705,500	0.0%	0.0%	0.0%	4.0%
Building G (2018)	\$450	3,790	\$1,705,500	0.0%	0.0%	0.0%	3.7%
Building H (2018)	\$450	7,183	\$3,232,350	0.0%	0.0%	0.0%	1.5%
Portable P21	\$175	882	\$154,350	0.0%	0.0%	4.6%	12.4%
Portable P22	\$175	882	\$154,350	0.0%	0.0%	4.6%	12.4%
Portable P23	\$175	882	\$154,350	0.0%	0.0%	4.6%	12.4%
Portable P24	\$175	882	\$154,350	0.0%	0.0%	4.6%	12.4%
Portable P25	\$175	882	\$154,350	0.0%	0.0%	4.6%	12.4%


Facility (year built)	Cost/SF	Total SF	Replaceme nt Value	Current	3-Year	5-Year	10-Year
Portable P26	\$175	882	\$154,350	0.0%	0.0%	4.6%	12.4%
Portable P27	\$175	882	\$154,350	0.0%	0.0%	4.6%	12.4%
Portable P28	\$175	882	\$154,350	0.0%	0.0%	4.6%	13.1%
Portable P29	\$175	882	\$154,350	0.0%	0.0%	4.6%	12.4%
Portable P30	\$175	882	\$154,350	0.0%	0.0%	4.6%	12.4%
Portable P31	\$175	882	\$154,350	0.0%	0.0%	4.6%	12.4%
Portable P32	\$175	882	\$154,350	0.0%	0.0%	4.6%	12.4%
Portable P33	\$175	882	\$154,350	0.0%	0.0%	4.6%	12.4%
Portable P34	\$175	1,253	\$219,275	0.0%	0.0%	3.3%	11.1%
Portable P35	\$175	1,253	\$219,275	0.0%	0.0%	3.3%	11.1%
Portable P36	\$175	1,253	\$219,275	0.0%	0.0%	3.3%	11.1%
Portable P37	\$175	882	\$154,350	0.0%	0.0%	4.6%	12.4%
Portable P38	\$175	882	\$154,350	0.0%	0.0%	4.6%	12.4%
Portable P39	\$175	882	\$154,350	0.0%	0.0%	4.6%	12.4%
Portable P40	\$175	882	\$154,350	0.0%	0.0%	4.6%	12.4%
Portable P41	\$175	882	\$154,350	0.0%	0.0%	4.6%	12.4%
Portable Restrooms	\$175	600	\$105,000	0.0%	0.0%	0.0%	3.0%

The orange line in the graph below forecasts what would happen to the FCI (left axis) over time, assuming zero capital expenditures. The capital expenditures for each year (blue bars) are associated with the right axis.

Needs by Year with Unaddressed FCI Over Time

FCI Analysis: Ina Aruckle Elementary School

Replacement Value: \$ 24,867,900; Inflation rate: 3.0%



Immediate Needs

Facility/Building	Total Items	Total Cost
Ina Arbuckle Elementary School	1	\$38,745
Total	1	\$38,745

Ina Arbuckle Elementary School Detail

ID	Location	Location Description	UF Code	Description	Condition	Plan Type	Cost
1465677	Ina Arbuckle Elementary School / Site	Site	G2047	Play Structure, Large, Replace	Failed	Performance/Integrity	\$38,745
Total (1 ite	ems)						\$38,745

Key Findings



Parking Lots in Poor condition.

Asphalt Pavement Site

Uniformat Code: G2022

Recommendation: Cut & Patch in 2021

Priority Score: 87.0

Plan Type:

Performance/Integrity

Cost Estimate: \$38,700

\$\$\$\$

Significant amount of damage and wear. - AssetCALC ID: 1465680



Play Structure in Failed condition.

Large Site

Uniformat Code: G2047

Recommendation: Replace in 2019

Priority Score: 83.0

Plan Type:

Performance/Integrity

Cost Estimate: \$38,700


\$\$\$\$


The play set is not in use due to vandalism. It was set on fire. - AssetCALC ID: 1465677

System Expenditure Forecast

System	Immediate	Short Term (3 yr.)	Near Term (5 yr.)	Med Term (10 yr.)	Long Term (20 yr.)	TOTAL
Structure	-	-	-	\$4,100	\$5,500	\$9,600
Facade	-	-	-	\$162,000	\$757,800	\$919,800
Roofing	-	-	-	\$65,500	\$685,500	\$751,000
Interiors	-	-	-	\$419,200	\$707,800	\$1,127,000
Plumbing	-	-	-	\$14,300	\$73,000	\$87,300
HVAC	-	-	\$146,500	\$6,400	\$861,000	\$1,013,900
Electrical	-	-	-	\$2,900	\$587,700	\$590,600
Fire Alarm & Comm	-	-	-	-	\$174,800	\$174,800
Equipment/Special	-	-	-	\$32,800	\$18,400	\$51,200
Site Development	\$38,700	-	-	-	\$337,400	\$376,100
Pavement	-	\$41,100	\$16,800	\$19,500	\$48,800	\$126,200
TOTALS	\$38,700	\$41,100	\$163,300	\$726,700	\$4,257,700	\$5,227,500

1. Building A-B Systems Summary






	0000 Parkered Otracet, Islanda Nalland OA 00500	
Address	3600 Packard Street, Jurupa Valley, CA 92509	
Constructed/Renovated	1956/ 2018	
Building Size	8,504 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood and steel frame structure on concrete slab with concrete-topped metal decks	Good
Façade	Stucco with aluminum windows Dry stacked stone	Good
Roof	Primary: Gable construction with built-up finish	Good
Interiors	Walls: Painted gypsum board & CMU, painted Floors: Carpet, VCT & ceramic tile Ceilings: Suspended ACT	Good
Elevators	None	Good
Plumbing	Copper supply and cast iron waste & venting Electric domestic water heaters. Toilets, urinals, and sinks in all restrooms	Good

Building A-B: Systems Summary			
HVAC	Individual package	Good	
Fire Suppression	None		
Electrical	Source & Distribution: Main panel Fed from A building with copper wiring Interior Lighting: T-8, T-12, CFL	Good	
Fire Alarm	Alarm panel, smoke detectors, alarms, strobes, pull stations, back-up emergency lights, and exit signs	Good	
Equipment/Special	None		
Accessibility	No Issues		
Key Issues and Findings	No Issues		

See Appendix D for the Component Condition Table.

2. Building C,D,E,F & G Systems Summary





Building C, D, E, F &	G: Systems Summary	
Address	3600 Packard Street, Jurupa Valley, CA 92509	
Constructed/Renovated	1956/ 2018	
Building Size	C: 4,180 SF	
	D: 3,790 SF	
	E: 3,790 SF	
	F: 3,790 SF	
	G: 3,790 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood and steel frame structure on concrete slab with concrete-topped metal decks	Good
Façade	Stucco with aluminum windows	Good
,	Dry stacked stone	
Roof	Primary: Gable construction with built-up finish	Good
Interiors	Walls: Painted gypsum board & CMU, painted	Good
	Floors: Carpet, VCT & ceramic tile	2234
	Ceilings: Suspended ACT	
Elevators	None	Good

Building C, D, E, F &	G: Systems Summary	
Plumbing	Copper supply and cast iron waste & venting Electric domestic water heaters. Toilets, urinals, and sinks in all restrooms	
HVAC	Individual package	Good
Fire Suppression	None	
Electrical	Source & Distribution: Main panel Fed from A building with copper wiring Interior Lighting: T-8, T-12, CFL	Good
Fire Alarm	Alarm panel, smoke detectors, alarms, strobes, pull stations, back-up emergency lights, and exit signs	Good
Equipment/Special	None	
Accessibility	No Issues	
Key Issues and Findings	No Issues	

See Appendix D for the Component Condition Table.

3. Building H Sytems Summary





Building H: Systems	S Summary	
Address	3600 Packard Street, Jurupa Valley, CA 92509	
Constructed/Renovated	2018	
Building Size	9,000 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood and steel frame structure on concrete slab with concrete-topped metal decks	Good
Façade	Stucco with aluminum windows Dry stacked stone	Good
Roof	Primary: Gable construction with built-up finish	Good
Interiors	Walls: Painted gypsum board & CMU, painted Floors: Carpet, VCT & ceramic tile Ceilings: Suspended ACT	Good
Elevators	None	Good
Plumbing	Copper supply and cast iron waste & venting Electric domestic water heaters. Toilets, urinals, and sinks in all restrooms	Good

Building H: Systems Summary			
HVAC	Individual package	Good	
Fire Suppression	None		
Electrical	Source & Distribution: Main panel Fed from A building with copper wiring Interior Lighting: T-8, T-12, CFL	Good	
Fire Alarm	Alarm panel, smoke detectors, alarms, strobes, pull stations, back-up emergency lights, and exit signs	Good	
Equipment/Special	None		
Accessibility	No Issues		
Key Issues and Findings	No Issues		

See Appendix D for the Component Condition Table.

4. Portable Classrooms Systems Summary





Portable Classroom	s: Systems Summary	
Address	8700 Galena Street, Jurupa Valley, CA 92509	
Constructed/Renovated	1975/ 2018	
Building Size	P21-P33: 882 SF P34-P36: 1,253 SF P37-P41: 882 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood frame structure with raised floor	Fair
Façade	Wood siding with aluminum windows	Fair
Roof	Primary: Flat construction with coated metal finish	Fair
Interiors	Walls: vinyl , painted Floors: Carpet Ceilings: ACT	Fair
Elevators	None	Fair
Plumbing	Copper supply and cast iron waste & venting Toilets, urinals, and sinks in all restrooms	Fair

Portable Classrooms: Systems Summary			
HVAC	Individual package through wall	Fair	
Fire Suppression	None		
Electrical	Source & Distribution: Main panel fed from site with copper wiring Interior Lighting: T-8, T-12	Fair	
Fire Alarm	Alarm panel, smoke detectors, alarms, strobes, pull stations, back-up emergency lights, and exit signs	Fair	
Equipment/Special	None		
Accessibility	Presently it does not appear an accessibility study is needed for this building.		
Key Issues and Findings	Some of the HVAC units appear to be close to end of life expectancy. The nameplate da not visible.	ata was	

See Appendix D for the Component Condition Table.

5. Site Summary





Site Information		
Lot Size	8.30 acres (estimated)	
Parking Spaces	59 total; 2 accessible (included in total above)	
System	Description	Condition
Pavement/Flatwork	Asphalt lots with areas of concrete and concrete sidewalks, curbs, ramps, and stairs	Good
Site Development	Building-mounted signage, chain link temporary fencing, iron tube fencing, CMU dumpster enclosures	Good
Site Development	Playgrounds and sports courts, and site lights Limited park benches, picnic tables, trash receptacles	
Landscaping and Topography	No significant landscaping features Irrigation not present No retaining walls Low to moderate site slopes throughout	Good
Utilities	Municipal water and sewer Local utility-provided electric and natural gas	Good
Site Lighting	Pole-mounted: LED	Good
Ancillary Structures	Playground equipment	Fair
Key Issues and Findings	Heavy asphalt wear, severe alligator cracking and potholes in asphalt walk ways and sport court areas	

See Appendix D for the Component Condition Table.



6. ADA Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of "areas of public accommodations" and "public facilities" on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG).

A public entity (i.e. city governments) shall operate each service, program, or activity so that the service, program, or activity, when viewed in its entirety, is readily accessible to and usable by individuals with disabilities.

However, this does not:

- 1. Necessarily require a public entity to make each of its existing facilities accessible to and usable by individuals with disabilities:
- Require a public entity to take any action that would threaten or destroy the historic significance of an historic property; or
- 3. Require a public entity to take any action that it can demonstrate would result in a fundamental alteration in the nature of a service, program, or activity or in undue financial and administrative burdens. In those circumstances where personnel of the public entity believe that the proposed action would fundamentally alter the service, program, or activity or would result in undue financial and administrative burdens, a public entity has the burden of proving that compliance with 35.150(a) of this part would result in such alteration or burdens. The decision that compliance would result in such alteration or burdens must be made by the head of a public entity or his or her designee after considering all resources available for use in the funding and operation of the service, program, or activity, and must be accompanied by a written statement of the reasons for reaching that conclusion. If an action would result in such an alteration or such burdens, a public entity shall take any other action that would not result in such an alteration or such burdens but would nevertheless ensure that individuals with disabilities receive the benefits or services provided by the public entity.

During the FCA, EMG performed a limited high-level accessibility review of the facility non-specific to any local regulations or codes. The scope of the visual observation was limited to those areas and categories set forth in the tables throughout this report. It is understood by the Client that the limited observations described herein do not comprise a full ADA Compliance Survey, and that such a survey is beyond the scope of EMG's undertaking. Only a representative sample of areas was observed and actual measurements were not taken to verify compliance.

The facility was originally constructed in 1956. The facility was significantly renovated in 2018. Complaints about accessibility issues have not been received by the property management. The property does not have pending litigation related to existing barriers or previously removed barriers.

An accessibility study has not been performed at the site. Although no significant issues were identified, a comprehensive ADA Compliance Survey would reveal specific aspects of the property that are not in full compliance.

The table below is intended to be used as a general reference guide to help differentiate the orders of magnitude between some of the more commonly observed accessibility issues. The table is not intended to be all-inclusive, and boxes checked in the tables above do not necessarily mean those specific problems or shortcomings cited as examples below exist at the subject buildings and sites. Reference the photolog (in the appendix) and/or *Key Findings* section for visuals and/or more specifics about the subject site conditions.

Building AB, C, D, E, F, G & H: Accessibility Issues				
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues	
Exterior Path of Travel			\boxtimes	
Interior Path of Travel				
Public Use Restrooms				

Portable Classroom Accessibility Issues				
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues	
Exterior Path of Travel				
Interior Path of Travel				
Public Use Restrooms			\boxtimes	

Removal of barriers to accessibility should be addressed from a liability standpoint in order to comply with federal law, but the barriers may or may not be building code violations. The Americans with Disabilities Act Accessibility Guidelines are part of the ADA federal civil rights law pertaining to the disabled and are not a construction code. State and local jurisdictions have adopted the ADA Guidelines or have adopted other standards for accessibility as part of their construction codes.

Reference Guide			
	Major Issues	Moderate Issues	Minor/No Issues
	(ADA study recommended)	(ADA study recommended)	
Parking	 Needs full reconstruction Excessive slopes over 3% require major re-grading No level locations to add required spaces 	 No or non-compliant curb cuts Moderate difficulty to add required accessible spaces Slopes close to compliant 	Painting of markings neededSignage height non-compliantSignage missing
Exterior Path of Travel	Large areas of sidewalks with excessive slopes No ramp when needed Ramps with excessive slopes	 Ramps need rails Ramps need rail extensions Need significant # of lever handles All or most entrance door exterior maneuvering clearance areas with excessive slopes 	One entrance door exterior maneuvering clearance area with excessive slope A few door knobs instead of lever handles Non-compliant signage
Interior Path of Travel	- All or most interior doors appear less than 32" wide - Corridors less than 36" wide - No ramp when needed - Ramps with excessive slopes - Non-compliant treads/risers at means of egress stairways	- Single height drinking fountains - Drinking fountain too high or protrudes into accessible route - Ramps need rails - Ramps need rail extensions - Need significant # of lever handles - Non-compliant rail extensions at egress stairways - All/most door thresholds high	- One door threshold too high - A few door knobs instead of lever handles - Non-compliant door pressures - Non-compliant signage - Switches not within reach range
Public Use Restrooms	 No ADA RR on each accessible floor Restroom(s) too small Entire restroom(s) requires renovation Water closet clearance requires moving walls 	- Interior doors appear less than 32" wide - Missing or non-compliant grab bars - Easily fixable clearance issues	 Minor height adjustments required Non-compliant door pressures Missing a visual strobe (only required if audible fire alarm already present) Missing lavatory pipe wraps Signage not compliant

Reference Guide			
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues
Elevators	No elevator present when required Elevator cab too small	 Panel control buttons not at compliant height No hands-free emergency communication system Elevator only has mechanical stops 	 Audible/visual signals at every floor may be lacking Minor signage / Braille issues
Kitchens/Kitchenettes	Clear space for each appliance not present Clearance between opposing counters too narrow	 Sink and counter too high Sink knee and toe clearance not provided where required (built-in) Less than 50% of cabinetry within reach range 	- Dispensers not within reach range - Switches not within reach range - Missing sink pipe wraps if knee and toe clearance required

7. Purpose and Scope

Purpose

EMG was retained by the client to render an opinion as to the Property's current general physical condition on the day of the site visit.

Based on the observations, interviews and document review outlined below, this report identifies significant deferred maintenance issues, existing deficiencies, and material code violations of record, which affect the Property's use. Opinions are rendered as to its structural integrity, building system condition and the Property's overall condition. The report also notes building systems or components that have realized or exceeded their typical expected useful lives.

The physical condition of building systems and related components are typically defined as being in one of five condition ratings. For the purposes of this report, the following definitions are used:

Condition Ratings	
Excellent	New or very close to new; component or system typically has been installed within the past year, sound and performing its function. Eventual repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Good	Satisfactory as-is. Component or system is sound and performing its function, typically within the first third of its lifecycle. However, it may show minor signs of normal wear and tear. Repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Fair	Showing signs of wear and use but still satisfactory as-is, typically near the median of its estimated useful life. Component or system is performing adequately at this time but may exhibit some signs of wear, deferred maintenance, or evidence of previous repairs. Repair or replacement will be required due to the component or system's condition and/or its estimated remaining useful life.
Poor	Component or system is significantly aged, flawed, functioning intermittently or unreliably; displays obvious signs of deferred maintenance; shows evidence of previous repair or workmanship not in compliance with commonly accepted standards; has become obsolete; or exhibits an inherent deficiency. The present condition could contribute to or cause the deterioration of contiguous elements or systems. Either full component replacement is needed or repairs are required to restore to good condition, prevent premature failure, and/or prolong useful life.
Failed	Component or system has ceased functioning or performing as intended. Replacement, repair, or other significant corrective action is recommended or required.
Not Applicable	Assigning a condition does not apply or make logical sense, most commonly due to the item in question not being present.

Scope

The standard scope of the Facility Condition Assessment includes the following:

- Visit the Property to evaluate the general condition of the building and site improvements, review available construction documents in order to familiarize ourselves with, and be able to comment on, the in-place construction systems, life safety, mechanical, electrical, and plumbing systems, and the general built environment.
- Identify those components that are exhibiting deferred maintenance issues and provide cost estimates for Immediate Costs and Replacement Reserves based on observed conditions, maintenance history and industry standard useful life estimates. This will include the review of documented capital improvements completed within the last five-year period and work currently contracted for, if applicable.
- Provide a full description of the Property with descriptions of in-place systems and commentary on observed conditions.
- Provide a high-level categorical general statement regarding the subject Property's compliance to Title III of the Americans
 with Disabilities Act. This will not constitute a full ADA survey, but will help identify exposure to issues and the need for
 further review.



- Obtain background and historical information about the facility from a building engineer, property manager, maintenance staff, or other knowledgeable source. The preferred methodology is to have the client representative or building occupant complete a Pre-Survey Questionnaire (PSQ) in advance of the site visit. Common alternatives include a verbal interview just prior to or during the walk-through portion of the assessment.
- Review maintenance records and procedures with the in-place maintenance personnel.
- Observe a representative sample of the interior spaces/units, including vacant spaces/units, to gain a clear understanding
 of the property's overall condition. Other areas to be observed include the exterior of the property, the roofs, interior
 common areas, and the significant mechanical, electrical and elevator equipment rooms.
- Provide recommendations for additional studies, if required, with related budgetary information.
- Provide an Executive Summary at the beginning of this report, which highlights key findings and includes a Facility Condition Index as a basis for comparing the relative conditions of the buildings within the portfolio.

8. Opinions of Probable Costs

Cost estimates are attached throughout this report, with the Replacement Reserves in the appendix.

These estimates are based on Invoice or Bid Document/s provided either by the Owner/facility and construction costs developed by construction resources such as *R.S. Means, CBRE Whitestone*, and *Marshall & Swift*, EMG's experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions.

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs most probably will vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing or bundling of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, use of subcontractors, and whether competitive pricing is solicited, etc. Certain opinions of probable costs cannot be developed within the scope of this guide without further study. Opinions of probable cost for further study should be included in the FCA.

Methodology

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, EMG opines as to when a system or component will most probably necessitate replacement. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its effective age, whether explicitly or implicitly stated. Projections of Remaining Useful Life (RUL) are based primarily on age and condition with the presumption of continued use and maintenance of the Property similar to the observed and reported past use and maintenance practices, in conjunction with the professional judgment of EMG's assessors. Significant changes in occupants and/or usage may affect the service life of some systems or components.

Where quantities could not be or were not derived from an actual construction document take-off or facility walk-through, and/or where systemic costs are more applicable or provide more intrinsic value, budgetary square foot and gross square foot costs are used. Estimated costs are based on professional judgment and the probable or actual extent of the observed defect, inclusive of the cost to design, procure, construct and manage the corrections.

Definitions

Immediate Needs

Immediate Needs are line items that require immediate action as a result of: (1) material existing or potential unsafe conditions, (2) failed or imminent failure of mission critical building systems or components, or (3) conditions that, if not addressed, have the potential to result in, or contribute to, critical element or system failure within one year or will most probably result in a significant escalation of its remedial cost.

For database and reporting purposes the line items with RUL=0, and commonly associated with *Safety* or *Performance/Integrity* Plan Types, are considered Immediate Needs.

Replacement Reserves

Cost line items traditionally called Replacement Reserves (equivalently referred to as Lifecycle/Renewals) are for recurring probable renewals or expenditures, which are not classified as operation or maintenance expenses. The replacement reserves should be budgeted for in advance on an annual basis. Replacement Reserves are reasonably predictable both in terms of frequency and cost. However, Replacement Reserves may also include components or systems that have an indeterminable life but, nonetheless, have a potential for failure within an estimated time period.

Replacement Reserves generally exclude systems or components that are estimated to expire after the reserve term and are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that are not deemed to have a material effect on the use of the Property are also excluded. Costs that are caused by acts of God, accidents, or other occurrences that are typically covered by insurance, rather than reserved for, are also excluded.



Replacement costs are solicited from ownership/property management, EMG's discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by the ownership's or property management's maintenance staff are also considered.

EMG's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the assessment period. The assessment period is defined as the effective age plus the reserve term. Additional information concerning system's or component's respective replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Replacement Reserves Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined as Immediate Needs.

For the purposes of 'bucketizing' the System Expenditure Forecasts in this report, the Replacement Reserves have been subdivided and grouped as follows: Short Term (years 1-3), Near Term (years 4-5), Medium Term (years 6-10), and Long Term (years 11-20).

Key Findings

In an effort to highlight the most significant cost items and not be overwhelmed by the Replacement Reserves report in its totality, a subsection of Key Findings is included within the Executive Summary section of this report. Key Findings typically include repairs or replacements of deficient items within the first five-year window, as well as the most significant high-dollar line items that fall anywhere within the ten-year term. Note that while there is some subjectivity associated with identifying the Key Findings, the Immediate Needs are always included as a subset.

Exceedingly Aged

A fairly common scenario encountered during the assessment process, and a frequent source of debate, occurs when classifying and describing "very old" systems or components that are still functioning adequately and do not appear nor were reported to be in any way deficient. To help provide some additional intelligence on these items, such components will be tagged in the database as Exceedingly Aged. This designation will be reserved for mechanical or electrical systems or components that have aged well beyond their industry standard lifecycles, typically at least 15 years beyond and/or twice their Estimated Useful Life (EUL). In tandem with this designation, these items will be assigned a Remaining Useful Life (RUL) not less than two years but not greater than 1/3 of their standard EUL. As such the recommended replacement time for these components will reside outside the typical Short Term window but will not be pushed 'irresponsibly' (too far) into the future.



9. Certification

HMC Architects (the Client) retained EMG to perform this Facility Condition Assessment in connection with its Facility Master Planning effort for the Jurupa Unified School District at Ina Arbuckle Elementary School, 3600 Packard Street, Jurupa Valley, CA 92509, the "Property". It is our understanding that the primary interest of the Client is to locate and evaluate materials and building system defects that might significantly affect the value of the property and to determine if the present Property has conditions that will have a significant impact on its continued operations.

The conclusions and recommendations presented in this report are based on the brief review of the plans and records made available to our Project Manager during the site visit, interviews of available property management personnel and maintenance contractors familiar with the Property, appropriate inquiry of municipal authorities, our Project Manager's walk-through observations during the site visit, and our experience with similar properties.

No testing, exploratory probing, dismantling or operating of equipment or in-depth studies were performed unless specifically required under the *Purpose and Scope* section of this report. This assessment did not include engineering calculations to determine the adequacy of the Property's original design or existing systems. Although walk-through observations were performed, not all areas may have been observed (see Section 1 for specific details). There may be defects in the Property, which were in areas not observed or readily accessible, may not have been visible, or were not disclosed by management personnel when questioned. The report describes property conditions at the time that the observations and research were conducted.

This report has been prepared on behalf of and exclusively for the use of the Client for the purpose stated within the *Purpose and Scope* section of this report. The report, or any excerpt thereof, shall not be used by any party other than the Client or for any other purpose than that specifically stated in our agreement or within the *Purpose and Scope* section of this report without the express written consent of EMG.

Any reuse or distribution of this report without such consent shall be at the Client and the recipient's sole risk, without liability to EMG.

Prepared by: Jennifer Medley,

Project Manager

Reviewed by: Fathles Sulles

Kathleen Sullivan Technical Report Reviewer for

Mark Surdam Program Manager

msurdam@emgcorp.com 800.733.0660 x6251

10. Appendices

Appendix A: Photographic Record

Appendix B: Site and Floor Plans

Appendix C: Pre-Survey Questionnaire

Appendix D: Component Condition Report

Appendix E: Replacement Reserves

Appendix F: Equipment Inventory List

Appendix A: Photographic Record



#1 SCHOOL ENTRANCE




#2 FRONT ELEVATION



#3 RIGHT ELEVATION



#4 LEFT ELEVATION BLDG B



#5 ADA RAMP



#6 REAR ELEVATION BLDG B

#7



REAR ELEVATION 2



#8 LIBRARY INTERIOR



#9 RIGHT ELEVATION 2



#10 RIGHT ELEVATION 3



#11 PLAY AREA



#12 PLAY AREA



#13 LIBRARY INTERIOR



#14 EXTERIOR STAIR/RAMP RAILS, WOOD, REFINISH



#15 EXTERIOR WALL, STONE VENEER



EXTERIOR DOOR, ALUMINUM-FRAMED FULLY-GLAZED

#16

#18




#17 EXTERIOR DOOR, STEEL



GUTTERS & DOWNSPOUTS, ALUMINUM W/ FITTINGS



#19 INTERIOR WALL CONSTRUCTION, FIBERGLASS PANEL



#20 INTERIOR WALL FINISH, PLATE GLASS



#21 INTERIOR FLOOR FINISH, CARPET COMMERCIAL TILE



INTERIOR FLOOR FINISH, CARPET COMMERCIAL TILE

#22



#23 INTERIOR CEILING FINISH



#24 INTERIOR CEILING FINISH



#25 DRINKING FOUNTAIN, EXTERIOR



#26 WATER FOUNTAINS

#28



#27 HVAC WALL UNIT



SECONDARY TRANSFORMER




#29 MAIN DISTRIBUTION PANEL



#30 BUILDING/MAIN SWITCHBOARD



#31 LIGHT FIXTURE



#32 LIGHTING SYSTEM, INTERIOR



#33 LIGHTING SYSTEM, INTERIOR



FIRE ALARM CONTROL PANEL

#34




#35 PARKING LOTS, ASPHALT PAVEMENT



#36 PARKING LOTS, CONCRETE PAVEMENT



#37 PARKING LOTS, ASPHALT PAVEMENT



#38 PEDESTRIAN PAVEMENT, SIDEWALK



#39 FENCES & GATES



#40 FENCES & GATES



#41 SITE FURNISHINGS



#42 SITE FURNISHINGS



#43 SITE FURNISHINGSL



#44 PLAY SURFACES



#45 PLAY SURFACES



#46 PLAY SURFACES



#47 PLAY STRUCTURE



#48 PLAY STRUCTURE



#49 CAFETERIA ENTRY



#50 WALL FINISH



#51 LIBRARY



#52 LIBRARY



#53 OFFICE



#54 KITCHEN

Appendix B: Site and Floor Plans

Aerial Site Plan



SOURCE:


Google Maps: Imagery ©2018 Google, Map data ©2019 Google



ON-SITE DATE:

October 3, 2019

Site Plan



SOURCE:

Jurupa Middle School - Admin to Principal



ON-SITE DATE:

October 3, 2019

Appendix C: Pre-Survey Questionnaire

THIS PAGE INTENTIONALLY BLANK A PRE-SURVEY QUESTIONNAIRE WAS NOT RECEIVED



Appendix D: Component Condition Report

Component Condition Report

Ina Arbuckle Elementary School / Building A-B

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						
B2011	Building Exterior	Good	Exterior Wall, Concrete Cast-in-Place, 1-2 Stories	3,000 SF	49	1465652
B2011	Building Exterior	Good	Exterior Wall, Stucco, 1-2 Stories, Prep & Fog Coat or Paint	3,000 SF	9	1465657
B2011	Building Exterior	Good	Exterior Wall, Stone, 1-2 Stories	5,000 SF	49	1465664
B2021	Building Exterior	Good	Window, 24 SF	6	29	1465662
B2031	Building Exterior	Good	Exterior Door, Aluminum-Framed Fully-Glazed	8	29	1465650
B2032	Building Exterior	Good	Exterior Door, Steel	9	39	1465659
Roofing						
B3011	Roof	Good	Roof, Single-Ply TPO/PVC Membrane	8,500 SF	19	1578631
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Gypsum Board/Plaster	3,000 SF	49	1465661
C1017	Building Interior	Good	Interior Window, 12 SF	2	39	1465654
C1021	Building exterior	Good	Interior Door, Aluminum-Framed Fully-Glazed	1	39	1465653
C1021	Kitchen	Good	Interior Door, Steel	7	39	1465426
C1021	Building Interior	Good	Interior Door, Steel	1	39	1465665
C3012	Building Interior	Good	Interior Wall Finish, Plate Glass	50 SF	39	1465651
C3012	Cafeteria/Gym	Good	Interior Wall Finish, Fabric	2,000 SF	14	1465415
C3024	Throughout building	Good	Interior Floor Finish, Vinyl Tile (VCT)	5,600 SF	14	1465416
C3024	Building Interior	Good	Interior Floor Finish, Ceramic Tile	50 SF	39	1465647
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	3,000 SF	9	1465655
C3031	Building Interior	Good	Interior Ceiling Finish, Gypsum Board/Plaster	500 SF	49	1465644
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	8,504 SF	24	1465422
Plumbing						
D2014	Kitchen	Good	Trough Style Sink, Solid Surface, Vandalism Resistant [0]	2	29	1465427
D2018	Building Interior	Good	Drinking Fountain, Interior	2	14	1465656
HVAC						
D3051	Kitchen	Good	Air Conditioner, 1 TON	1	9	1465424
D3051	Kitchen	Good	Air Conditioner, 1 TON	1	9	1465429

Ina Arbuckle Elementary School / Building A-B

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D3052	Roof - B	Good	Packaged Unit (RTU), 4 TON [AC-2.1]	1	19	1547649
D3052	Roof B	Good	Packaged Unit (RTU), 2 TON [SAC-2.2]	1	19	1550562
D3052	Roof - B	Good	Packaged Unit (RTU), 3 TON [AC-1.2]	1	19	1547645
D3052	Roof B	Good	Packaged Unit (RTU), 2 TON [SAC-2.1]	1	19	1550558
D3052	Roof - B	Good	Packaged Unit (RTU), 5 TON [AC-1.1]	1	19	1547651
D3052	Roof - B	Good	Packaged Unit (RTU), 3 TON [AC-1.3]	1	19	1547647
Electrical						
D5012	Electrical room	Good	Secondary Transformer, 112.5 kVA	1	29	1465658
D5012	Electrical room	Good	Main Distribution Panel, 400 AMP	1	29	1465648
D5022	Building exterior	Good	Light Fixture, 50 WATT	5	19	1465663
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures [0]	8,504 SF	19	1465414
D5092	Building Interior	Good	Exit Sign Light Fixture, LED	7	9	1465645
Fire Alarm &	Comm					
D5037	Kitchen	Good	Fire Alarm System, Basic/Zoned, Upgrade/Install [0]	8,504 SF	19	1465417
Equipment/Sp	pecial					
E1093	Kitchen	Good	Commercial Kitchen, Range/Oven, 4-Burner [0]	1	6	1465428
E1093	Kitchen	Good	Commercial Kitchen, Convection Oven, Double [0]	1	9	1465421
E1093	Kitchen	Good	Commercial Kitchen, Food Warmer [0]	1	6	1465418
E1093	Kitchen	Fair	Commercial Kitchen, Refrigerator, 2-Door Reach-In [0]	1	6	1465419
E1093	Kitchen	Fair	Commercial Kitchen, Dairy Cooler/Wells [0]	1	6	1465413

Ina Arbuckle Elementary School / Building C

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						
B2011	Building Exterior	Good	Exterior Wall, Stucco, 1-2 Stories, Prep & Fog Coat or Paint	7,400 SF	9	1519557
B2021	Building Exterior	Good	Window, 24 SF	13	29	1519543
B2021	Building Exterior	Good	Window, 12 SF	1	29	1519559
B2031	Building Exterior	Good	Exterior Door, Aluminum-Framed Fully-Glazed	3	29	1519544
B2032	Building Exterior	Good	Exterior Door, Steel	5	39	1519545

Ina Arbuckle Elementary School / Building C

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Roofing						
B3011	Roof	Good	Roof, Built-Up	4,180 SF	24	1519563
Interiors						
C1031	Restrooms	Good	Toilet Partitions, Plastic/Laminate	3	19	1519561
C3012	Throughout building	Good	Interior Wall Finish, any surface, Prep & Paint	5,400 SF	9	1519558
C3012	Classrooms	Good	Interior Wall Finish, Vinyl	500 SF	14	1519551
C3012	Restrooms	Good	Interior Wall Finish, Ceramic Tile	2,000 SF	39	1519562
C3024	Restrooms	Good	Interior Floor Finish, Ceramic Tile	600 SF	39	1519549
C3024		Good	Interior Floor Finish, Vinyl Tile (VCT)	1,100 SF	14	1519546
C3025		Good	Interior Floor Finish, Carpet Commercial Tile	1,400 SF	9	1519542
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	4,180 SF	24	1519540
Plumbing						
D2011	Restrooms	Good	Toilet, Commercial Water Closet	3	29	1519547
D2012	Restrooms	Good	Urinal, Standard	1	29	1519554
D2014	Restrooms	Good	Sink/Lavatory, Wall-Hung, Vitreous China	3	29	1519550
D2014	Classrooms	Good	Sink/Lavatory, Vanity Top, Stainless Steel	4	29	1519548
D2018	Building exterior	Good	Drinking Fountain, Outside/Site Style	2	14	1519553
HVAC						
D3052	Roof C	Good	Packaged Unit (RTU), 5 TON [X-702]	1	19	1550565
D3052	Roof C	Good	Packaged Unit (RTU), 3.5 TON [X-605]	1	19	1550564
D3052	Roof C	Good	Packaged Unit (RTU), 5 TON [X-701]	1	19	1550566
D3052	Roof	Good	Packaged Unit (RTU), 3 TON	3	11	1519560
Electrical						
D5012	Electrical room	Good	Main Distribution Panel, 200 AMP	1	29	1519552
D5022	Building exterior	Good	Light Fixture, 50 WATT	8	19	1519556
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	4,180 SF	19	1519555
Fire Alarm & 0	Comm					
D5037	Throughout building	Good	Fire Alarm System, Basic/Zoned, Upgrade/Install	4,180 SF	19	1519541

Ina Arbuckle Elementary School / Building D

System Exp - AssetCALC

Unite Cooking December 2015 School / Building Decondition		g D Condition	Asset/Component/Repair	Quantity	RUL	ID
UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						
B2011	Building Exterior	Good	Exterior Wall, Stucco, 1-2 Stories, Prep & Fog Coat or Paint	6,400 SF	9	1519533
B2021	Building Exterior	Good	Window, 24 SF	12	29	1519535
B2031	Building Exterior	Good	Exterior Door, Aluminum-Framed Fully-Glazed	3	29	1519534
B2032	Building Exterior	Good	Exterior Door, Steel	5	39	1519525
Roofing						
B3011	Roof	Good	Roof, Built-Up	4,180 SF	24	1519539
Interiors						
C1031	Restrooms	Good	Toilet Partitions, Plastic/Laminate	5	19	1519519
C3012	Restrooms	Good	Interior Wall Finish, Ceramic Tile	2,000 SF	39	1519523
C3012	Throughout building	Good	Interior Wall Finish, any surface, Prep & Paint	5,500 SF	9	1519529
C3024	Classrooms	Good	Interior Floor Finish, Ceramic Tile	800 SF	39	1519530
C3024	Classrooms	Good	Interior Floor Finish, Vinyl Tile (VCT)	800 SF	14	1519518
C3025	Classrooms	Good	Interior Floor Finish, Carpet Commercial Tile	2,100 SF	9	1519538
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	3,790 SF	24	1519528
Plumbing						
D2011	Restrooms	Good	Toilet, Commercial Water Closet	6	29	1519521
D2012	Restrooms	Good	Urinal, Standard	4	29	1519517
D2014	Restrooms	Good	Sink/Lavatory, Wall-Hung, Vitreous China	4	29	1519531
D2014	Utility closet	Good	Service Sink, Wall-Hung	1	34	1519524
D2014	Classrooms	Good	Sink/Lavatory, Vanity Top, Stainless Steel	4	29	1519522
D2018	Building exterior	Good	Drinking Fountain, Outside/Site Style	2	14	1519532
HVAC						
D3052	Roof D	Good	Packaged Unit (RTU), 5 TON [X-703]	1	19	1550561
D3052	Roof D	Good	Packaged Unit (RTU), 5 TON [X-704]	1	19	1550573
D3052	Building exterior	Good	Packaged Unit (RTU), 3 TON	3	16	1519526
Electrical						
D5012	Electrical room	Good	Main Distribution Panel, 200 AMP	1	29	1519536
D5022	Building exterior	Good	Light Fixture, 50 WATT	8	19	1519537

11/29/2019

Ina Arbuckle Elementary School / Building D

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	3,790 SF	19	1519520
Fire Alarm & 0	Comm					
D5037	Throughout building	Good	Fire Alarm System, Basic/Zoned, Upgrade/Install	3,790 SF	19	1519527

Ina Arbuckle Elementary School / Building E

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						
B2011	Building Exterior	Good	Exterior Wall, Stucco, 1-2 Stories, Prep & Fog Coat or Paint	6,400 SF	9	1578586
B2021	Building Exterior	Good	Window, 24 SF	12	29	1578587
B2031	Building Exterior	Good	Exterior Door, Aluminum-Framed Fully-Glazed	3	29	1578588
B2032	Building Exterior	Good	Exterior Door, Steel	5	39	1578589
Roofing						
B3011	Roof	Good	Roof, Built-Up	4,180 SF	24	1578590
Interiors						
C1031	Restrooms	Good	Toilet Partitions, Plastic/Laminate	5	19	1578591
C3012	Restrooms	Good	Interior Wall Finish, Ceramic Tile	2,000 SF	39	1578592
C3012	Throughout building	Good	Interior Wall Finish, any surface, Prep & Paint	5,500 SF	9	1578593
C3024	Classrooms	Good	Interior Floor Finish, Vinyl Tile (VCT)	800 SF	14	1578595
C3024	Classrooms	Good	Interior Floor Finish, Ceramic Tile	800 SF	39	1578594
C3025	Classrooms	Good	Interior Floor Finish, Carpet Commercial Tile	2,100 SF	9	1578596
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	3,790 SF	24	1578597
Plumbing						
D2011	Restrooms	Good	Toilet, Commercial Water Closet	6	29	1578598
D2012	Restrooms	Good	Urinal, Standard	4	29	1578599
D2014	Utility closet	Good	Service Sink, Wall-Hung	1	34	1578600
D2014	Restrooms	Good	Sink/Lavatory, Wall-Hung, Vitreous China	4	29	1578601
D2014	Classrooms	Good	Sink/Lavatory, Vanity Top, Stainless Steel	4	29	1578602
D2018	Building exterior	Good	Drinking Fountain, Outside/Site Style	2	14	1578603
HVAC						

Ina Arbuckle Elementary School / Building E

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D3052	Roof E	Good	Packaged Unit (RTU), 5 TON [X-604]	1	19	1550560
D3052	Roof E	Good	Packaged Unit (RTU), 3.5 TON [X-504]	1	19	1550567
D3052	Roof E	Good	Packaged Unit (RTU), 3.5 TON [X-503]	1	19	1550568
D3052	Roof E	Good	Packaged Unit (RTU), 3.5 TON [X-603]	1	19	1550572
Electrical						
D5012	Electrical room	Good	Main Distribution Panel, 200 AMP	1	29	1578604
D5022	Building exterior	Good	Light Fixture, 50 WATT	8	19	1578605
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	3,790 SF	19	1578606
Fire Alarm &	Comm					
D5037	Throughout building	Good	Fire Alarm System, Basic/Zoned, Upgrade/Install	3,790 SF	19	1578607

Ina Arbuckle Elementary School / Building F

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						
B2011	Building Exterior	Good	Exterior Wall, Stucco, 1-2 Stories, Prep & Fog Coat or Paint	6,400 SF	9	1519447
B2021	Building Exterior	Good	Window, 24 SF	12	29	1519450
B2031	Building Exterior	Good	Exterior Door, Aluminum-Framed Fully-Glazed	3	29	1519449
B2032	Building Exterior	Good	Exterior Door, Steel	5	39	1519445
Roofing						
B3011	Roof	Good	Roof, Built-Up	7,400 SF	24	1519454
Interiors						
C3012	Classrooms	Good	Interior Wall Finish, any surface, Prep & Paint	5,500 SF	9	1519436
C3012	Restrooms	Good	Interior Wall Finish, Ceramic Tile	2,000 SF	39	1519438
C3024	Classrooms	Good	Interior Floor Finish, Vinyl Tile (VCT)	1,200 SF	14	1519453
C3025	Classrooms	Good	Interior Floor Finish, Carpet Commercial Tile	2,500 SF	9	1519437
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	3,790 SF	24	1519440
Plumbing						
D2011	Restrooms	Good	Toilet, Commercial Water Closet	5	29	1519443
D2012	Restrooms	Good	Urinal, Standard	4	29	1519448

Ina Arbuckle Elementary School / Building F

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D2014	Utility closet	Good	Service Sink, Wall-Hung	1	34	1519452
D2014	Restrooms	Good	Sink/Lavatory, Wall-Hung, Vitreous China	6	29	1519444
HVAC						
D3052	Roof F	Good	Packaged Unit (RTU), 3.5 TON [X-502]	1	19	1550563
D3052	Roof F	Good	Packaged Unit (RTU), 3.5 TON [X-501]	1	19	1550574
D3052	Roof	Good	Packaged Unit (RTU), 3 TON	3	16	1519439
D3052	Roof F	Good	Packaged Unit (RTU), 5 TON [X-403]	1	19	1550559
Electrical						
D5012	Electrical room	Good	Main Distribution Panel, 150	1	29	1519451
D5022	Building exterior	Good	Light Fixture, 50 WATT	8	19	1519442
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	3,790 SF	19	1519441
Fire Alarm &	Comm					
D5037	Classrooms	Good	Fire Alarm System, Basic/Zoned, Upgrade/Install	3,790 SF	19	1519446

Ina Arbuckle Elementary School / Building G

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						
B2011	Building Exterior	Good	Exterior Wall, Stucco, 1-2 Stories, Prep & Fog Coat or Paint	5,400 SF	9	1519428
B2011	Building Exterior	Good	Exterior Wall, Stone, 1-2 Stories	1,500 SF	49	1519424
B2021	Building Exterior	Good	Window, 24 SF	12	29	1519435
B2031	Building Exterior	Good	Exterior Door, Aluminum-Framed Fully-Glazed	3	29	1519434
B2032	Building Exterior	Good	Exterior Door, Steel	2	39	1519425
Roofing						
B3011	Roof	Good	Roof, Built-Up	5,400 SF	24	1519431
Interiors						
C3012	Classrooms	Good	Interior Wall Finish, any surface, Prep & Paint	5,400 SF	9	1519430
C3024	Classrooms	Good	Interior Floor Finish, Vinyl Tile (VCT)	1,100 SF	14	1519419
C3025	Classrooms	Good	Interior Floor Finish, Carpet Commercial Tile	2,500 SF	9	1519422
C3032	Classrooms	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	3,790 SF	24	1519433

Ina Arbuckle Elementary School / Building G

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Plumbing						
D2018	Building exterior	Good	Drinking Fountain, Outside/Site Style	2	14	1519429
HVAC						
D3052	Roof	Fair	Packaged Unit (RTU), 3 TON	3	16	1519426
D3052	Roof - G	Good	Packaged Unit (RTU), 5 TON [AC-3.2]	1	19	1547650
D3052	Roof - G	Good	Packaged Unit (RTU), 5 TON [AC-3.1]	1	19	1547648
D3052	Roof G	Good	Packaged Unit (RTU), 5 TON [X-301]	1	19	1550570
D3052	Roof G	Good	Packaged Unit (RTU), 5 TON [X-401]	1	19	1550569
D3052	Roof G	Good	Packaged Unit (RTU), 5 TON [X-402]	1	19	1550571
Electrical						
D5012	Electrical room	Good	Main Distribution Panel, 150 AMP	1	29	1519421
D5022	Building exterior	Good	Light Fixture, 50 WATT	9	19	1519432
D5029	Classrooms	Good	Lighting System, Interior, Low Density & Standard Fixtures	3,790 SF	19	1519420
Fire Alarm & 0	Comm					
D5037	Classrooms	Good	Fire Alarm Control Panel, Basic/Zoned	1	14	1519423
D5037	Classrooms	Good	Fire Alarm System, Basic/Zoned, Upgrade/Install	3,790 SF	19	1519427

Ina Arbuckle Elementary School / Building H

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						
B2011	Building Exterior	Good	Exterior Wall, Stone, 1-2 Stories	12,000 SF	49	1547699
B2021	Building Exterior	Good	Window, 24 SF	18	29	1547700
B2031	Building Exterior	Good	Exterior Door, Aluminum-Framed Fully-Glazed	6	29	1547693
Roofing						
B3011	Roof	Good	Roof, Single-Ply TPO/PVC Membrane	9,500 SF	19	1578633
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Gypsum Board/Plaster	9,000 SF	49	1547708
C1017	Building Interior	Good	Interior Window, 12 SF	2	39	1547706
C1017	Building Interior	Good	Interior Window, 6 SF	2	39	1547702

Ina Arbuckle Elementary School / Building H

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
C1021		Good	Interior Door, Wood Solid-Core	9	39	1547697
C1021	Building Interior	Good	Interior Door, Wood Solid-Core	1	39	1547711
C3012		Good	Interior Wall Finish, Ceramic Tile	200 SF	39	1547692
C3024		Good	Interior Floor Finish, Vinyl Sheeting	1,500 SF	14	1547701
C3024		Good	Interior Floor Finish, Ceramic Tile	100 SF	39	1547710
C3024		Good	Interior Floor Finish, Vinyl Tile (VCT)	200 SF	14	1547703
C3025		Good	Interior Floor Finish, Carpet Commercial Tile	5,000 SF	9	1547707
C3031	Building Interior	Good	Interior Ceiling Finish, Wood	150 SF	29	1547705
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	9,000 SF	24	1547695
Plumbing						
D2011		Good	Toilet, Commercial Water Closet	3	29	1547696
D2014		Good	Sink/Lavatory, Wall-Hung, Vitreous China	3	29	1547712
D2014	Building Interior	Good	Sink/Lavatory, Vanity Top, Stainless Steel	1	29	1547698
D2018	Building Interior	Good	Drinking Fountain, Interior	2	14	1547704
HVAC						
D3052	Roof - H	Good	Packaged Unit (RTU), 4 TON [AC-2.2]	1	19	1547653
D3052	Roof - H	Good	Packaged Unit (RTU), 5 TON [AC-2.4]	1	19	1547644
D3052	Roof - H	Good	Packaged Unit (RTU), 5 TON [AC-2.5]	1	19	1547646
D3052	Roof - H	Good	Packaged Unit (RTU), 5 TON [AC-2.3]	1	19	1547652
Electrical						
D5092	Throughout building	Good	Exit Sign Light Fixture, LED	2	9	1547694
Fire Alarm & C	Comm					
D5037	Building Interior	Good	Fire Alarm System, Basic/Zoned, Upgrade/Install	9,000 SF	19	1547709

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518838
Facade						

Ina Arbuckle Elementary School / Portable P21

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
B2011	Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,300 SF	11	1518839
B2032	Building Exterior	Good	Exterior Door, Steel	1	39	1518837
Roofing						
B3011	Roof	Good	Roof, Cool Reflective Coating	1,200 SF	9	1578608
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Fiberglass Panel	1,000 SF	49	1518842
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	882 SF	9	1518841
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	882 SF	24	1518840
HVAC						
D3051	P21	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465799
Electrical						
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518843
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	882 SF	19	1518844

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518846
Facade						
B2011	Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,300 SF	11	1518847
B2032	Building Exterior	Good	Exterior Door, Steel	1	39	1518845
Roofing						
B3011	Roof	Good	Roof, Cool Reflective Coating	1,200 SF	9	1578609
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Fiberglass Panel	1,000 SF	49	1518850
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	882 SF	9	1518849
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	882 SF	24	1518848
HVAC						
D3051	P22	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465804

Ina Arbuckle Elementary School / Portable P22

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Electrical						
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518851
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	882 SF	19	1518852

Ina Arbuckle Elementary School / Portable P23

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518854
Facade						
B2011	Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,300 SF	11	1518855
B2032	Building Exterior	Good	Exterior Door, Steel	1	39	1518853
Roofing						
B3011	Roof	Good	Roof, Cool Reflective Coating	1,200 SF	9	1578610
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Fiberglass Panel	882 SF	49	1518858
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	882 SF	9	1518857
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	882 SF	24	1518856
HVAC						
D3051	P23	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465772
Electrical						
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518859
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	882 SF	19	1518860

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518862
Facade						
B2011	Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,300 SF	11	1518863
B2032	Building Exterior	Good	Exterior Door, Steel	1	39	1518861

Ina Arbuckle Elementary School / Portable P24

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Roofing						
B3011	Roof	Good	Roof, Cool Reflective Coating	1,200 SF	9	1578611
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Fiberglass Panel	882 SF	49	1518866
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	882 SF	9	1518865
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	882 SF	24	1518864
HVAC						
D3051	P24	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465777
Electrical						
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518867
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	882 SF	19	1518868

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518870
Facade						
B2011	Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,300 SF	11	1518871
B2032	Building Exterior	Good	Exterior Door, Steel	1	39	1518869
Roofing						
B3011	Roof	Good	Roof, Cool Reflective Coating	1,200 SF	9	1578612
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Fiberglass Panel	882 SF	49	1518874
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	882 SF	9	1518873
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	1,000 SF	24	1518872
HVAC						
D3051	P25	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465784
Electrical						
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518875

Ina Arbuckle Elementary School / Portable P25

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	882 SF	19	1518876

Ina Arbuckle Elementary School / Portable P26

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518878
Facade						
B2011	Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,300 SF	11	1518879
B2032	Building Exterior	Good	Exterior Door, Steel	1	39	1518877
Roofing						
B3011	Roof	Good	Roof, Cool Reflective Coating	1,200 SF	9	1578613
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Fiberglass Panel	1,000 SF	49	1518882
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	882 SF	9	1518881
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	882 SF	24	1518880
HVAC						
D3051	P26	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465776
Electrical						
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518883
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	882 SF	19	1518884

Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518886
Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,300 SF	11	1518887
Building Exterior	Good	Exterior Door, Steel	1	39	1518885
Roof	Good	Roof, Cool Reflective Coating	1,200 SF	9	1578614
	Building Exterior Building Exterior Building Exterior	Building Exterior Good Building Exterior Good Building Exterior Good	Building Exterior Good Exterior Stair/Ramp Rails, Wood, Refinish Building Exterior Good Exterior Wall, Textured Plywood (T1-11) Building Exterior Good Exterior Door, Steel	Building Exterior Good Exterior Stair/Ramp Rails, Wood, Refinish Building Exterior Good Exterior Wall, Textured Plywood (T1-11) Building Exterior Good Exterior Door, Steel 1	Building Exterior Good Exterior Stair/Ramp Rails, Wood, Refinish Building Exterior Good Exterior Wall, Textured Plywood (T1-11) Building Exterior Good Exterior Door, Steel 1 39

Ina Arbuckle Elementary School / Portable P27

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Fiberglass Panel	882 SF	49	1518890
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	882 SF	9	1518889
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	882 SF	24	1518888
HVAC						
D3051	P27	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465778
Electrical						
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518891
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	882 SF	19	1518892

Ina Arbuckle Elementary School / Portable P28

Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518894
Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,300 SF	11	1518895
Building Exterior	Good	Exterior Door, Steel	1	39	1518893
Roof	Good	Roof, Cool Reflective Coating	1,200 SF	9	1578615
Throughout building	Good	Interior Wall Construction, Fiberglass Panel	882 SF	49	1518898
Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	1,000 SF	9	1518897
Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	882 SF	24	1518896
P28	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465789
Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518899
Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	882 SF	19	1518900
	Building Exterior Building Exterior Building Exterior Roof Throughout building Throughout building Throughout building P28 Building exterior	Building Exterior Good Building Exterior Good Building Exterior Good Roof Good Throughout building Good Building Exterior Good	Building Exterior Good Exterior Stair/Ramp Rails, Wood, Refinish Building Exterior Good Exterior Wall, Textured Plywood (T1-11) Building Exterior Good Exterior Door, Steel Roof Good Roof, Cool Reflective Coating Throughout building Good Interior Wall Construction, Fiberglass Panel Throughout building Good Interior Floor Finish, Carpet Commercial Tile Throughout building Good Interior Ceiling Finish, Suspended Acoustical Tile (ACT) P28 Fair Air Conditioner, 2.5 - 5 TON Building exterior Good Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	Building Exterior Good Exterior Stair/Ramp Rails, Wood, Refinish 90 LF Building Exterior Good Exterior Wall, Textured Plywood (T1-11) 1,300 SF Building Exterior Good Exterior Door, Steel 1 Roof Good Roof, Cool Reflective Coating 1,200 SF Throughout building Good Interior Wall Construction, Fiberglass Panel 882 SF Throughout building Good Interior Floor Finish, Carpet Commercial Tile 1,000 SF Throughout building Good Interior Ceiling Finish, Suspended Acoustical Tile (ACT) 882 SF P28 Fair Air Conditioner, 2.5 - 5 TON 1 Building exterior Good Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W 1	Building Exterior Good Exterior Stair/Ramp Rails, Wood, Refinish 90 LF 9 Building Exterior Good Exterior Wall, Textured Plywood (T1-11) 1,300 SF 11 Building Exterior Good Exterior Door, Steel 1 39 Roof Good Roof, Cool Reflective Coating 1,200 SF 9 Throughout building Good Interior Wall Construction, Fiberglass Panel 882 SF 49 Throughout building Good Interior Floor Finish, Carpet Commercial Tile 1,000 SF 9 Throughout building Good Interior Ceilling Finish, Suspended Acoustical Tile (ACT) 882 SF 24 Building exterior Good Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W 1 1 1

Unia Goldieckie	Ma Orduckle Elemention School / Portable Bendition		Asset/Component/Repair	Quantity	RUL	ID
UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518902
Facade						
B2011	Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,300 SF	11	1518903
B2032	Building Exterior	Good	Exterior Door, Steel	1	39	1518901
Roofing						
B3011	Roof	Good	Roof, Cool Reflective Coating	1,200 SF	9	1578616
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Fiberglass Panel	882 SF	49	1518906
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	882 SF	9	1518905
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	1,000 SF	24	1518904
HVAC						
D3051	P29	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465786
Electrical						
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518907
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	882 SF	19	1518908

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518910
Facade						
B2011	Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,300 SF	11	1518911
B2032	Building Exterior	Good	Exterior Door, Steel	1	39	1518909
Roofing						
B3011	Roof	Good	Roof, Cool Reflective Coating	1,200 SF	9	1578617
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Fiberglass Panel	882 SF	49	1518914
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	882 SF	9	1518913

Ina Arbuckle Elementary School / Portable P30

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	882 SF	24	1518912
HVAC						
D3051	P30	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465797
Electrical						
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518915
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	882 SF	19	1518916

Ina Arbuckle Elementary School / Portable P31

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518918
Facade						
B2011	Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,300 SF	11	1518919
B2032	Building Exterior	Good	Exterior Door, Steel	1	39	1518917
Roofing						
B3011	Roof	Good	Roof, Cool Reflective Coating	1,200 SF	9	1578618
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Fiberglass Panel	882 SF	49	1518922
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	882 SF	9	1518921
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	882 SF	24	1518920
HVAC						
D3051	P31	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465787
Electrical						
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518923
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	882 SF	19	1518924

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518926

Ina Arbuckle Elementary School / Portable P32

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						
B2011	Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,300 SF	11	1518927
B2032	Building Exterior	Good	Exterior Door, Steel	1	39	1518925
Roofing						
B3011	Roof	Good	Roof, Cool Reflective Coating	1,200 SF	9	1578619
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Fiberglass Panel	882 SF	49	1518930
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	882 SF	9	1518929
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	882 SF	24	1518928
HVAC						
D3051	P32	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465783
Electrical						
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518931
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	882 SF	19	1518932

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518934
Facade						
B2011	Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,300 SF	11	1518935
B2032	Building Exterior	Good	Exterior Door, Steel	1	39	1518933
Roofing						
B3011	Roof	Good	Roof, Cool Reflective Coating	1,200 SF	9	1578620
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Fiberglass Panel	882 SF	49	1518938
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	882 SF	9	1518937
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	882 SF	24	1518936
HVAC						

Ina Arbuckle Elementary School / Portable P33

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D3051	P33	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465785
Electrical						
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518939
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	1,000 SF	19	1518940

Ina Arbuckle Elementary School / Portable P34

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518942
Facade						
B2011	Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,600 SF	11	1518943
B2032	Building Exterior	Good	Exterior Door, Steel	1	39	1518941
Roofing						
B3011	Roof	Good	Roof, Cool Reflective Coating	1,850 SF	9	1578621
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Fiberglass Panel	1,100 SF	49	1518946
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	1,253 SF	9	1518945
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	1,253 SF	24	1518944
HVAC						
D3051	P34	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465805
Electrical						
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518947
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	1,253 SF	19	1518948

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518950
Facade						
B2011	Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,600 SF	11	1518951

Ina Arbuckle Elementary School / Portable P35

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
B2032	Building Exterior	Good	Exterior Door, Steel	1	39	1518949
Roofing						
B3011	Roof	Good	Roof, Cool Reflective Coating	1,850 SF	9	1578622
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Fiberglass Panel	1,100 SF	49	1518954
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	1,253 SF	9	1518953
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	1,253 SF	24	1518952
HVAC						
D3051	P35	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465793
Electrical						
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518955
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	1,253 SF	19	1518956

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518958
Facade						
B2011	Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,600 SF	11	1518959
B2032	Building Exterior	Good	Exterior Door, Steel	1	39	1518957
Roofing						
B3011	Roof	Good	Roof, Cool Reflective Coating	1,850 SF	9	1578623
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Fiberglass Panel	1,100 SF	49	1518962
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	1,253 SF	9	1518961
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	1,253 SF	24	1518960
HVAC						
D3051	P36	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465803
Electrical						

Ina Arbuckle Elementary School / Portable P36

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518963
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	1,253 SF	19	1518964

Ina Arbuckle Elementary School / Portable P37

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518966
Facade						
B2011	Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,300 SF	11	1518967
B2032	Building Exterior	Good	Exterior Door, Steel	1	39	1518965
Roofing						
B3011	Roof	Good	Roof, Cool Reflective Coating	1,200 SF	9	1578624
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Fiberglass Panel	1,000 SF	49	1518970
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	882 SF	9	1518969
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	882 SF	24	1518968
HVAC						
D3051	P37	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465782
Electrical						
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518971
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	882 SF	19	1518972

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518974
Facade						
B2011	Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,300 SF	11	1518975
B2032	Building Exterior	Good	Exterior Door, Steel	1	39	1518973
Roofing						

Ina Arbuckle Elementary School / Portable P38

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
B3011	Roof	Good	Roof, Cool Reflective Coating	1,200 SF	9	1578625
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Fiberglass Panel	1,000 SF	49	1518978
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	882 SF	9	1518977
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	882 SF	24	1518976
HVAC						
D3051	P38	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465792
Electrical						
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518979
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	882 SF	19	1518980

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518982
Facade						
B2011	Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,300 SF	11	1518983
B2032	Building Exterior	Good	Exterior Door, Steel	1	39	1518981
Roofing						
B3011	Roof	Good	Roof, Cool Reflective Coating	1,200 SF	9	1578626
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Fiberglass Panel	1,000 SF	49	1518986
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	882 SF	9	1518985
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	1,000 SF	24	1518984
HVAC						
D3051	P39	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465795
Electrical						
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518987
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	882 SF	19	1518988

Ina Arbuckle Elementary School / Portable P40

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518990
Facade						
B2011	Building Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,300 SF	11	1518991
B2032	Building Exterior	Good	Exterior Door, Steel	1	39	1518989
Roofing						
B3011	Roof	Good	Roof, Cool Reflective Coating	1,200 SF	9	1578627
Interiors						
C1011	Throughout building	Good	Interior Wall Construction, Fiberglass Panel	1,000 SF	49	1518994
C3025	Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	882 SF	9	1518993
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	882 SF	24	1518992
HVAC						
D3051	P40	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465788
Electrical						
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1518995
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	882 SF	19	1518996

Building Exterior Building Exterior	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518998
	Good	Exterior Stair/Ramp Rails, Wood, Refinish	90 LF	9	1518998
Building Exterior					
Building Exterior					
Zananig Exterior	Good	Exterior Wall, Textured Plywood (T1-11)	1,300 SF	11	1518999
Building Exterior	Good	Exterior Door, Steel	1	39	1518997
Roof	Good	Roof, Cool Reflective Coating	1,200 SF	9	1578628
Throughout building	Good	Interior Wall Construction, Fiberglass Panel	1,000 SF	49	1519002
Throughout building	Good	Interior Floor Finish, Carpet Commercial Tile	882 SF	9	1519001
	Building Exterior Roof Throughout building	Building Exterior Good Roof Good Throughout building Good	Building Exterior Good Exterior Door, Steel Roof Good Roof, Cool Reflective Coating Throughout building Good Interior Wall Construction, Fiberglass Panel	Building Exterior Good Exterior Door, Steel 1 Roof Good Roof, Cool Reflective Coating 1,200 SF Throughout building Good Interior Wall Construction, Fiberglass Panel 1,000 SF	Building Exterior Good Exterior Door, Steel 1 39 Roof Good Roof, Cool Reflective Coating 1,200 SF 9 Throughout building Good Interior Wall Construction, Fiberglass Panel 1,000 SF 49

Ina Arbuckle Elementary School / Portable P41

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
C3032	Throughout building	Good	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	882 SF	24	1519000
HVAC						
D3051	P41	Fair	Air Conditioner, 2.5 - 5 TON	1	4	1465773
Electrical						
D5022	Building exterior	Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	1	19	1519003
D5029	Throughout building	Good	Lighting System, Interior, Low Density & Standard Fixtures	882 SF	19	1519004

Ina Arbuckle Elementary School / Portable Restrooms

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						
B2011	Building Exterior	Fair	Exterior Wall, Stucco, 1-2 Stories, Prep & Fog Coat or Paint	50 SF	9	1465794
Roofing						
B3011	Roof	Good	Roof, Cool Reflective Coating	1,200 SF	9	1578629
Interiors						
C1031	Restrooms	Good	Toilet Partitions, Plastic/Laminate	6	19	1465791
Plumbing						
D2011	Restrooms	Good	Toilet, Commercial Water Closet	8	29	1465780
D2012	Restrooms	Good	Urinal, Standard	2	29	1465796
D2014	Restrooms	Good	Sink/Lavatory, Wall-Hung, Vitreous China	6	29	1465801
D2018	Building exterior	Good	Drinking Fountain, Outside/Site Style	2	14	1465771

Ina Arbuckle Elementary School / Site

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Roofing						
B3016	Roof	Good	Gutters & Downspouts, Aluminum w/ Fittings	200 LF	19	1465685
Plumbing						
D2018	Site	Fair	Drinking Fountain, Outside/Site Style	3	6	1465687
Electrical						
D5012		Good	Secondary Transformer, 300 kVA	1	27	1465679
D5012		Good	Main Distribution Panel, 800 AMP	1	29	1465686

Ina Arbuckle Elementary School / Site

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D5012		Good	Building/Main Switchboard, 800 AMP	1	38	1465684
D5022		Good	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W	10	19	1465676
Fire Alarm & C	Comm					
D5037		Good	Fire Alarm Control Panel, Addressable	1	14	1465692
Pavement						
G2022	Site	Good	Parking Lots, Asphalt Pavement, Seal & Stripe	30,000 SF	4	1465673
G2022	Site	Poor	Parking Lots, Asphalt Pavement, Cut & Patch	10,000 SF	0	1465680
G2031	Site	Good	Pedestrian Pavement, Sidewalk, Concrete Sections/Small Areas	5,000 SF	41	1465671
G2031	Site	Fair	Pedestrian Pavement, Sidewalk, Concrete Large Areas	15,000 SF	41	1465691
G2035	Site	Good	Exterior Stairs & Ramps, Concrete (per LF of Nosing)	3,000 LF	49	1465683
Site Developm	nent					
G2041	Site	Good	Fences & Gates, Metal Tube, 6' High	600 LF	39	1465690
G2041	Site	Fair	Fences & Gates, Chain Link, 6' High	3,000 LF	39	1465678
G2045	Site	Good	Site Furnishings, Picnic Table, Plastic-Coated Metal	2	24	1465672
G2045	Site	Good	Site Furnishings, Bike Rack	2	24	1465693
G2045	Site	Good	Site Furnishings, Picnic Table, Plastic-Coated Metal	10	24	1465675
G2047	Site	Good	Play Surfaces & Sports Courts, Sand, 3" Depth	2,700 SF	19	1465666
G2047	Site	Good	Play Surfaces & Sports Courts, Poured-in-place Rubber	100 SF	19	1465674
G2047	Site	Good	Play Surfaces & Sports Courts, Asphalt, Mill & Overlay	30,000 SF	16	1465670
G2047	Site	Good	Play Structure, Small	1	19	1465688
G2047	Site	Failed	Play Structure, Large	1	0	1465677
G2047	Site	Good	Play Structure, Very Small	3	19	1465669
G2047	Site	Good	Play Structure, Swing Set only, 4 Seats	2	19	1465681
G2047	Site	Good	Play Surfaces, Artificial Turf, 1/2" Pile, 5/16" Pad	400 SF	19	1465689
G2048	Site	Good	Flagpole, Metal	1	29	1465682

Appendix E: Replacement Reserves



emg

11/29/2019

11/29/2019

Location	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	Total Escalated Estima
Ina Arbuckle Elementary School	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	
Ina Arbuckle Elementary School / Building A-B	\$0	\$0	\$0	\$0	\$0	\$0	\$19,034	\$0	\$0	\$64,333	\$0	\$0	\$0	\$0	\$59,945	\$0	\$0	\$0	\$0	\$590,147	\$0	\$733,45
Ina Arbuckle Elementary School / Building C	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$59,046	\$0	\$34,478	\$0	\$0	\$23,358	\$0	\$0	\$0	\$0	\$210,205	\$0	\$327,08
Ina Arbuckle Elementary School / Building D	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$61,213	\$0	\$0	\$0	\$0	\$18,754	\$0	\$39,969	\$0	\$0	\$194,055	\$0	\$313,99
Ina Arbuckle Elementary School / Building E	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$61,213	\$0	\$0	\$0	\$0	\$18,754	\$0	\$0	\$0	\$0	\$220,454	\$0	\$300,42
Ina Arbuckle Elementary School / Building F	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$64,968	\$0	\$0	\$0	\$0	\$10,047	\$0	\$39,969	\$0	\$0	\$202,305	\$0	\$317,28
Ina Arbuckle Elementary School / Building G	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$60,130	\$0	\$0	\$0	\$0	\$27,963	\$0	\$39,969	\$0	\$0	\$249,746	\$0	\$377,80
Ina Arbuckle Elementary School / Building H	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$47,578	\$0	\$0	\$0	\$0	\$25,619	\$0	\$0	\$0	\$0	\$493,901	\$0	\$567,09
Ina Arbuckle Elementary School / Portable P21	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$25,798	\$0	\$78,30
Ina Arbuckle Elementary School / Portable P22	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$25,798	\$0	\$78,30
Ina Arbuckle Elementary School / Portable P23	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$25,798	\$0	\$78,30
Ina Arbuckle Elementary School / Portable P24	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$25,798	\$0	\$78,30
Ina Arbuckle Elementary School / Portable P25	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$25,798	\$0	\$78,30
Ina Arbuckle Elementary School / Portable P26	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$25,798	\$0	\$78,30
Ina Arbuckle Elementary School / Portable P27	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$25,798	\$0	\$78,30
Ina Arbuckle Elementary School / Portable P28	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$12,357	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$27,287	\$0	\$80,89
Ina Arbuckle Elementary School / Portable P29	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$25,798	\$0	\$78,30
Ina Arbuckle Elementary School / Portable P30	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$25,798	\$0	\$78,30
Ina Arbuckle Elementary School / Portable P31	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$25,798	\$0	\$78,30
Ina Arbuckle Elementary School / Portable P32	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$25,798	\$0	\$78,30
Ina Arbuckle Elementary School / Portable P33	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$27,172	\$0	\$79,67
Ina Arbuckle Elementary School / Portable P34	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$16,235	\$0	\$30,647	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$36,819	\$0	\$100,05
Ina Arbuckle Elementary School / Portable P35	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$16,235	\$0	\$30,647	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$36,819	\$0	\$100,05
Ina Arbuckle Elementary School / Portable P36	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$16,235	\$0	\$30,647	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$36,819	\$0	\$100,05
Ina Arbuckle Elementary School / Portable P37	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$25,798	\$0	\$78,30
Ina Arbuckle Elementary School / Portable P38	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$25,798	\$0	\$78,30
Ina Arbuckle Elementary School / Portable P39	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$25,798	\$0	\$78,30
Ina Arbuckle Elementary School / Portable P40	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$25,798	\$0	\$78,30
Ina Arbuckle Elementary School / Portable P41	\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$25,798	\$0	\$78,30
Ina Arbuckle Elementary School / Portable Restrooms	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,004	\$0	\$0	\$0	\$0	\$12,056	\$0	\$0	\$0	\$0	\$12,773	\$0	\$27,83
Ina Arbuckle Elementary School / Site	\$38,745	\$0	\$41,105	\$0	\$16,820	\$0	\$14,276	\$0	\$0	\$19,499	\$0	\$0	\$0	\$0	\$47,721	\$0	\$186,523	\$0	\$0	\$114,638	\$69,978	\$549,30
Grand Total	\$38,745	\$0	\$41,105	\$0	\$163,343		\$33,310			\$693,283	\$0	\$574,630	\$0							, ,	\$69,978	\$5,227,86

Ina Arbuckle Elementary School

 * Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Building A-B

Uniformat Code	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	yUnit	Unit Cost *	Subtota	I 2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039 F	ciency Repair timate
B2011	14656	Exterior Wall, Stucco, 1-2 Stories, Prep & Fog Coat or Paint	10	1	9	3000	SF	\$3.54	\$10,62	27								9	\$10,627										\$10,627	\$2	21,254
B3011	15786	Roof, Single-Ply TPO/PVC Membrane, Replace	20	1	19	8500	SF	\$18.82	\$159,96	62																		\$	159,962	\$15	59,962
C3012	14654	Interior Wall Finish, Fabric, Replace	15	1	14	2000	SF	\$2.21	\$4,42	28														\$4,428							Help 54,428

https://www.assetcalc.net/Reports/ReplacementReserve.aspx

Uniformat Code	ID	Coet Description	Lifespan (EUL)	EAge RUL	Qua	ntityUnit	Unit Cost * Subtotal 2	2019 2	2020 202	1 2022	2023	2024 2025	2026 2027	2028	2029	2030	2031	2032 2033	2034	2035	2036 2	2037 2038	Deficiency 2039 Repair Estimate
C3024	146541	16 Interior Floor Finish, Vinyl Tile (VCT), Replace	15	1 1	1 56	800 SF	\$5.54 \$30,996											\$30,996					\$30,996
C3025	146565	Interior Floor Finish, Carpet Commercial Tile, Replace	10	1 9	30	000 SF	\$7.20 \$21,587						\$2	1,587								\$21,587	\$43,173
D2018	146565	Drinking Fountain, Interior, Replace	15	1 1	1	2 EA	\$2,103.30 \$4,207											\$4,207					\$4,207
D3051	146542	24 Air Conditioner, 1 TON, Replace	10	1 9		1 EA	\$2,435.40 \$2,435						\$	2,435								\$2,435	\$4,871
D3051	146542	29 Air Conditioner, 1 TON, Replace	10	1 9		1 EA	\$2,435.40 \$2,435						3	2,435								\$2,435	\$4,871
D3052	154764	Packaged Unit (RTU), 4 TON, Replace	20	1 1	9	1 EA	\$9,963.00 \$9,963															\$9,963	\$9,963
D3052	155056	Packaged Unit (RTU), 2 TON, Replace	20	1 1	9	1 EA	\$6,088.50 \$6,089															\$6,089	\$6,089
D3052	154764	Packaged Unit (RTU), 3 TON, Replace	20	1 1	9	1 EA	\$8,302.50 \$8,303															\$8,303	\$8,303
D3052	155055	Packaged Unit (RTU), 2 TON, Replace	20	1 1	9	1 EA	\$6,088.50 \$6,089															\$6,089	\$6,089
D3052	154765	Packaged Unit (RTU), 5 TON, Replace	20	1 1	9	1 EA	\$12,177.00 \$12,177															\$12,177	\$12,177
D3052	154764	Packaged Unit (RTU), 3 TON, Replace	20	1 1	9	1 EA	\$8,302.50 \$8,303															\$8,303	\$8,303
D5022	146566	63 Light Fixture, 50 WATT, Replace	20	1 1	9	5 EA	\$210.33 \$1,052															\$1,052	\$1,052
D5029	146541	14 Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1 1	85	504 SF	\$6.64 \$56,484															\$56,484	\$56,484
D5037	146541	17 Fire Alarm System, Basic/Zoned, Upgrade/Install	20	1 1	9 85	504 SF	\$2.21 \$18,828															\$18,828	\$18,828
D5092	146564	Exit Sign Light Fixture, LED, Replace	10	1 9		7 EA	\$243.54 \$1,705						\$	1,705								\$1,705	\$3,410
E1093	146542	Commercial Kitchen, Range/Oven, 4-Burner, Replace	15	9 6		1 EA	\$4,981.50 \$4,982					\$4,982											\$4,982
E1093	146541	18 Commercial Kitchen, Food Warmer, Replace	15	9 6		1 EA	\$1,881.90 \$1,882					\$1,882											\$1,882
E1093	146541	Ommercial Kitchen, Refrigerator, 2-Door Reach-In, Replace	15	9 6		1 EA	\$5,092.20 \$5,092					\$5,092											\$5,092
E1093	146541	Commercial Kitchen, Dairy Cooler/Wells, Replace	15	9 6		1 EA	\$3,985.20 \$3,985					\$3,985											\$3,985
E1093	146542	Commercial Kitchen, Convection Oven, Double, Replace	10	1 9		1 EA	\$10,516.50 \$10,517						\$1	0,517								\$10,517	\$21,033
Totals, Unes	calated							\$0	\$0 \$0	\$0	\$0	\$0 \$15,941	\$0 \$0 \$4	9,306	\$0	\$0	\$0	\$0 \$39,631	\$0	\$0	\$0	\$0 \$336,552	\$0 \$441,430
Totals, Escal	ated (3.0°	% inflation, compounded annually)						\$0	\$0 \$0	\$0	\$0	\$0 \$19,034	\$0 \$0 \$6	4,333	\$0	\$0	\$0	\$0 \$59,945	\$0	\$0	\$0	\$0 \$590,147	\$0 \$733,458

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Building C

Uniformat Code	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost * S	ubtotal 20	19	2020	2021	2022	2023 2	2024	2025	2026 2	2027 2028	2029 2030	2031	2032 2033	2034	2035	2036	2037 2038	2039	Deficiency Repair Estimate
B2011	1519557	7 Exterior Wall, Stucco, 1-2 Stories, Prep & Fog Coat or Paint	10	1	9	7400	SF	\$3.54	\$26,214									\$26,214							\$26,214		\$52,428
C1031	1519561	Toilet Partitions, Plastic/Laminate, Replace	20	1	19	3	EA	\$830.25	\$2,491																\$2,491		\$2,491
C3012	1519558	Interior Wall Finish, any surface, Prep & Paint	10	1	9	5400	SF	\$1.66	\$8,967									\$8,967							\$8,967		\$17,933
C3012	151955	1 Interior Wall Finish, Vinyl, Replace	15	1	14	500	SF	\$2.77	\$1,384												\$1,384						\$1,384
C3024	1519546	Interior Floor Finish, Vinyl Tile (VCT), Replace	15	1	14	1100	SF	\$5.54	\$6,089												\$6,089						\$6,089
C3025	1519542	Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	1400	SF	\$7.20	\$10,074									\$10,074							\$10,074		\$20,147
D2018	1519553	Drinking Fountain, Outside/Site Style, Replace	15	1	14	2	EA	\$3,985.20	\$7,970												\$7,970						\$7,970
D3052	1519560	Packaged Unit (RTU), 3 TON, Replace	20	9	11	3	EA	\$8,302.50	\$24,908										\$24,908								\$24,908
D3052	1550565	Packaged Unit (RTU), 5 TON, Replace	20	1	19	1	EA	\$12,177.00	\$12,177																\$12,177		\$12,177
D3052	1550564	Packaged Unit (RTU), 3.5 TON, Replace	20	1	19	1	EA	\$9,077.40	\$9,077																\$9,077		\$9,077
D3052	1550566	Packaged Unit (RTU), 5 TON, Replace	20	1	19	1	EA	\$12,177.00	\$12,177																\$12,177		\$12,177
D5022	1519556	C Light Fixture, 50 WATT, Replace	20	1	19	8	EA	\$210.33	\$1,683																\$1,683		\$1,683
D5029	1519555	Lighting System, Interior, Low Density & Standard Fixtures, Replace	ce 20	1	19	4180	SF	\$6.64	\$27,764																\$27,764		\$27,764
D5037	1519541	1 Fire Alarm System, Basic/Zoned, Upgrade/Install	20	1	19	4180	SF	\$2.21	\$9,255																\$9,255		\$9,255
Totals, Unes	scalated									\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0 \$45,254	\$0 \$24,908	\$0	\$0 \$15,443	\$0	\$0	\$0	\$0 \$119,877	\$0	\$205,481
Totals, Esca	lated (3.0%	inflation, compounded annually)								\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0 \$59,046	\$0 \$34,478	\$0	\$0 \$23,358	\$0	\$0	\$0	\$0 \$210,205	\$0	\$327,088

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Help

Ina Arbuckle	Elementa	ry School / Building D																										
Uniformat Code	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	yUnit	Unit Cost * Subtotal2	2019	2020	2021	2022	2023 2	2024	2025	2026	2027 2028	2029	2030	2031	2032	2033	2034 2035	2036	2037	2038 2	2039	Deficiency Repair Estimate
B2011	1519533	3 Exterior Wall, Stucco, 1-2 Stories, Prep & Fog Coat or Paint	10	1	9	6400	SF	\$3.54 \$22,671									\$22,671									\$22,671		\$45,343
C1031	1519519	Toilet Partitions, Plastic/Laminate, Replace	20	1	19	5	EA	\$830.25 \$4,151																		\$4,151		\$4,151
C3012	1519529	Interior Wall Finish, any surface, Prep & Paint	10	1	9	5500	SF	\$1.66 \$9,133									\$9,133									\$9,133		\$18,266
C3024	1519518	Interior Floor Finish, Vinyl Tile (VCT), Replace	15	1	14	800	SF	\$5.54 \$4,428													\$4	428						\$4,428
C3025	1519538	Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	2100	SF	\$7.20 \$15,111									\$15,111									\$15,111		\$30,221
D2018	1519532	2 Drinking Fountain, Outside/Site Style, Replace	15	1	14	2	EA	\$3,985.20 \$7,970													\$7	,970						\$7,970
D3052	1519526	Packaged Unit (RTU), 3 TON, Replace	20	4	16	3	EA	\$8,302.50 \$24,908															\$24,908					\$24,908
D3052	155056	Packaged Unit (RTU), 5 TON, Replace	20	1	19	1	EA	\$12,177.00 \$12,177																		\$12,177		\$12,177
D3052	1550573	Packaged Unit (RTU), 5 TON, Replace	20	1	19	1	EA	\$12,177.00 \$12,177																		\$12,177		\$12,177
D5022	1519537	Light Fixture, 50 WATT, Replace	20	1	19	8	EA	\$210.33 \$1,683																		\$1,683		\$1,683
D5029	1519520	Lighting System, Interior, Low Density & Standard Fixtures, Replace	e 20	1	19	3790	SF	\$6.64 \$25,173																		\$25,173		\$25,173
D5037	1519527	Fire Alarm System, Basic/Zoned, Upgrade/Install	20	1	19	3790	SF	\$2.21 \$8,391																		\$8,391		\$8,391
Totals, Unes	calated								\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0 \$46,915	\$0	\$0	\$0	\$0 \$12	,398	\$0 \$24,908	\$0	\$0 \$	110,667	\$0	\$194,887
Totals, Esca	lated (3.0%	inflation, compounded annually)							\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0 \$61,213	\$0	\$0	\$0	\$0 \$18	,754	\$0 \$39,969	\$0	\$0 \$	194,055	\$0	\$313,991

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Building E

Uniformat Code	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit Unit Cost * Subtota	12019	2020	2021	2022	2023	2024	2025	2026	2027 2028	2029	2030	2031	2032 2033	2034	2035	2036	2037 2038	2039	Deficiency Repair Estimate
B2011	157858	6 Exterior Wall, Stucco, 1-2 Stories, Prep & Fog Coat or Paint	10	1	9	6400	SF \$3.54 \$22,67	1								\$22,671								\$22,671		\$45,343
C1031	157859	1 Toilet Partitions, Plastic/Laminate, Replace	20	1	19	5	EA \$830.25 \$4,15	1																\$4,151		\$4,151
C3012	157859	3 Interior Wall Finish, any surface, Prep & Paint	10	1	9	5500	SF \$1.66 \$9,133	3								\$9,133								\$9,133		\$18,266
C3024	157859	5 Interior Floor Finish, Vinyl Tile (VCT), Replace	15	1	14	800	SF \$5.54 \$4,428	3												\$4,428						\$4,428
C3025	157859	6 Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	2100	SF \$7.20 \$15,111	1								\$15,111								\$15,111		\$30,221
D2018	157860	3 Drinking Fountain, Outside/Site Style, Replace	15	1	14	2	EA \$3,985.20 \$7,970	0												\$7,970						\$7,970
D3052	155056	0 Packaged Unit (RTU), 5 TON, Replace	20	1	19	1	EA \$12,177.00 \$12,177	7																\$12,177		\$12,177
D3052	155056	7 Packaged Unit (RTU), 3.5 TON, Replace	20	1	19	1	EA \$9,077.40 \$9,077	7																\$9,077		\$9,077
D3052	155056	8 Packaged Unit (RTU), 3.5 TON, Replace	20	1	19	1	EA \$9,077.40 \$9,077	7																\$9,077		\$9,077
D3052	155057	2 Packaged Unit (RTU), 3.5 TON, Replace	20	1	19	1	EA \$9,077.40 \$9,077	7																\$9,077		\$9,077
D5022	157860	5 Light Fixture, 50 WATT, Replace	20	1	19	8	EA \$210.33 \$1,683	3																\$1,683		\$1,683
D5029	157860	6 Lighting System, Interior, Low Density & Standard Fixtures, Replac	e 20	1	19	3790	SF \$6.64 \$25,173	3																\$25,173		\$25,173
D5037	157860	7 Fire Alarm System, Basic/Zoned, Upgrade/Install	20	1	19	3790	SF \$2.21 \$8,39°	1																\$8,391		\$8,391
Totals, Unes	scalated							\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0 \$46,915	\$0	\$0	\$0	\$0 \$12,398	\$0	\$0	\$0	\$0 \$125,722	\$0	\$185,035
Totals, Esca	alated (3.0%	6 inflation, compounded annually)						\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0 \$61,213	\$0	\$0	\$0	\$0 \$18,754	\$0	\$0	\$0	\$0 \$220,454	\$0	\$300,421

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Building F

Uniformat Code	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	yUnit	Unit Cost * Subtotal 2019	2020 202 ⁻	1 2022 202	3 2024	2025 2026	2027 2028	2029	2030 203 ⁻	1 2032	2033	2034	2035	2036 2	37 203	3 2039	Deficiency Repair Estimate
B2011	1519447 Exterior Wall, Stucco, 1-2 Stories, Prep & Fog Coat or Paint	10	1	9	6400	SF	\$3.54 \$22,671					\$22,671								\$22,671		\$45,343
C3012	1519436 Interior Wall Finish, any surface, Prep & Paint	10	1	9	5500	SF	\$1.66 \$9,133					\$9,133								\$9,133		\$18,266
C3024	1519453 Interior Floor Finish, Vinyl Tile (VCT), Replace	15	1	14	1200	SF	\$5.54 \$6,642									\$6,642						\$6,642
C3025	1519437 Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	2500	SF	\$7.20 \$17,989					\$17,989								\$17,989		35,97 8

Uniformat Code	ID Coet Description	Lifespan (EUL)	EAge	RUL	Quantit	yUnit	Unit Cost *	Subtotal	2019	2020	2021	2022	2023	2024	2025	2026	3 2027	2028	2029	2030	2031	2032	2 2033	2034	2035	2036	2037	2038	2039	Deficiency Repair Estimate
D3052	1519439 Packaged Unit (RTU), 3 TON, Replace	20	4	16	3	EA	\$8,302.50	\$24,908																	\$24,908					\$24,908
D3052	1550563 Packaged Unit (RTU), 3.5 TON, Replace	20	1	19	1	EA	\$9,077.40	\$9,077																			\$	9,077		\$9,077
D3052	1550574 Packaged Unit (RTU), 3.5 TON, Replace	20	1	19	1	EA	\$9,077.40	\$9,077																			\$	9,077		\$9,077
D3052	1550559 Packaged Unit (RTU), 5 TON, Replace	20	1	19	1	EA	\$12,177.00	\$12,177																			\$1	12,177		\$12,177
D5022	1519442 Light Fixture, 50 WATT, Replace	20	1	19	8	EA	\$210.33	\$1,683																			\$	\$1,683		\$1,683
D5029	1519441 Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	3790	SF	\$6.64	\$25,173																			\$2	25,173		\$25,173
D5037	1519446 Fire Alarm System, Basic/Zoned, Upgrade/Install	20	1	19	3790	SF	\$2.21	\$8,391																			\$	88,391		\$8,391
Totals, Unes	scalated								\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0 \$	\$49,793	\$0	\$0	\$0	\$0	\$6,642	\$0	\$24,908	\$0	\$0 \$11	15,372	\$0	\$196,714
Totals, Esca	alated (3.0% inflation, compounded annually)								\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0 \$	64,968	\$0	\$0	\$0	\$0	\$10,047	\$0	\$39,969	\$0	\$0 \$20	2,305	\$0	\$317,289

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Building G

Uniformat Code	ID	Cost Description	Lifespan (EUL)	EAge R	RUL	Quantity	Unit Unit Cost * Subtotal	2019	2020	2021	2022	2023	2024	2025	2026	2027 2028	2029	2030	2031	2032 2033	2034 2035	2036	2037 2038	2039	eficiency Repair Estimate
B2011	15194	28 Exterior Wall, Stucco, 1-2 Stories, Prep & Fog Coat or Paint	10	1	9	5400	SF \$3.54 \$19,129									\$19,129							\$19,129		\$38,258
C3012	15194	30 Interior Wall Finish, any surface, Prep & Paint	10	1	9	5400	SF \$1.66 \$8,967									\$8,967							\$8,967		\$17,933
C3024	15194	19 Interior Floor Finish, Vinyl Tile (VCT), Replace	15	1	14	1100	SF \$5.54 \$6,089													\$6,089					\$6,089
C3025	15194	.22 Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	2500	SF \$7.20 \$17,989									\$17,989							\$17,989		\$35,978
D2018	15194	29 Drinking Fountain, Outside/Site Style, Replace	15	1	14	2	EA \$3,985.20 \$7,970													\$7,970					\$7,970
D3052	15194	26 Packaged Unit (RTU), 3 TON, Replace	20	4	16	3	EA \$8,302.50 \$24,908														\$24,908				\$24,908
D3052	15476	Packaged Unit (RTU), 5 TON, Replace	20	1	19	1	EA \$12,177.00 \$12,177																\$12,177		\$12,177
D3052	15476	Packaged Unit (RTU), 5 TON, Replace	20	1	19	1	EA \$12,177.00 \$12,177																\$12,177		\$12,177
D3052	15505	Packaged Unit (RTU), 5 TON, Replace	20	1	19	1	EA \$12,177.00 \$12,177																\$12,177		\$12,177
D3052	15505	69 Packaged Unit (RTU), 5 TON, Replace	20	1	19	1	EA \$12,177.00 \$12,177																\$12,177		\$12,177
D3052	15505	71 Packaged Unit (RTU), 5 TON, Replace	20	1	19	1	EA \$12,177.00 \$12,177																\$12,177		\$12,177
D5022	15194	32 Light Fixture, 50 WATT, Replace	20	1	19	9	EA \$210.33 \$1,893																\$1,893		\$1,893
D5029	15194	20 Lighting System, Interior, Low Density & Standard Fixtures, Replace	e 20	1	19	3790	SF \$6.64 \$25,173																\$25,173		\$25,173
D5037	15194	23 Fire Alarm Control Panel, Basic/Zoned, Replace	15	1	14	1	EA \$4,428.00 \$4,428													\$4,428					\$4,428
D5037	15194	27 Fire Alarm System, Basic/Zoned, Upgrade/Install	20	1	19	3790	SF \$2.21 \$8,391																\$8,391		\$8,391
Totals, Une	scalated							\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0 \$46,084	\$0	\$0	\$0	\$0 \$18,487	\$0 \$24,908	\$0	\$0 \$142,427	\$0	\$231,905
Totals, Esc	alated (3.0)% inflation, compounded annually)						\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0 \$60,130	\$0	\$0	\$0	\$0 \$27,963	\$0 \$39,969	\$0	\$0 \$249,746	\$0	\$377,808

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Building H

Uniformat Code	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost *	Subtotal 2	019 202	20 2021	1 2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	Deficiency Repair Estimate
B3011	1578633 Roof, Single-Ply TPO/PVC Membrane, Replace	20	1	19	9500	SF	\$18.82	\$178,781																		\$1	78,781		\$178,781
C3024	1547701 Interior Floor Finish, Vinyl Sheeting, Replace	15	1	14	1500	SF	\$7.75	\$11,624													9	511,624							\$11,624
C3024	1547703 Interior Floor Finish, Vinyl Tile (VCT), Replace	15	1	14	200	SF	\$5.54	\$1,107														\$1,107							\$1,107
C3025	1547707 Interior Floor Finish, Carpet Commercial Tile, Re	eplace 10	1	9	5000	SF	\$7.20	\$35,978								5	\$35,978									\$	35,978		\$71,955
D2018	1547704 Drinking Fountain, Interior, Replace	15	1	14	2	EA	\$2,103.30	\$4,207														\$4,207							\$4,207
D3052	1547653 Packaged Unit (RTU), 4 TON, Replace	20	1	19	1	EA	\$9,963.00	\$9,963																			\$9,963		\$9,963
D3052	1547644 Packaged Unit (RTU), 5 TON, Replace	20	1	19	1	EA	\$12,177.00	\$12,177																		\$	12,177		\$12,177
D3052	1547646 Packaged Unit (RTU), 5 TON, Replace	20	1	19	1	EA	\$12,177.00	\$12,177																		\$	12,177		\$12,177
D3052	1547652 Packaged Unit (RTU), 5 TON, Replace	20	1	19	1	EA	\$12,177.00	\$12,177																		\$	12,177		3 \$12; 137 70

Uniformat Code	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	yUnit	Unit Cost *	Subtotal	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	Deficiency Repair Estimate
D5037	1547709 Fire Alarm System, Basic/Zoned, Upgrade/Install	20	1	19	9000	SF	\$2.21	\$19,926																				\$19,926		\$19,926
D5092	1547694 Exit Sign Light Fixture, LED, Replace	10	1	9	2	EA	\$243.54	\$487										\$487										\$487		\$974
Totals, Uneso	scalated								\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$36,465	\$0	\$0	\$0	\$0 \$	16,937	\$0	\$0	\$0	\$0	\$281,665	\$0	\$335,067
Totals, Escal	lated (3.0% inflation, compounded annually)								\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$47,578	\$0	\$0	\$0	\$0 \$	25,619	\$0	\$0	\$0	\$0	\$493,901	\$0	\$567,098

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Uniformat Code	ID		Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost * Subtota	12019	2020	2021	2022 2023	2024	2025	2026	2027	2028	2029 2	030	2031 203	2 2033	2034	2035	2036	2037	7 2038	2039	eficiency Repair Estimate
B1015	151883	8 Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.66 \$150									\$150									\$150		\$299
B2011	151883	9 Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1300	SF	\$13.84 \$17,989										\$17,	989									\$17,989
B3011	157860	Roof, Cool Reflective Coating	10	1	9	1200	SF	\$1.77 \$2,125	1								\$2,125									\$2,125		\$4,251
C3025	151884	Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	882	SF	\$7.20 \$6,346									\$6,346									\$6,346		\$12,693
D3051	146579	9 Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.20 \$6,199				\$6,199									\$6,199							\$12,398
D5022	151884	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace	20	1	19	1	EA	\$232.47 \$232																		\$232		\$232
D5029	151884	4 Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	882	SF	\$6.64 \$5,858																		\$5,858		\$5,858
Totals, Une	scalated								\$0	\$0	\$0	\$0 \$6,199	\$0	\$0	\$0	\$0	\$8,622	\$0 \$17,	989	\$0 \$0	\$6,199	\$0	\$0	\$0	\$0	\$14,712	\$0	\$53,721
Totals, Esc	alated (3	.0% inflation, compounded annually)							\$0	\$0	\$0	\$0 \$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0 \$24,	901	\$0 \$0	\$9,377	\$0	\$0	\$0	\$0	\$25,798	\$0	\$78,302

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Portable P22

Uniformat Code	II) (:0st l)ascrintion	Lifespan (EUL)	EAge	RUL	Quantit	yUnit	Unit Cost *	Subtotal	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	Deficiency 2039 Repair Estimate
B1015	1518846 Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.66	\$150										\$150										\$150	\$299
B2011	1518847 Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1300	SF	\$13.84	\$17,989											\$	17,989									\$17,989
B3011	1578609 Roof, Cool Reflective Coating	10	1	9	1200	SF	\$1.77	\$2,125										\$2,125										\$2,125	\$4,251
C3025	1518849 Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	882	SF	\$7.20	\$6,346										\$6,346										\$6,346	\$12,693
D3051	1465804 Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.20	\$6,199					\$6,199										\$6,199						\$12,398
D5022	1518851 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace	∋ 20	1	19	1	EA	\$232.47	\$232																				\$232	\$232
D5029	1518852 Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	882	SF	\$6.64	\$5,858																				\$5,858	\$5,858
Totals, Un	escalated								\$0	\$0	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0	\$8,622	\$0 \$	17,989	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0 \$	\$14,712	\$0 \$53,721
Totals, Es	calated (3.0% inflation, compounded annually)								\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0 \$	24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0 \$	\$25,798	\$0 \$78,302

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Portable P23

Uniformat Code	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	/Unit	Unit Cost	Subtotal 2019	2020	2021	2022	2023 2024	2025	2026 202	27 202	3 2029 2	30 2	2031 20	32 20	33 2034	2035	2036	2037 2038	2039	Deficiency Repair Estimate
B1015	1518854	Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.6	\$150							\$150								\$150		\$299
B2011	1518855	Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1300	SF	\$13.8	\$17,989								\$17,9	89								\$17,989
B3011	1578610	Roof, Cool Reflective Coating	10	1	9	1200	SF	\$1.7	7 \$2,125							\$2,125								\$2,125		\$4,251
C3025	1518857	Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	882	SF	\$7.20	\$6,346							\$6,346								\$6,346		\$12,693
D3051	1465772	2 Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.20	\$6,199				\$6,199							\$6,19	99					\$12,398
D5022	1518859	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace	e 20	1	19	1	EA	\$232.4	\$232															\$232		\$232
D5029	1518860	Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	882	SF	\$6.6	\$5,858															\$5,858		\$5,858 Help

Uniformat Code ID Cost Description	Lifespan EAge RUL QuantityUnit . Subtota	12019	2020	2021	2022	2023 2	024 202	5 2026	2027	2028	2029 2	030 203 ⁻	2032	2 2033	2034	2035	2036	2037 2	038 2	Deficiei 2039 Rep Estim	pair
Totals, Unescalated		\$0	\$0	\$0	\$0 \$	6,199	\$0 \$	\$0	\$0	\$8,622	\$0 \$17,9	989 \$0	\$0	\$6,199	\$0	\$0	\$0	\$0 \$14,7	712	\$0 \$53,	,721
Totals, Escalated (3.0% inflation, compounded annually)		\$0	\$0	\$0	\$0 \$	6,977	\$0 \$	\$0	\$0	\$11,249	\$0 \$24,9	901 \$0	\$0	\$9,377	\$0	\$0	\$0	\$0 \$25,7	798	\$0 \$78,	,302

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Uniformat Code	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost * Subtot	al2019	2020	2021	2022 2023	2024	2025	2026	2027	2028	2029	2030	2031 203	2 2033	2034	2035	2036	2037	7 2038	2039	eficiency Repair Estimate
B1015	151886	2 Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.66 \$15	0								\$150									\$150		\$299
B2011	151886	3 Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1300	SF	\$13.84 \$17,98	9									\$17	,989									\$17,989
B3011	157861	1 Roof, Cool Reflective Coating	10	1	9	1200	SF	\$1.77 \$2,12	5								\$2,125									\$2,125		\$4,251
C3025	151886	5 Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	882	SF	\$7.20 \$6,34	6								\$6,346									\$6,346		\$12,693
D3051	146577	7 Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.20 \$6,19	9			\$6,199									\$6,199							\$12,398
D5022	151886	7 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace	20	1	19	1	EA	\$232.47 \$23	2																	\$232		\$232
D5029	151886	8 Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	882	SF	\$6.64 \$5,85	8																	\$5,858		\$5,858
Totals, Une	scalated								\$0	\$0	\$0	\$0 \$6,199	\$0	\$0	\$0	\$0	\$8,622	\$0 \$17	,989	\$0 \$	0 \$6,199	\$0	\$0	\$0	\$0	\$14,712	\$0	\$53,721
Totals, Esc	alated (3	.0% inflation, compounded annually)							\$0	\$0	\$0	\$0 \$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0 \$24	,901	\$0 \$	0 \$9,377	\$0	\$0	\$0	\$0	\$25,798	\$0	\$78,302

 $^{^{\}star}$ Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Portable P25

Uniformat Code	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quantit	yUnit	Unit Cost s	Subtotal	2019	2020	2021	2022	2023	2024	2025	2026	2027	7 2028	2029	2030	2031	2032	2033	2034	2035	2036	2037 2038	Deficienc 2039 Repa Estimat
B1015	1518870 Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.66	\$150										\$150									\$150	\$299
B2011	1518871 Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1300	SF	\$13.84	\$17,989											\$	17,989								\$17,989
B3011	1578612 Roof, Cool Reflective Coating	10	1	9	1200	SF	\$1.77	\$2,125										\$2,125									\$2,125	\$4,25
C3025	1518873 Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	882	SF	\$7.20	\$6,346										\$6,346									\$6,346	\$12,69
D3051	1465784 Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.20	\$6,199					\$6,199										\$6,199					\$12,398
D5022	1518875 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace	20	1	19	1	EA	\$232.47	\$232																			\$232	\$23
D5029	1518876 Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	882	SF	\$6.64	\$5,858																			\$5,858	\$5,85
Totals, Ui	escalated								\$0	\$0	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0	\$8,622	\$0 \$	17,989	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0 \$14,712	\$0 \$53,72
Totals, Es	calated (3.0% inflation, compounded annually)								\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0 \$	24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0 \$25,798	\$0 \$78,302

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Portable P26

Uniformat Code	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost	Subtota	12019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029 2030	2031	2032	2033	2034	2035	2036	2037	2038	Deficiency 2039 Repair Estimate
B1015	1518878 Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.66	\$150										\$150									\$150	\$299
B2011	1518879 Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1300	SF	\$13.84	\$17,989											\$17,989									\$17,989
B3011	1578613 Roof, Cool Reflective Coating	10	1	9	1200	SF	\$1.77	\$2,125										\$2,125									\$2,125	\$4,251
C3025	1518881 Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	882	SF	\$7.20	\$6,346	1									\$6,346									\$6,346	\$12,693
D3051	1465776 Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.20	\$6,199					\$6,199								\$	6,199						\$12,398
D5022	1518883 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replacement	e 20	1	19	1	EA	\$232.47	\$232																			\$232	\$232
D5029	1518884 Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	882	SF	\$6.64	\$5,858	8																		\$5,858	\$5,858
Totals, Une	scalated								\$0	\$0	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0	\$8,622	\$0 \$17,989	\$0	\$0 \$	6,199	\$0	\$0	\$0	\$0 \$	14,712	\$0 \$53,721
Totals, Esc	alated (3.0% inflation, compounded annually)								\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0 \$24,901	\$0	\$0 \$	9,377	\$0	\$0	\$0	\$0 \$	25,798	\$0 3 578,302

Uniformat Code	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	yUnit	Unit Cost	Subtotal	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2 2033	2034	2035	2036	2037 203		ciency Repair timate
B1015	1518886 Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.66	\$150										\$150									\$15	,	\$299
B2011	1518887 Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1300	SF	\$13.84	\$17,989											\$	17,989								\$17	7,989
B3011	1578614 Roof, Cool Reflective Coating	10	1	9	1200	SF	\$1.77	\$2,125										\$2,125									\$2,12	\$4	4,251
C3025	1518889 Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	882	SF	\$7.20	\$6,346										\$6,346									\$6,34	\$12	2,693
D3051	1465778 Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.20	\$6,199					\$6,199										\$6,199					\$12	2,398
D5022	1518891 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace	e 20	1	19	1	EA	\$232.47	\$232																			\$23	:	\$232
D5029	1518892 Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	882	SF	\$6.64	\$5,858																			\$5,85	\$ \$ £	5,858
Totals, Ur	escalated								\$0	\$0	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0	\$8,622	\$0 \$	17,989	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0 \$14,71	2 \$0 \$53	3,721
Totals, Es	calated (3.0% inflation, compounded annually)								\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0 \$	24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0 \$25,79	\$0 \$78	8,302

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Portable P28

Uniformat Code	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	yUnit	Unit Cost *	Subtotal	2019	2020	2021	2022	2023	2024	2025	2026	202	7 2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	Deficiency 2039 Repair Estimate
B1015	1518894 Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.66	\$150										\$150										\$150	\$299
B2011	1518895 Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1300	SF	\$13.84	\$17,989												\$17,989									\$17,989
B3011	1578615 Roof, Cool Reflective Coating	10	1	9	1200	SF	\$1.77	\$2,125										\$2,125									\$	\$2,125	\$4,251
C3025	1518897 Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	1000	SF	\$7.20	\$7,196										\$7,196									\$	\$7,196	\$14,391
D3051	1465789 Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.20	\$6,199					\$6,199										\$6,199						\$12,398
D5022	1518899 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace	e 20	1	19	1	EA	\$232.47	\$232																				\$232	\$232
D5029	1518900 Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	882	SF	\$6.64	\$5,858																			\$	\$5,858	\$5,858
Totals, Un	escalated								\$0	\$0	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0	\$9,471	\$0	\$17,989	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0 \$1	15,561	\$0 \$55,419
Totals, Es	calated (3.0% inflation, compounded annually)								\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$12,357	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0 \$2	27,287	\$0 \$80,899

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Portable P29

Uniformat Code	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	/Unit	Unit Cost	t Subtota	12019	2020	2021	202	2 2023	2024	2025	2026	2027	2028	2029 2030	2031	2032	2 2033	2034	2035	2036	2037 20	038 20	Deficiency 339 Repair Estimate
B1015	1518902	Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.60	6 \$15)									\$150								\$15	50	\$299
B2011	1518903	Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1300	SF	\$13.84	4 \$17,98	9										\$17,989									\$17,989
B3011	1578616	Roof, Cool Reflective Coating	10	1	9	1200	SF	\$1.7	7 \$2,12	5									\$2,125								\$2,12	25	\$4,251
C3025	1518905	Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	882	SF	\$7.20	0 \$6,34	3									\$6,346								\$6,34	46	\$12,693
D3051	1465786	Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.20	0 \$6,19	9				\$6,199									\$6,199						\$12,398
D5022	1518907	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace	€ 20	1	19	1	EA	\$232.47	7 \$23	2																	\$23	32	\$232
D5029	1518908	B Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	882	SF	\$6.64	4 \$5,85	3																	\$5,85	58	\$5,858
Totals, Un	escalated									\$0	\$0	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0	\$8,622	\$0 \$17,989	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0 \$14,71	12 !	\$0 \$53,721
Totals, Esc	alated (3.0	0% inflation, compounded annually)								\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0 \$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0 \$25,79	98 !	\$0 \$78,302

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Portable P30

Help

Uniformat Code	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quantit	yUnit	Unit Cost *	Subtotal	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037 2	2038	Deficiency 2039 Repair Estimate
B1015	1518910 Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.66	\$150										\$150									\$	150	\$299
B2011	1518911 Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1300	SF	\$13.84	\$17,989											\$1	7,989									\$17,989
B3011	1578617 Roof, Cool Reflective Coating	10	1	9	1200	SF	\$1.77	\$2,125										\$2,125									\$2,	125	\$4,251
C3025	1518913 Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	882	SF	\$7.20	\$6,346										\$6,346									\$6,3	346	\$12,693
D3051	1465797 Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.20	\$6,199				;	6,199										\$6,199						\$12,398
D5022	1518915 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace	20	1	19	1	EA	\$232.47	\$232																			\$:	232	\$232
D5029	1518916 Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	882	SF	\$6.64	\$5,858																			\$5,8	858	\$5,858
Totals, Un	escalated								\$0	\$0	\$0	\$0	6,199	\$0	\$0	\$0	\$0	\$8,622	\$0 \$1	7,989	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0 \$14,	712	\$0 \$53,721
Totals, Esc	alated (3.0% inflation, compounded annually)								\$0	\$0	\$0	\$0	6,977	\$0	\$0	\$0	\$0	\$11,249	\$0 \$2	4,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0 \$25,	798	\$0 \$78,302

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Uniformat Code	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost	Subtotal 20	019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029 2030	203	1 2032	2033	2034	2035	2036	2037 203	8 203	Deficiency 39 Repair Estimate
B1015	1518918	B Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.66	\$150										\$150								\$15	j	\$299
B2011	1518919	Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1300	SF	\$13.84	\$17,989											\$17,989									\$17,989
B3011	1578618	Roof, Cool Reflective Coating	10	1	9	1200	SF	\$1.77	\$2,125										\$2,125								\$2,12	5	\$4,251
C3025	151892°	Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	882	SF	\$7.20	\$6,346										\$6,346								\$6,34	3	\$12,693
D3051	1465787	7 Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.20	\$6,199					\$6,199									\$6,199						\$12,398
D5022	1518923	B Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace	e 20	1	19	1	EA	\$232.47	\$232																		\$23	2	\$232
D5029	1518924	Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	882	SF	\$6.64	\$5,858																		\$5,85	3	\$5,858
Totals, Un	escalated									\$0	\$0	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0	\$8,622	\$0 \$17,989	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0 \$14,71	2 \$	\$0 \$53,721
Totals, Es	alated (3.	0% inflation, compounded annually)								\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0 \$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0 \$25,79	3 \$	\$0 \$78,302

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Portable P32

Uniformat Code	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	yUnit	Unit Cost *	Subtotal	2019	2020	2021	2022	2023	2024	2025	2026	2027	7 2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	Deficie 2039 Rej Estim	pair
B1015	1518926 Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.66	\$150										\$150										\$150	\$:	299
B2011	1518927 Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1300	SF	\$13.84	\$17,989												\$17,989									\$17,9	989
B3011	1578619 Roof, Cool Reflective Coating	10	1	9	1200	SF	\$1.77	\$2,125										\$2,125										\$2,125	\$4,2	251
C3025	1518929 Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	882	SF	\$7.20	\$6,346										\$6,346										\$6,346	\$12,6	693
D3051	1465783 Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.20	\$6,199					\$6,199										\$6,199						\$12,3	398
D5022	1518931 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replacement	e 20	1	19	1	EA	\$232.47	\$232																				\$232	\$:	232
D5029	1518932 Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	882	SF	\$6.64	\$5,858																				\$5,858	\$5,8	858
Totals, Un	escalated								\$0	\$0	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0	\$8,622	\$0	\$17,989	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0 \$	14,712	\$0 \$53,7	721
Totals, Es	calated (3.0% inflation, compounded annually)								\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0 \$	25,798	\$0 \$78,3	302

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Portable P33

Uniformat Code	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost Subtotal 20	19 20	20 202	1 2022	2023	2024 2	2025 20	26 2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038		eficiency Repair Estimate
B1015	1518934 Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.66 \$150								\$150										\$150		\$299
B2011	1518935 Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1300	SF	\$13.84 \$17,989									\$	17,989									8	\$17,989

Uniformat Code	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	/Unit	Unit Co	ost Subtot	tal2019	2020	2021	2022	2023	2024	2025	2026 2	2027	2028	2029 203	0 203	1 2032	2 2033	2034	2035	2036	2037 2038		Deficiency 9 Repair Estimate
B3011	1578620	Roof, Cool Reflective Coating	10	1	9	1200	SF	\$1	.77 \$2,12	25								\$	\$2,125								\$2,125		\$4,251
C3025	1518937	Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	882	SF	\$7	7.20 \$6,34	46								\$	66,346								\$6,346		\$12,693
D3051	1465785	Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199	.20 \$6,19	99				\$6,199									\$6,199						\$12,398
D5022	1518939	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace	20	1	19	1	EA	\$232	.47 \$23	32																	\$232		\$232
D5029	1518940	Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	1000	SF	\$6	5.64 \$6,64	42																	\$6,642		\$6,642
Totals, Un	escalated									\$0	\$0	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0 \$	8,622	\$0 \$17,98	9 \$(\$0	\$6,199	\$0	\$0	\$0	\$0 \$15,496	\$0	0 \$54,505
Totals, Es	calated (3.	0% inflation, compounded annually)								\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0 \$1	11,249	\$0 \$24,90	1 \$0	\$0	\$9,377	\$0	\$0	\$0	\$0 \$27,172	\$0	0 \$79,676

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Uniformat Code	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quantit	yUnit	Unit Cost *	Subtotal	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037 2038	Deficiency 2039 Repair Estimate
B1015	1518942 Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.66	\$150										\$150									\$150	\$299
B2011	1518943 Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1600	SF	\$13.84	\$22,140											\$2	2,140								\$22,140
B3011	1578621 Roof, Cool Reflective Coating	10	1	9	1850	SF	\$1.77	\$3,277										\$3,277									\$3,277	\$6,553
C3025	1518945 Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	1253	SF	\$7.20	\$9,016										\$9,016									\$9,016	\$18,032
D3051	1465805 Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.20	\$6,199					6,199									\$	6,199					\$12,398
D5022	1518947 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replacement	e 20	1	19	1	EA	\$232.47	\$232																			\$232	\$232
D5029	1518948 Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	1253	SF	\$6.64	\$8,322																			\$8,322	\$8,322
Totals, Un	escalated								\$0	\$0	\$0	\$0	6,199	\$0	\$0	\$0	\$0	\$12,442	\$0 \$2	2,140	\$0	\$0 \$	6,199	\$0	\$0	\$0	\$0 \$20,997	\$0 \$67,978
Totals, Es	calated (3.0% inflation, compounded annually)								\$0	\$0	\$0	\$0	6,977	\$0	\$0	\$0	\$0	\$16,235	\$0 \$3	0,647	\$0	\$0 \$	9,377	\$0	\$0	\$0	\$0 \$36,819	\$0 \$100,055

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Portable P35

Uniformat Code	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quantit	yUnit	Unit Cost *	Subtotal	2019	2020	2021	2022	2023	2024	2025	2026	2027	7 2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	Deficier 2039 Rep Estim	pair
B1015	1518950 Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.66	\$150										\$150										\$150	\$7	299
B2011	1518951 Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1600	SF	\$13.84	\$22,140											\$22	2,140									\$22,1	140
B3011	1578622 Roof, Cool Reflective Coating	10	1	9	1850	SF	\$1.77	\$3,277										\$3,277										\$3,277	\$6,5	553
C3025	1518953 Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	1253	SF	\$7.20	\$9,016										\$9,016										\$9,016	\$18,0	032
D3051	1465793 Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.20	\$6,199					\$6,199										\$6,199						\$12,3	398
D5022	1518955 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Repla	ace 20	1	19	1	EA	\$232.47	\$232																				\$232	\$:	232
D5029	1518956 Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	1253	SF	\$6.64	\$8,322																				\$8,322	\$8,3	322
Totals, Un	escalated								\$0	\$0	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0	\$12,442	\$0 \$22	2,140	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0	\$20,997	\$0 \$67,9	978
Totals, Es	alated (3.0% inflation, compounded annually)								\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$16,235	\$0 \$30	0,647	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$36,819	\$0 \$100,0	055

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Portable P36

Uniformat Code	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	/Unit	Unit Cost * Subto	tal2019	2020	2021 2022	2023	2024	2025 2	026 2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	Deficiency 2039 Repair Estimate
B1015	1518958 Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.66 \$1	50							\$150										\$150	\$299
B2011	1518959 Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1600	SF	\$13.84 \$22,1	40								\$	322,140									\$22,140
B3011	1578623 Roof, Cool Reflective Coating	10	1	9	1850	SF	\$1.77 \$3,2	77							\$3,277										\$3,277	\$6,553
C3025	1518961 Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	1253	SF	\$7.20 \$9,0	16							\$9,016										\$9,016	2 _{\$18,032}

Uniformat Code	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quantit	yUnit	Unit Cos *	t Subtotal	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028 2	2029 20	030 203	1 20	32 2033	2034	2035	2036	2037 2038	Deficiency 2039 Repair Estimate
D3051	1465803 Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.2	0 \$6,199					\$6,199									\$6,199					\$12,398
D5022	1518963 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Repla	ce 20	1	19	1	EA	\$232.4	7 \$232																		\$232	\$232
D5029	1518964 Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	1253	SF	\$6.6	4 \$8,322																		\$8,322	\$8,322
Totals, Un	escalated								\$0	\$0	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0 \$1	12,442	\$0 \$22,1	140 \$	0	\$0 \$6,199	\$0	\$0	\$0	\$0 \$20,997	\$0 \$67,978
Totals, Es	calated (3.0% inflation, compounded annually)								\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0 \$1	16,235	\$0 \$30,6	§47 \$	0	\$0 \$9,377	\$0	\$0	\$0	\$0 \$36,819	\$0 \$100,055

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Uniformat Code	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	yUnit	Unit Cost s	Subtotal	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037 203	Deficien 2039 Repa Estima
B1015	1518966 Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.66	\$150										\$150									\$150	\$29
B2011	1518967 Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1300	SF	\$13.84	\$17,989											\$	17,989								\$17,98
B3011	1578624 Roof, Cool Reflective Coating	10	1	9	1200	SF	\$1.77	\$2,125										\$2,125									\$2,125	\$4,25
C3025	1518969 Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	882	SF	\$7.20	\$6,346										\$6,346									\$6,346	\$12,69
D3051	1465782 Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.20	\$6,199					6,199										\$6,199					\$12,39
D5022	1518971 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replacement	e 20	1	19	1	EA	\$232.47	\$232																			\$232	\$23
D5029	1518972 Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	882	SF	\$6.64	\$5,858																			\$5,858	\$5,85
Totals, Un	scalated								\$0	\$0	\$0	\$0	6,199	\$0	\$0	\$0	\$0	\$8,622	\$0 \$	17,989	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0 \$14,712	\$0 \$53,72
Totals, Es	alated (3.0% inflation, compounded annually)								\$0	\$0	\$0	\$0	6,977	\$0	\$0	\$0	\$0	\$11,249	\$0 \$	24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0 \$25,798	\$0 \$78,30

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Portable P38

Uniformat			Lifespan					Unit Cos	•																				Deficie	ncy
Code	ID	Cost Description	(EUL)	EAge	RUL	Quantity	/Unit	*	t Subtotal2	019	2020	2021	202	2 2023	2024	2025	2026	2027	2028	2029 203	0 2031	1 2032	2033	2034	2035	2036	2037 20	38 20	039 Re Estin	
B1015	1518974	Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.6	\$150										\$150								\$1	i0	\$	299
B2011	1518975	Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1300	SF	\$13.8	\$4 \$17,989											\$17,989)								\$17,	989
B3011	1578625	Roof, Cool Reflective Coating	10	1	9	1200	SF	\$1.7	7 \$2,125										\$2,125								\$2,12	:5	\$4,	251
C3025	1518977	Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	882	SF	\$7.2	96,346										\$6,346								\$6,34	₋ 6	\$12,	ŝ93
D3051	1465792	Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.2	96,199					\$6,199									\$6,199						\$12,	398
D5022	1518979	Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replacement	e 20	1	19	1	EA	\$232.4	7 \$232																		\$23	.2	\$	232
D5029	1518980	Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	882	SF	\$6.6	\$5,858																		\$5,8	8	\$5,	358
Totals, Un	escalated									\$0	\$0	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0	\$8,622	\$0 \$17,989	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0 \$14,7°	2	\$0 \$53,	721
Totals, Esc	alated (3.0	0% inflation, compounded annually)								\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0 \$24,90°	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0 \$25,79	18	\$0 \$78,	302

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Portable P39

Uniformat Code	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quantit	yUnit	Unit Cos	Subtot	tal 2019	9 2020	2021	2022	2023 2	2024	2025 2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038		ency epair mate
B1015	1518982 Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.6	\$15	50								\$150										\$150	\$	\$299
B2011	1518983 Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1300	SF	\$13.8	34 \$17,98	39									\$	17,989									\$17,	7,989
B3011	1578626 Roof, Cool Reflective Coating	10	1	9	1200	SF	\$1.7	77 \$2,12	25								\$2,125										\$2,125	\$4,	1,251
C3025	1518985 Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	882	SF	\$7.2	20 \$6,34	16								\$6,346										\$6,346	\$12,	2,693
D3051	1465795 Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.2	20 \$6,19	99			\$6	5,199									\$6,199						\$12,	2,398
D5022	1518987 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace	e 20	1	19	1	EA	\$232.4	17 \$23	32																		\$232	0 l _{\$}	\$232

Uniformat Code	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quantit	tyUnit	Unit Cos	t Subtotal2	019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	203	7 2038	2039 R	ciency Repair timate
D5029	1518988 Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	882	SF	\$6.6	4 \$5,858																				\$5,858	\$	5,858
Totals, Un	escalated								\$0	\$0	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0	\$8,622	\$0 \$	17,989	\$0	\$0	\$6,199	\$0	\$0	\$0	\$(0 \$14,712	\$0 \$5	53,721
Totals, Es	calated (3.0% inflation, compounded annually)								\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0 \$2	24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$(0 \$25,798	\$0 \$7	78,302

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Uniformat Code	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost * Subtotal	2019	2020	2021	2022 202	3 2024	2025	2026	2027	2028	2029	2030	2031 2	032	2033	2034	2035	2036	2037	2038	2039	ficiency Repair Estimate
B1015	151899	0 Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.66 \$150									\$150										\$150		\$299
B2011	151899	1 Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1300	SF	\$13.84 \$17,989										\$1	7,989										\$17,989
B3011	157862	7 Roof, Cool Reflective Coating	10	1	9	1200	SF	\$1.77 \$2,125									\$2,125									\$	\$2,125		\$4,251
C3025	151899	Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	882	SF	\$7.20 \$6,346									\$6,346									\$	\$6,346		\$12,693
D3051	146578	8 Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.20 \$6,199				\$6,199									\$6	6,199							\$12,398
D5022	151899	5 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace	e 20	1	19	1	EA	\$232.47 \$232																			\$232		\$232
D5029	151899	6 Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	882	SF	\$6.64 \$5,858																		\$	\$5,858		\$5,858
Totals, Une	scalated								\$0	\$0	\$0	\$0 \$6,199	\$0	\$0	\$0	\$0	\$8,622	\$0 \$1	7,989	\$0	\$0 \$6	6,199	\$0	\$0	\$0	\$0 \$1	14,712	\$0	\$53,721
Totals, Esc	alated (3	.0% inflation, compounded annually)							\$0	\$0	\$0	\$0 \$6,97	\$0	\$0	\$0	\$0	\$11,249	\$0 \$2	4,901	\$0	\$0 \$9	9,377	\$0	\$0	\$0	\$0 \$2	25,798	\$0	\$78,302

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Portable P41

Uniformat Code	ID Cost Description	Lifespan (EUL)	EAge	RUL	Quantit	yUnit	Unit Cost *	Subtotal	2019	2020	2021	2022	2023	2024	2025	2026	2027	7 2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	Deficiency 2039 Repair Estimate
B1015	1518998 Exterior Stair/Ramp Rails, Wood, Refinish	10	1	9	90	LF	\$1.66	\$150										\$150										\$150	\$299
B2011	1518999 Exterior Wall, Textured Plywood (T1-11), Replace	20	9	11	1300	SF	\$13.84	\$17,989												\$17,989									\$17,989
B3011	1578628 Roof, Cool Reflective Coating	10	1	9	1200	SF	\$1.77	\$2,125										\$2,125										\$2,125	\$4,251
C3025	1519001 Interior Floor Finish, Carpet Commercial Tile, Replace	10	1	9	882	SF	\$7.20	\$6,346										\$6,346										\$6,346	\$12,693
D3051	1465773 Air Conditioner, 2.5 - 5 TON, Replace	10	6	4	1	EA	\$6,199.20	\$6,199					\$6,199										\$6,199						\$12,398
D5022	1519003 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replacement	ce 20	1	19	1	EA	\$232.47	\$232																				\$232	\$232
D5029	1519004 Lighting System, Interior, Low Density & Standard Fixtures, Replace	20	1	19	882	SF	\$6.64	\$5,858																				\$5,858	\$5,858
Totals, Un	escalated								\$0	\$0	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0	\$8,622	\$0	\$17,989	\$0	\$0	\$6,199	\$0	\$0	\$0	\$0	\$14,712	\$0 \$53,721
Totals, Es	alated (3.0% inflation, compounded annually)								\$0	\$0	\$0	\$0	\$6,977	\$0	\$0	\$0	\$0	\$11,249	\$0	\$24,901	\$0	\$0	\$9,377	\$0	\$0	\$0	\$0	\$25,798	\$0 \$78,302

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Ina Arbuckle Elementary School / Portable Restrooms

Uniformat Code	ID COST DESCRIPTION	Lifespan (EUL)	EAge	RUL	Quantity	yUnit	Unit Cost Subtotal 2	019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	Deficiency Repair Estimate
B2011	1465794 Exterior Wall, Stucco, 1-2 Stories, Prep & Fog Coat or Paint	10	1	9	50	SF	\$3.54 \$177										\$177										\$177		\$354
B3011	1578629 Roof, Cool Reflective Coating	10	1	9	1200	SF	\$1.77 \$2,125										\$2,125										\$2,125		\$4,251
C1031	1465791 Toilet Partitions, Plastic/Laminate, Replace	20	1	19	6	EA	\$830.25 \$4,982																				\$4,982		\$4,982
D2018	1465771 Drinking Fountain, Outside/Site Style, Replace	15	1	14	2	EA	\$3,985.20 \$7,970														\$7	970							\$7,970
Totals, Une	scalated							\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$2,303	\$0	\$0	\$0	\$0 \$7	970	\$0	\$0	\$0	\$0	\$7,284	\$0	\$17,557
Totals, Esca	alated (3.0% inflation, compounded annually)							\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$3,004	\$0	\$0	\$0	\$0 \$12	056	\$0	\$0	\$0	\$0 \$	12,773	\$0	\$27,833

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Help

Ina Arbuckle Elementary School / Site

Uniformat Code	Cost Description	Lifespan (EUL)	Age	RUL	Quantit	yUnit	Unit Cost *	Subtotal	2019	2020	2021	2022 2023	2024	2025 20)26 2	2027 2028	2029	2030	2031 2	032 2	.033 2	2034 203	5 2036	2037	2038	Deficiency 2039 Repai Estimate
B3016 14656	85 Gutters & Downspouts, Aluminum w/ Fittings, Replace	20	1	19	200	LF	\$9.96	\$1,99	3																\$1,993	\$1,993
D2018 14656	87 Drinking Fountain, Outside/Site Style, Replace	15	9	6	3	EA	\$3,985.20	\$11,95	6				\$	11,956												\$11,956
D5022 14656	76 Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replac	e 20	1	19	10	EA	\$232.47	\$2,32	5																\$2,325	\$2,325
D5037 14656	92 Fire Alarm Control Panel, Addressable, Replace	15	1	14	1	EA	\$16,605.00	\$16,60	5											\$16,	305					\$16,605
G2022 14656	80 Parking Lots, Asphalt Pavement, Cut & Patch	0	14	* 0	10000	SF	\$3.87	\$38,74	5	\$38	3,745															\$38,745
G2022 14656	73 Parking Lots, Asphalt Pavement, Seal & Stripe	5	1	4	30000	SF	\$0.50	\$14,94	5			\$14,945				\$14,945				\$14,	945				\$14,945	\$59,778
G2047 14656	77 Play Structure, Large, Replace	20	20	0	1	EA	\$38,745.00	\$38,74	5 \$38,745																	\$38,745 \$77,490
G2047 14656	70 Play Surfaces & Sports Courts, Asphalt, Mill & Overlay	25	9	16	30000	SF	\$3.87	\$116,23	5													\$116,235	,			\$116,235
G2047 14656	66 Play Surfaces & Sports Courts, Sand, 3" Depth, Replace	20	1	19	2700	SF	\$0.88	\$2,38	8																\$2,388	\$2,388
G2047 14656	74 Play Surfaces & Sports Courts, Poured-in-place Rubber, Replace	20	1	19	100	SF	\$23.25	\$2,32	5																\$2,325	\$2,325
G2047 14656	88 Play Structure, Small, Replace	20	1	19	1	EA	\$11,070.00	\$11,07	0																\$11,070	\$11,070
G2047 14656	69 Play Structure, Very Small, Replace	20	1	19	3	EA	\$6,642.00	\$19,92	6																\$19,926	\$19,926
G2047 14656	81 Play Structure, Swing Set only, 4 Seats, Replace	20	1	19	2	EA	\$2,767.50	\$5,53	5																\$5,535	\$5,535
G2047 14656	Play Surfaces, Artificial Turf, 1/2" Pile, 5/16" Pad, Replace	20	1	19	400	SF	\$12.18	\$4,87	1																\$4,871	\$4,871
Totals, Unescala	ted								\$38,745	\$0 \$38	8,745	\$0 \$14,945	\$0 \$ ⁴	11,956	\$0	\$0 \$14,945	\$0	\$0	\$0	\$0 \$31,	550	\$0 \$116,235	5 \$0	\$0	\$65,376	\$38,745 \$371,241
Totals, Escalate	d (3.0% inflation, compounded annually)								\$38,745	\$0 \$41	1,105	\$0 \$16,820	\$0 \$ ²	14,276	\$0	\$0 \$19,499	\$0	\$0	\$0	\$0 \$47,	721	\$0 \$186,523	3 \$0	\$0 \$	\$114,638	\$69,978 \$549,305

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Appendix F: Equipment Inventory List

11/29/2019



ID	Location	Location Detail	Description	Manufacturer	Model	Details Ba	rcode Asset	ag Quant	ity L	Init	Year Installed/In Service	Replacement Year	Total Cost
1519554	Ina Arbuckle Elementary School / Building C	Restrooms	D2012 - Urinal, Standard, Replace; Lifespan:30						1	EA	2018	2048	\$1,10
1519517	Ina Arbuckle Elementary School / Building D	Restrooms	D2012 - Urinal, Standard, Replace; Lifespan:30						4	EA	2018	2048	\$4,40
1578599	Ina Arbuckle Elementary School / Building E	Restrooms	D2012 - Urinal, Standard, Replace; Lifespan:30						4	EA	2018	2048	\$4,40
1519448	Ina Arbuckle Elementary School / Building F	Restrooms	D2012 - Urinal, Standard, Replace; Lifespan:30						4	EA	2018	2048	\$4,40
1465796	Ina Arbuckle Elementary School / Portable Restrooms	Restrooms	D2012 - Urinal, Standard, Replace; Lifespan:30						2	EA	2018	2048	\$2,20
1465427	Ina Arbuckle Elementary School / Building A-B	Kitchen	D2014 - Trough Style Sink, Solid Surface, Vandalism Resistant, Replace; Lifespan:30	0	0	0	0		2	EA	2018	2048	\$5,12
1519550	Ina Arbuckle Elementary School / Building C	Restrooms	D2014 - Sink/Lavatory, Wall-Hung, Vitreous China, Replace; Lifespan:30						3	EA	2018	2048	\$4,50
1519548	Ina Arbuckle Elementary School / Building C	Classrooms	D2014 - Sink/Lavatory, Vanity Top, Stainless Steel, Replace; Lifespan:30						4	EA	2018	2048	\$4,80
1519531	Ina Arbuckle Elementary School / Building D	Restrooms	D2014 - Sink/Lavatory, Wall-Hung, Vitreous China, Replace; Lifespan:30						4	EA	2018	2048	\$6,00
1519524		Utility closet	D2014 - Service Sink, Wall-Hung, Replace; Lifespan:35						1	EA	2018	2053	\$1,40
	2 Ina Arbuckle Elementary School / Building D	Classrooms	D2014 - Sink/Lavatory, Vanity Top, Stainless Steel, Replace; Lifespan:30						4	EA	2018	2048	\$4,80
	Ina Arbuckle Elementary School / Building E	Utility closet	D2014 - Service Sink, Wall-Hung, Replace; Lifespan:35						1	EA	2018	2053	\$1,40
1578601		Restrooms	D2014 - Sink/Lavatory, Wall-Hung, Vitreous China, Replace; Lifespan:30							EA	2018	2048	\$6,00
1578602		Classrooms	D2014 - Sink/Lavatory, Vanity Top, Stainless Steel, Replace; Lifespan:30						4	EA	2018	2048	\$4,80
	Ina Arbuckle Elementary School / Building F								4	EA	2018		
	, ,	Utility closet	D2014 - Service Sink, Wall-Hung, Replace; Lifespan:35						1			2053	\$1,40
	Ina Arbuckle Elementary School / Building F	Restrooms	D2014 - Sink/Lavatory, Wall-Hung, Vitreous China, Replace; Lifespan:30						6	EA	2018	2048	\$9,00
	Ina Arbuckle Elementary School / Building H		D2014 - Sink/Lavatory, Wall-Hung, Vitreous China, Replace; Lifespan:30						3	EA	2018	2048	\$4,50
1547698		Building Interior	D2014 - Sink/Lavatory, Vanity Top, Stainless Steel, Replace; Lifespan:30						1	EA	2018	2048	\$1,20
1465801	·	Restrooms	D2014 - Sink/Lavatory, Wall-Hung, Vitreous China, Replace; Lifespan:30						6	EA	2018	2048	\$9,00
1465656	Ina Arbuckle Elementary School / Building A-B	Building Interior	D2018 - Drinking Fountain, Interior, Replace; Lifespan:15						2	EA	2018	2033	\$3,80
1519553	B Ina Arbuckle Elementary School / Building C	Building exterior	D2018 - Drinking Fountain, Outside/Site Style, Replace; Lifespan:15						2	EA	2018	2033	\$7,20
1519532	Ina Arbuckle Elementary School / Building D	Building exterior	D2018 - Drinking Fountain, Outside/Site Style, Replace; Lifespan:15						2	EA	2018	2033	\$7,20
1578603	Ina Arbuckle Elementary School / Building E	Building exterior	D2018 - Drinking Fountain, Outside/Site Style, Replace; Lifespan:15						2	EA	2018	2033	\$7,20
1519429	Ina Arbuckle Elementary School / Building G	Building exterior	D2018 - Drinking Fountain, Outside/Site Style, Replace; Lifespan:15	0	0	0			2	EA	2018	2033	\$7,20
1547704	Ina Arbuckle Elementary School / Building H	Building Interior	D2018 - Drinking Fountain, Interior, Replace; Lifespan:15						2	EA	2018	2033	\$3,80
1465771	Ina Arbuckle Elementary School / Portable Restrooms	Building exterior	D2018 - Drinking Fountain, Outside/Site Style, Replace; Lifespan:15						2	EA	2018	2033	\$7,20
1465687	Ina Arbuckle Elementary School / Site	Site	D2018 - Drinking Fountain, Outside/Site Style, Replace; Lifespan:15						3	EA	1980	2025	\$10,80
1465424	Ina Arbuckle Elementary School / Building A-B	Kitchen	D3051 - Air Conditioner, 1 TON, Replace; Lifespan:10						1	EA	2018	2028	\$2,20
1465429	Ina Arbuckle Elementary School / Building A-B	Kitchen	D3051 - Air Conditioner, 1 TON, Replace; Lifespan:10	Mars	60CH	887PE60CH-SL			1	EA	2018	2028	\$2,20
1465799	Ina Arbuckle Elementary School / Portable P21	P21	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10	Bard	W42H1-A04UP4	332F122903255-02			1	EA	2000	2023	\$5,60
1465804	Ina Arbuckle Elementary School / Portable P22	P22	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10	Bard	W42H1-A04UP4	332D122901115-02			1	EA	2000	2023	\$5,60
1465772	2 Ina Arbuckle Elementary School / Portable P23	P23	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10	Bard	W48H1-A04UP4	321K092645174-02			1	EA	2000	2023	\$5,60
1465777	/ Ina Arbuckle Elementary School / Portable P24	P24	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10	Bard	W42H1-A04UP4	332D122901101-02			1	EA	2000	2023	\$5,60
1465784	Ina Arbuckle Elementary School / Portable P25	P25	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10	Bard	WH483-A0ZUP4	236B052004567-02			1	EA	2000	2023	\$5,60
	Ina Arbuckle Elementary School / Portable P26	P26	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10						1	EA	2000	2023	\$5,60
	Ina Arbuckle Elementary School / Portable P27	P27	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10						1	EA	2000	2023	\$5,60
	Ina Arbuckle Elementary School / Portable P28	P28	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10						1	EA	2000	2023	\$5,60
	Ina Arbuckle Elementary School / Portable P29	P29	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10			238DO 2			1	EA	2000	2023	\$5,60
	Ina Arbuckle Elementary School / Portable P29 Ina Arbuckle Elementary School / Portable P30	P30	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan: 10	Eubank	HW42C600B1F01A	98A-P10031			1	EA	2000	2023	\$5,60
	· · · · · · · · · · · · · · · · · · ·			Lubalik	THY AZOUUD IFU IA	55A-1 10051			1		2000	2023	\$5,60
	Ina Arbuckle Elementary School / Portable P31	P31	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10	Eubani	LIMA2CEOOR4FO44	09A B40027			1	EA			
	Ina Arbuckle Elementary School / Portable P32	P32	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10	Eubank	HW42C600B1F01A	98A-P10027			1	EA	2000	2023	\$5,60
	Ina Arbuckle Elementary School / Portable P33	P33	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10						1	EA	2000	2023	\$5,60
	Ina Arbuckle Elementary School / Portable P34	P34	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10	Bard	WH483-A0ZUP4	236H072360887-02			1	EA	2000	2023	\$5,60
	Ina Arbuckle Elementary School / Portable P35	P35	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10	Bard	W48H2-A04Up4	343P143189656-02			1	EA	2000	2023	\$5,60
	Ina Arbuckle Elementary School / Portable P36	P36	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10	Bard	W48H2-A04Up4	343P143189660-02			1	EA	2000	2023	\$5,60
1465782	Ina Arbuckle Elementary School / Portable P37	P37	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10	Crispaire	AVP48HPA10NB	DJ8701			1	EA	2000	2023	\$5,60
1465792	Ina Arbuckle Elementary School / Portable P38	P38	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10	Bard	W42Ha-A04CP4	362P183617431-02			1	EA	2000	2023	\$5,60
1465795	Ina Arbuckle Elementary School / Portable P39	P39	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10						1	EA	2000	2023	\$5,60
1465788	Ina Arbuckle Elementary School / Portable P40	P40	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10						1	EA	2000	2023	\$5,60
1465773	Ina Arbuckle Elementary School / Portable P41	P41	D3051 - Air Conditioner, 2.5 - 5 TON, Replace; Lifespan:10						1	EA	2000	2023	\$5,60
1547649	Ina Arbuckle Elementary School / Building A-B	Roof - B	D3052 - Packaged Unit (RTU), 4 TON, Replace; Lifespan:20	Carrier	48LC005A2M6A0A3D0	2018C86941	AC-2.1		1	EA	2018	2038	\$9,00
1550562	Ina Arbuckle Elementary School / Building A-B	Roof B	D3052 - Packaged Unit (RTU), 2 TON, Replace; Lifespan:20	Carrier	FX4DNF025	1617A68273	SAC-2.2		1	EA	2018	2038	\$5,5
1547645	Ina Arbuckle Elementary School / Building A-B	Roof - B	D3052 - Packaged Unit (RTU), 3 TON, Replace; Lifespan:20	Carrier	48LC004A2M6A0A3D0	2018C86961	AC-1.2		1	EA	2018	2038	\$7,50
1550558	Ina Arbuckle Elementary School / Building A-B	Roof B	D3052 - Packaged Unit (RTU), 2 TON, Replace; Lifespan:20	Carrier	FX4DNF026	4417A68063	SAC-2.1		1	EA	2018	2038	\$5,50
	Ina Arbuckle Elementary School / Building A-B	Roof - B	D3052 - Packaged Unit (RTU), 5 TON, Replace; Lifespan:20	Carrier	48LC006A2M6A0A3D0	2018C86941	AC-1.1			EA	2018	2038	\$11,00

1547647	Ina Arbuckle Elementary School / Building A-B	Roof - B	D3052 - Packaged Unit (RTU), 3 TON, Replace; Lifespan:20	Carrier	48LC004A2M6A0A3D0	2018C86963	AC-1.3	1 EA	2018	2038	\$7,50
1550565	Ina Arbuckle Elementary School / Building C	Roof C	D3052 - Packaged Unit (RTU), 5 TON, Replace; Lifespan:20	Trane	VSC060A4ELA2V	732102351L	X-702	1 EA	2018	2038	\$11,00
1550564	Ina Arbuckle Elementary School / Building C	Roof C	D3052 - Packaged Unit (RTU), 3.5 TON, Replace; Lifespan:20	Trane	4YCZ6048A4096CA	11265G949H	X-605	1 EA	2018	2038	\$8,20
1550566	Ina Arbuckle Elementary School / Building C	Roof C	D3052 - Packaged Unit (RTU), 5 TON, Replace; Lifespan:20	Trane	VSC060A4ELA2V	732102331	X-701	1 EA	2018	2038	\$11,00
1519560	Ina Arbuckle Elementary School / Building C	Roof	D3052 - Packaged Unit (RTU), 3 TON, Replace; Lifespan:20					3 EA	2010	2030	\$22,50
1550561	Ina Arbuckle Elementary School / Building D	Roof D	D3052 - Packaged Unit (RTU), 5 TON, Replace; Lifespan:20	Trane	YSC060A4RLA2U	72210217L	X-703	1 EA	2018	2038	\$11,00
1550573	Ina Arbuckle Elementary School / Building D	Roof D	D3052 - Packaged Unit (RTU), 5 TON, Replace; Lifespan:20	Trane	2YCC3024A1040AA	6382M229H	X-704	1 EA	2018	2038	\$11,00
1519526	Ina Arbuckle Elementary School / Building D	Building exterior	D3052 - Packaged Unit (RTU), 3 TON, Replace; Lifespan:20					3 EA	2015	2035	\$22,50
	Ina Arbuckle Elementary School / Building E	Roof E	D3052 - Packaged Unit (RTU), 5 TON, Replace; Lifespan:20	Trane	YHC063A4ELA0000	825100253L	X-604	1 EA	2018	2038	\$11,00
	Ina Arbuckle Elementary School / Building E	Roof E		Trane	4YCZ6048A4096CA	11281H44A9H	X-504	1 EA	2018	2038	\$8,2
	Ina Arbuckle Elementary School / Building E	Roof E		Trane	4YCZ6048A4096CA	11281H5A9H	X-503	1 EA	2018	2038	\$8,20
	Ina Arbuckle Elementary School / Building E	Roof E		Trane	4YCZ6048A4096CA	11193LL19H	X-603	1 EA	2018	2038	\$8,2
	Ina Arbuckle Elementary School / Building F	Roof F	D3052 - Packaged Unit (RTU), 3.5 TON, Replace; Lifespan:20	Trane	4YCZ6048A4096BA	13251406L	X-502	1 EA	2018	2038	\$8,2
	Ina Arbuckle Elementary School / Building F	Roof F	D3052 - Packaged Unit (RTU), 3.5 TON, Replace; Lifespan:20	Trane	4YCZ6048A4096CA	11281H5J9H	X-501	1 EA	2018	2038	\$8,2
1519439	Ina Arbuckle Elementary School / Building F	Roof	D3052 - Packaged Unit (RTU), 3 TON, Replace; Lifespan:20					3 EA	2015	2035	\$22,5
1550559	Ina Arbuckle Elementary School / Building F	Roof F	D3052 - Packaged Unit (RTU), 5 TON, Replace; Lifespan:20	Trane	YSC060G4	173710587L	X-403	1 EA	2018	2038	\$11,0
1519426	Ina Arbuckle Elementary School / Building G	Roof	D3052 - Packaged Unit (RTU), 3 TON, Replace; Lifespan:20					3 EA	2015	2035	\$22,5
1547650	Ina Arbuckle Elementary School / Building G	Roof - G	D3052 - Packaged Unit (RTU), 5 TON, Replace; Lifespan:20	Carrier	48LC006	3917C87745	AC-3.2	1 EA	2018	2038	\$11,0
1547648	Ina Arbuckle Elementary School / Building G	Roof - G	D3052 - Packaged Unit (RTU), 5 TON, Replace; Lifespan:20	Carrier	48LC006	3917C87746	AC-3.1	1 EA	2018	2038	\$11,0
1550570	Ina Arbuckle Elementary School / Building G	Roof G	D3052 - Packaged Unit (RTU), 5 TON, Replace; Lifespan:20	Trane	YSC060G	173710576L	X-301	1 EA	2018	2038	\$11,0
1550569	Ina Arbuckle Elementary School / Building G	Roof G	D3052 - Packaged Unit (RTU), 5 TON, Replace; Lifespan:20	Trane	YSC060G	173710576L	X-401	1 EA	2018	2038	\$11,0
	Ina Arbuckle Elementary School / Building G	Roof G		Trane	YSC060G4	173710542L	X-402	1 EA	2018	2038	\$11,0
	Ina Arbuckle Elementary School / Building H	Roof - H		Carrier	48LC005A2M6A0A3D0	3917C86940	AC-2.2	1 EA	2018	2038	\$9,0
	Ina Arbuckle Elementary School / Building H	Roof - H		Carrier	48LC006A2M6A0A3D0	3917C86953	AC-2.4	1 EA	2018	2038	\$11,0
	Ina Arbuckle Elementary School / Building H	Roof - H		Carrier	48LC006A2M6A0A3D0	3917C86951	AC-2.5	1 EA	2018	2038	\$11,0
	Ina Arbuckle Elementary School / Building H	Roof - H		Carrier	48LC006A2M6A0A3D0	3917C86952	AC-2.3	1 EA	2018	2038	\$11,0
	Ina Arbuckle Elementary School / Building A-B	Electrical room	D5012 - Secondary Transformer, 112.5 kVA, Replace; Lifespan:30					1 EA	2018	2048	\$16,0
1465648	Ina Arbuckle Elementary School / Building A-B	Electrical room	D5012 - Main Distribution Panel, 400 AMP, Replace; Lifespan:30					1 EA	2018	2048	\$5,3
1519552	Ina Arbuckle Elementary School / Building C	Electrical room	D5012 - Main Distribution Panel, 200 AMP, Replace; Lifespan:30					1 EA	2018	2048	\$3,0
1519536	Ina Arbuckle Elementary School / Building D	Electrical room	D5012 - Main Distribution Panel, 200 AMP, Replace; Lifespan:30					1 EA	2018	2048	\$3,0
1578604	Ina Arbuckle Elementary School / Building E	Electrical room	D5012 - Main Distribution Panel, 200 AMP, Replace; Lifespan:30					1 EA	2018	2048	\$3,0
1519451	Ina Arbuckle Elementary School / Building F	Electrical room	D5012 - Main Distribution Panel, 150, Replace; Lifespan:30	Westinghouse	PRL2 CKT.42			1 EA	2018	2048	\$3,0
1519421	Ina Arbuckle Elementary School / Building G	Electrical room	D5012 - Main Distribution Panel, 150 AMP, Replace; Lifespan:30	Westinghouse	PRL2 CKT.42			1 EA	2018	2048	\$3,0
1465679	Ina Arbuckle Elementary School / Site		D5012 - Secondary Transformer, 300 kVA, Replace; Lifespan:30	НО	10104688	2759503016		1 EA	2016	2046	\$30,0
1465686	Ina Arbuckle Elementary School / Site		D5012 - Main Distribution Panel, 800 AMP, Replace; Lifespan:30	Eaton	PRL-C	SLA0788326		1 EA	2018	2048	\$10,0
1465684	Ina Arbuckle Elementary School / Site		D5012 - Building/Main Switchboard, 800 AMP, Replace; Lifespan:40	Eaton	PRL-C	SLA0788326		1 EA	2017	2057	\$45,0
1465663	Ina Arbuckle Elementary School / Building A-B	Building exterior	D5022 - Light Fixture, 50 WATT, Replace; Lifespan:20					5 EA	2018	2038	\$9
1519556	Ina Arbuckle Elementary School / Building C	Building exterior	D5022 - Light Fixture, 50 WATT, Replace; Lifespan:20					8 EA	2018	2038	\$1,5
	Ina Arbuckle Elementary School / Building D	Building exterior	D5022 - Light Fixture, 50 WATT, Replace; Lifespan:20					8 EA	2018	2038	\$1,5
	Ina Arbuckle Elementary School / Building E	Building exterior	D5022 - Light Fixture, 50 WATT, Replace; Lifespan:20					8 EA	2018	2038	\$1,5
	Ina Arbuckle Elementary School / Building E	Building exterior	D5022 - Light Fixture, 50 WATT, Replace; Lifespan.20					8 EA	2018	2038	\$1,5
	Ina Arbuckle Elementary School / Building G	Building exterior	D5022 - Light Fixture, 50 WATT, Replace; Lifespan:20					9 EA	2018	2038	\$1,7
	Ina Arbuckle Elementary School / Portable P21	Building exterior	D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1 EA	2018	2038	\$2
	Ina Arbuckle Elementary School / Portable P22	Building exterior	D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1 EA	2018	2038	\$2
1518859	Ina Arbuckle Elementary School / Portable P23	Building exterior	D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1 EA	2018	2038	\$2
1518867	Ina Arbuckle Elementary School / Portable P24	Building exterior	D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1 EA	2018	2038	\$2
1518875	Ina Arbuckle Elementary School / Portable P25	Building exterior	D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1 EA	2018	2038	\$2
1518883	Ina Arbuckle Elementary School / Portable P26	Building exterior	D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1 EA	2018	2038	\$2
1518891	Ina Arbuckle Elementary School / Portable P27	Building exterior	D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1 EA	2018	2038	\$2
1518899	Ina Arbuckle Elementary School / Portable P28	Building exterior	D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1 EA	2018	2038	\$2
1518907	Ina Arbuckle Elementary School / Portable P29	Building exterior	D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1 EA	2018	2038	\$2
	Ina Arbuckle Elementary School / Portable P30	Building exterior	D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1 EA	2018	2038	\$2
	Ina Arbuckle Elementary School / Portable P31	Building exterior	D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1 EA	2018	2038	\$2
	Ina Arbuckle Elementary School / Portable P32	Building exterior	D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1 EA	2018	2038	\$2
	Ina Arbuckle Elementary School / Portable P33	Building exterior	D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1 EA	2018	2038	\$2
	Ina Arbuckle Elementary School / Portable P34	Building exterior	D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1 EA	2018	2038	\$2
		Building exterior	D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1 EA	2018	2038	\$2
1518955	Ina Arbuckle Elementary School / Portable P35										
1518955	Ina Arbuckie Elementary School / Portable P36	Building exterior	D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1 EA	2018	2038	\$2
1518955 1518963			D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20 D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1 EA 1 EA	2018	2038	\$2

	Ina Arbuckle Elementary School / Portable P39	Building exterior	D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1	EA	2018 2038	\$210
1518995	Ina Arbuckle Elementary School / Portable P40	Building exterior	D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1	EA	2018 2038	\$210
1519003	Ina Arbuckle Elementary School / Portable P41	Building exterior	D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					1	EA	2018 2038	\$210
1465676	Ina Arbuckle Elementary School / Site		D5022 - Light Fixture, Exterior Flood (any type w/ LED Replacement), 100 W, Replace; Lifespan:20					10	EA	2018 2038	\$2,100
1465414	Ina Arbuckle Elementary School / Building A-B	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20	0	0	0	0	8504	SF	2018 2038	\$51,024
1519555	Ina Arbuckle Elementary School / Building C	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					4180	SF	2018 2038	\$25,080
1519520	Ina Arbuckle Elementary School / Building D	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					3790	SF	2018 2038	\$22,740
1578606	Ina Arbuckle Elementary School / Building E	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					3790	SF	2018 2038	\$22,740
1519441	Ina Arbuckle Elementary School / Building F	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					3790	SF	2018 2038	\$22,740
1519420	Ina Arbuckle Elementary School / Building G	Classrooms	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					3790	SF	2018 2038	\$22,740
1518844	Ina Arbuckle Elementary School / Portable P21	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					882	SF	2018 2038	\$5,292
1518852	Ina Arbuckle Elementary School / Portable P22	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					882	SF	2018 2038	\$5,292
1518860	Ina Arbuckie Elementary School / Portable P23	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					882	SF	2018 2038	\$5,292
1518868	Ina Arbuckie Elementary School / Portable P24	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					882	SF	2018 2038	\$5,292
1518876	Ina Arbuckle Elementary School / Portable P25	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					882	SF	2018 2038	\$5,292
1518884	Ina Arbuckle Elementary School / Portable P26	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					882	SF	2018 2038	\$5,292
1518892	Ina Arbuckle Elementary School / Portable P27	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					882	SF	2018 2038	\$5,292
1518900	Ina Arbuckle Elementary School / Portable P28	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					882	SF	2018 2038	\$5,292
1518908	Ina Arbuckle Elementary School / Portable P29	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					882	SF	2018 2038	\$5,292
1518916	Ina Arbuckle Elementary School / Portable P30	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					882	SF	2018 2038	\$5,292
1518924	Ina Arbuckle Elementary School / Portable P31	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					882	SF	2018 2038	\$5,292
1518932	Ina Arbuckle Elementary School / Portable P32	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					882	SF	2018 2038	\$5,292
1518940	Ina Arbuckle Elementary School / Portable P33	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					1000	SF	2018 2038	\$6,000
1518948	Ina Arbuckle Elementary School / Portable P34	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					1253	SF	2018 2038	\$7,518
1518956	Ina Arbuckle Elementary School / Portable P35	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					1253	SF	2018 2038	\$7,518
1518964	Ina Arbuckle Elementary School / Portable P36	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					1253	SF	2018 2038	\$7,518
1518972	Ina Arbuckle Elementary School / Portable P37	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					882	SF	2018 2038	\$5,292
1518980	Ina Arbuckle Elementary School / Portable P38	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					882	SF	2018 2038	\$5,292
1518988	Ina Arbuckle Elementary School / Portable P39	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					882	SF	2018 2038	\$5,292
1518996	Ina Arbuckle Elementary School / Portable P40	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					882	SF	2018 2038	\$5,292
1519004	Ina Arbuckle Elementary School / Portable P41	Throughout building	D5029 - Lighting System, Interior, Low Density & Standard Fixtures, Replace; Lifespan:20					882	SF	2018 2038	\$5,292
1465417	Ina Arbuckle Elementary School / Building A-B	Kitchen	D5037 - Fire Alarm System, Basic/Zoned, Upgrade/Install; Lifespan:20	0	0	0	0	8504	SF	2018 2038	\$17,008
1519541	Ina Arbuckle Elementary School / Building C	Throughout building	D5037 - Fire Alarm System, Basic/Zoned, Upgrade/Install; Lifespan:20					4180	SF	2018 2038	\$8,360
1519527	Ina Arbuckle Elementary School / Building D	Throughout building	D5037 - Fire Alarm System, Basic/Zoned, Upgrade/Install; Lifespan:20					3790	SF	2018 2038	\$7,580
1578607	Ina Arbuckle Elementary School / Building E	Throughout building	D5037 - Fire Alarm System, Basic/Zoned, Upgrade/Install; Lifespan:20					3790	SF	2018 2038	\$7,580
1519446	Ina Arbuckle Elementary School / Building F	Classrooms	D5037 - Fire Alarm System, Basic/Zoned, Upgrade/Install; Lifespan:20					3790	SF	2018 2038	\$7,580
1519423	Ina Arbuckle Elementary School / Building G	Classrooms	D5037 - Fire Alarm Control Panel, Basic/Zoned, Replace; Lifespan:15					1	EA	2018 2033	\$4,000
1519427	Ina Arbuckle Elementary School / Building G	Classrooms	D5037 - Fire Alarm System, Basic/Zoned, Upgrade/Install; Lifespan:20					3790	SF	2018 2038	\$7,580
1547709	Ina Arbuckle Elementary School / Building H	Building Interior	D5037 - Fire Alarm System, Basic/Zoned, Upgrade/Install; Lifespan:20					9000	SF	2018 2038	\$18,000
1465692	Ina Arbuckle Elementary School / Site		D5037 - Fire Alarm Control Panel, Addressable, Replace; Lifespan:15	Honeywell	5820XL			1	EA	2018 2033	\$15,000
1465645	Ina Arbuckle Elementary School / Building A-B	Building Interior	D5092 - Exit Sign Light Fixture, LED, Replace; Lifespan:10					7	EA	2018 2028	\$1,540
1547694	Ina Arbuckle Elementary School / Building H	Throughout building	D5092 - Exit Sign Light Fixture, LED, Replace; Lifespan:10					2	EA	2018 2028	\$440
1465428	Ina Arbuckle Elementary School / Building A-B	Kitchen	E1093 - Commercial Kitchen, Range/Oven, 4-Burner, Replace; Lifespan:15	0	0	0	0	1	EA	2010 2025	\$4,500
1465421	Ina Arbuckle Elementary School / Building A-B	Kitchen	E1093 - Commercial Kitchen, Convection Oven, Double, Replace; Lifespan:10	0	0	0	0	1	EA	2018 2028	\$9,500
1465418	Ina Arbuckle Elementary School / Building A-B	Kitchen	E1093 - Commercial Kitchen, Food Warmer, Replace; Lifespan:15	0	0	0	0	1	EA	2010 2025	\$1,700
1465419	Ina Arbuckle Elementary School / Building A-B	Kitchen	E1093 - Commercial Kitchen, Refrigerator, 2-Door Reach-In, Replace; Lifespan:15	0	0	0	0	1	EA	2010 2025	\$4,600
1465413	Ina Arbuckle Elementary School / Building A-B	Kitchen	E1093 - Commercial Kitchen, Dairy Cooler/Wells, Replace; Lifespan:15	0	0	0	0	1	EA	2010 2025	\$3,600
Total		1		ı		1					\$1,145,720