

FACILITY CONDITION ASSESSMENT

HMC ARCHITECTS 3546 Concours Street Ontario, California 91764 **Andrew Thompson**



INDIAN HILLS ELEMENTARY SCHOOL 7750 Linares Avenue Jurupa Valley, California 92509

PREPARED BY:

EMG | A Bureau Veritas Company 10461 Mill Run Circle, Suite 1100 Owings Mills, Maryland 21117 800.733.0660 www.emgcorp.com

EMG CONTACT:

Mark Surdam Program Manager 800.733.0660 x6251 msurdam@emgcorp.com

EMG PROJECT #:

139069.19R000-007.354

DATE OF REPORT:

October 22, 2019

ON SITE DATE:

September 19, 2019





TABLE OF CONTENTS

1.	Executive Summary	
	Campus Overview and Assessment Details	[,]
	Buildings	٠
	Plan Types	
	Campus Findings and Deficiencies	
	Facility Condition Index (FCI)	
	Immediate Needs	
	Key Findings	
	<i>l</i> lain Building	
3. F	Portable Buildings 18	. 1:
	Portable Buildings 19	
5. F	Portable Buildings 20	. 17
6. F	Portable Buildings 21	. 19
	Portable Buildings 22	
	Portable Buildings 23	
9. F	Portable Buildings 24	. 2
	Portable Buildings 26	
	Portable Buildings 27	
	Portable Buildings 28	
	Portable Buildings 29	
	Portable Buildings 30	
	Portable Buildings 31	
16.	Portable Buildings 32	39
17.	Portable Buildings 33	4
18.	Portable Buildings 34	4:
	Site Restrooms	
	Site Summary	
	ADA Accessibility	
	Purpose and Scope	
	Opinions of Probable Costs	
_0.	Methodology	
	Definitions	
24	Certification	
	Appendices	
~ J.	Appointed	· U

1. Executive Summary

Campus Overview and Assessment Details

General Information	
Main Address	Indian Hills Elementary School 7750 Linares Avenue Jurupa Valley, California 92509
Site Developed	1987
Property Type	Elementary School
Current Occupants	100%
Building Area	44,594 SF
Number of Buildings	18
Date(s) of Visit	9/19/2019
Management Point of Contact	Jurupa Unified School District Robin Griffin, Director, Planning & Development T 951.361.6571 robin_griffin@jusd.k12.ca.us
On-site Point of Contact (POC)	NA
Assessment and Report Prepared By	Tony Worthy
Reviewed By	Kathleen Sullivan, Technical Report Reviewer for Mark Surdam Program Manager msurdam@emgcorp.com 800.733.0660 x6251

Buildings

Building Summary			
Building	Use	Constructed	Area (SF)
1	Main Building	1987	28706
2	Portable Building 18	1987	960
3	Portable Building 19	1987	960

Building	Use	Constructed	Area (SF)
4	Portable Building 20	1987	96
5	Portable Building 21	1987	96
6	Portable Building 22	1987	96
7	Portable Building 23	1987	96
8	Portable Building 24	1987	96
9	Portable Building 26	1987	96
10	Portable Building 27	1987	96
11	Portable Building 28	2002	96
12	Portable Building 29	2002	96
13	Portable Building 30	2002	96
14	Portable Building 31	2002	96
15	Portable Building 32	2002	96
16	Portable Building 33	2002	96
17	Portable Building 34	2002	96
18	Site Restroom	2003	52
TOTAL			44,59

Unit Allocation

All of the property is occupied by the Jurupa Unified School District programs. There are no tenants leasing buildings or rooms at the school.

Areas Observed

The interior spaces were observed in order to gain a clear understanding of the property's overall condition. Other areas accessed included the site within the property boundaries, the exterior of the property, and the roofs.

Key Spaces Not Observed

All key areas of the property were accessible and observed.


Plan Types

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the "why" part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the "best" fit, typically the one with the greatest significance.

Plan Type Descriptio	ns
Safety	An observed or reported unsafe condition that if left unaddressed could result in injury; a system or component that presents potential liability risk.
Performance/Integrity	Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses risk to overall system stability.
Accessibility	Does not meet ADA, UFAS, and/or other handicap accessibility requirements.
Environmental	Improvements to air or water quality, including removal of hazardous materials from the building or site.
Retrofit/Adaptation	Components, systems, or spaces recommended for upgrades in in order to meet current standards, facility usage, or client/occupant needs.
Lifecycle/Renewal	Any component or system that is not currently deficient or problematic but for which future replacement or repair is anticipated and budgeted.

Plan Type Descriptions

Plan Type Distribution (by Cost)



10-YEAR TOTAL: \$4,830,200

Campus Findings and Deficiencies

Historical Summary

The Indian Hill Elementary School campus was constructed in 1987 with the Site Restroom Building constructed in 2003 and the Portable Buildings 28-34 added in 2002. Most buildings have had some upgrades and additions since their original construction.

Architectural

The buildings are constructed of wood frame, stucco and wood façade. There is water damages to the wood façades. For all the buildings, only typical lifecycle interior finish, exterior finish, and roof membrane replacements are budgeted and anticipated.

Mechanical, Electrical, Plumbing and Fire (MEPF)

The MEPF systems and components have been well-maintained since original construction and most of the building's MEPF portfolio has been upgraded. Most of roof-top equipment throughout the campus was upgraded in 2012. The wall mounted units serving the portable buildings are outdated. Due to the condition and age of the units, the district is advising replacement of units for energy efficiency purposes. Interior lighting throughout the campus buildings were upgraded to LED fixtures in 2016.

Site

Composed of regular landscaping and common area parking lots with pedestrian walkways, athletic fields and playgrounds, the site is in fair overall condition. The irrigation is in failed condition.

Recommended Additional Studies

The irrigation is in failed condition. The existing irrigation system has coverage issues throughout the campus. A professional engineer must be retained to analyze the existing condition, provide recommendations and, if necessary, estimate the scope and cost of any required repairs. The cost of this study is included in the cost tables. A budgetary cost allowance to replace the irrigation system is also included.



Facility Condition Index (FCI)

One of the major goals of the FCA is to calculate each building's Facility Condition Index (FCI), which provides a theoretical objective indication of a building's overall condition. By definition, the FCI is defined as the ratio of the cost of current needs divided by current replacement value (CRV) of the facility. The chart below presents the industry standard ranges and cutoff points.

FCI Ranges and Description					
0 – 5%	In new or well-maintained condition, with little or no visual evidence of wear or other deficiencies.				
5 – 10%	Subjected to wear but is still in a serviceable and functioning condition.				
10 – 30%	Subjected to hard or long-term wear. Nearing the end of its useful or serviceable life.				
30% and above	Has reached the end of its useful or serviceable life. Renewal is now necessary.				

The deficiencies and lifecycle needs identified in this assessment provide the basis for a portfolio-wide capital improvement funding strategy. In addition to the current FCI, extended FCI's have been developed to provide owners the intelligence needed to plan and budget for the "keep-up costs" for their facilities. As such the 3-year, 5-year, and 10-year FCI's are calculated by dividing the anticipated needs of those respective time periods by current replacement value. As a final point, the FCI's ultimately provide more value when used to relatively compare facilities across a portfolio instead of being overanalyzed and scrutinized as stand-alone values. The table below summarizes the individual findings for this FCA:


Facility (year built)	Cost/SF	Total SF	Replacement Value	Current	3-Year	5-Year	10-Year
Indian Hills Elementary School / Main Building	\$450	28,706	\$12,917,700	0.0%	2.7%	11.5%	23.1%
Indian Hills Elementary School / Portable Classroom #18	\$175	960	\$168,000	0.0%	6.2%	29.4%	46.9%
Indian Hills Elementary School / Portable Classroom #19	\$175	960	\$168,000	0.0%	6.2%	29.4%	46.9%
Indian Hills Elementary School / Portable Classroom #20	\$175	960	\$168,000	0.0%	13.9%	28.9%	46.4%
Indian Hills Elementary School / Portable Classroom #21	\$175	960	\$168,000	0.0%	13.9%	28.9%	46.4%
Indian Hills Elementary School / Portable Classroom #22	\$175	960	\$168,000	0.0%	6.2%	29.4%	46.9%
Indian Hills Elementary School / Portable Classroom #23	\$175	960	\$168,000	0.0%	6.2%	21.1%	51.2%
Indian Hills Elementary School / Portable Classroom #24	\$175	960	\$168,000	0.0%	6.2%	29.4%	46.9%
Indian Hills Elementary School / Portable Classroom #26	\$175	960	\$168,000	0.0%	3.8%	18.7%	38.7%
Indian Hills Elementary School / Portable Classroom #27	\$175	960	\$168,000	0.0%	11.5%	26.5%	46.6%
Indian Hills Elementary School / Portable Classroom #28	\$175	960	\$168,000	0.0%	3.8%	9.7%	18.9%
Indian Hills Elementary School / Portable Classroom #29	\$175	960	\$168,000	0.0%	3.8%	9.7%	18.9%
Indian Hills Elementary School / Portable Classroom #30	\$175	960	\$168,000	0.0%	3.8%	16.1%	25.7%
Indian Hills Elementary School / Portable Classroom #31	\$175	960	\$168,000	0.0%	3.8%	16.1%	25.7%
Indian Hills Elementary School / Portable Classroom #32	\$175	960	\$168,000	0.0%	3.8%	16.1%	25.7%
Indian Hills Elementary School / Portable Classroom #33	\$175	960	\$168,000	0.0%	3.8%	16.1%	25.7%
Indian Hills Elementary School / Portable Classroom #34	\$175	960	\$168,000	0.0%	3.8%	16.1%	36.7%
Indian Hills Elementary School / Site	\$0	0	\$1	0.0%	0.0%	0.0%	0.0%
Indian Hills Elementary School / Site Restrooms	\$175	528	\$92,400	0.0%	0.0%	23.7%	27.3%

The orange line in the graph below forecasts what would happen to the FCI (left axis) over time, assuming zero capital expenditures. The capital expenditures for each year (blue bars) are associated with the right axis.

Needs by Year with Unaddressed FCI Over Time

FCI Analysis: Indian Hills Elementary School

Replacement Value: \$ 20,067,300; Inflation rate: 3.0%



Immediate Needs

Facility/Building

Total (3 items)

Indian Hills	Elementary School				3	\$203,674
Total					3	\$203,674
Indian Hills	Elementary School	UF Code	Description	Condition	Plan Type	Cost
1434236	Indian Hills Elementary School / Site	G2047	Play Surfaces & Sports Courts, Asphalt, Replace	Poor	Performance/Integrity	\$21.572
1434163	Indian Hills Elementary School / Site	G2057	Irrigation System, Replace/Install	Poor	Performance/Integrity	\$174,353
1480140	Indian Hills Flomentany School / Site	DUUUA	Engineer Civil Landscaping	Door	Porformanco/Intogrity	¢7 7/0

Total Cost

\$203,674

Total Items

Key Findings



Roof in Poor condition.

Modified Bituminous Portable Classroom #27 Portable Building 27

Uniformat Code: B3011

Recommendation: Replace in 2020

Priority Score: 90.0

Plan Type:

Performance/Integrity

Cost Estimate: \$12.500

\$\$\$\$

The client has reported that there are roof leaks throughout this building. - AssetCALC ID: 1479766



Roof in Poor condition.

Modified Bituminous Portable Classroom #20 Portable Building 20 Roof

Uniformat Code: B3011

Recommendation: Replace in 2020

Priority Score: 90.0


Plan Type:

Performance/Integrity

Cost Estimate: \$12,500

\$\$\$\$

The client has reported that there are roof leaks in this portable building. - AssetCALC ID: 1445560



Roof in Poor condition.

Modified Bituminous Portable Classroom #21 Portable Building 21 Roof

Uniformat Code: B3011

Recommendation: Replace in 2020

Priority Score: 90.0

Plan Type:

Performance/Integrity

Cost Estimate: \$12,500

\$\$\$\$

The client has reported that there are roof leaks in this portable building. - AssetCALC ID: 1445574



Exterior Wall in Poor condition.

any Painted Surface, 1-2 Stories Main Building Main Building Exterior

Uniformat Code: B2011

Recommendation: Prep & Paint in 2020

Priority Score: **89.9**

Plan Type:

Performance/Integrity

Cost Estimate: \$8,200

\$\$\$\$

EMG PROJECT NO.: 139069.19R000-007.354

The existing wood was replaced due to water damaged and never repainted. Wood facade is peeling. -AssetCALC ID: 1434268



Packaged Unit (RTU) in Poor condition.

7.5 TON Main Building Main Building Roof

Uniformat Code: D3052

Recommendation: Replace in 2020

Priority Score: 86.0

Plan Type:

Performance/Integrity

Cost Estimate: \$16,600

Due to the condition and age of this unit the district is advising replacement of units for energy efficiency purposes - AssetCALC ID: 1434117



Irrigation System in Poor condition.

Site Site

Uniformat Code: G2057

Recommendation: Replace/Install in 2019

Priority Score: 83.0

Plan Type:

Performance/Integrity

Cost Estimate: \$174,400

Client has reported coverage issues with irrigation system. - AssetCALC ID: 1434163



Play Surfaces & Sports Courts in Poor condition.

Asphalt

Site Kindergarten playground

Uniformat Code: G2047

Recommendation: Replace in 2019

Priority Score: 83.0

Plan Type:

Performance/Integrity

Cost Estimate: \$21,600

The existing asphalt surface has large cracks throughout and several areas that are breaking up. -

AssetCALC ID: 1434236



Recommended Follow-up Study: Civil, Landscaping

Civil, Landscaping Site Site

Uniformat Code: P000X

Recommendation: Perform Study in 2019

Priority Score: 82.0

Plan Type:

Performance/Integrity

Cost Estimate: \$7,700

\$\$\$\$

The client has reported that existing irrigation system has coverage issues throughout the property. - AssetCALC ID: 1480140



Sprinkler System

Full Retrofit, Medium Density/Complexity Main Building Main Building

Uniformat Code: D4019

Recommendation: Renovate in 2023

Priority Score: 60.9

Plan Type:

Modernization/Adaptation

Cost Estimate: \$158,900

\$\$\$\$

There is no sprinkler system installed in this building. - AssetCALC ID: 1441146

2. Main Building





Main Building: Syste	ems Summary	
Address	7750 Linares Ave. Jurupa Valley, CA 92509	
Constructed/Renovated	1987	
Building Size	28,706 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood frame structure on concrete slab	Fair
Façade	Stucco with aluminum windows Wood siding with aluminum windows	Fair
Roof	Primary: Flat construction with single-ply TPO/PVC membrane Secondary: Gable construction with asphalt shingles	Fair
Interiors	Walls: Wallpaper, wood, ceramic tile Floors: Carpet, VCT, ceramic tile, quarry tile, linoleum, composite tile Ceilings: Painted gypsum board, ACT, wood	Fair
Elevators	None	

Main Building: Syste	ms Summary	
Plumbing	Copper supply and cast-iron waste & venting Electric water heaters Toilets, urinals, and sinks in all restrooms	Fair
HVAC	Individual rooftop package units	Fair
Fire Suppression	Fire extinguishers, kitchen hood system	Fair
Electrical	Source & Distribution: Main switchboard, panel with copper wiring Interior Lighting: LED	Fair
Fire Alarm	Alarm panel, smoke detectors, alarms, strobes, pull stations, back-up emergency lights, and exit signs	Fair
Equipment/Special	Commercial kitchen equipment	Fair
Accessibility	Presently it does not appear an accessibility study is needed for this property.	
Key Issues and Findings	Due to the condition and age of the units, the district is advising replacement of energy efficiency purposes, exterior wood façade cracking and peeling, building fire suppression	

See Appendix D for the Component Condition Table.

	Immediate	Short Term	Near Term	Med Term	Long Term	
System		(3 yr)	(5 yr)	(10 yr)	(20 yr)	TOTAL
Facade		\$70,500	\$181,700	\$26,100	\$463,500	\$741,700
Roofing	+	\$384,800	14	-	\$168,700	\$553,500
Interiors		\$102,600	\$286,400	\$405,200	\$479,600	\$1,273,700
Plumbing	-	\$4,300	\$22,800	\$506,800	\$18,100	\$552,100
Fire Suppression	2	-	\$178,800	\$5,000	\$6,700	\$190,400
HVAC		\$188,100	\$10,000	e	\$257,300	\$455,500
Electrical	(-)	\$11,200	\$7,500	\$217,100	\$706,900	\$942,700
Fire Alarm & Comm	9	-	(2)	\$19,800		\$19,800
Equipment/Special	-	\$9,200	\$200,700	\$4,800	\$30,300	\$245,000
Pavement	1	-	11		\$2,500	\$2,500
TOTALS		\$770,700	\$887,900	\$1,184,800	\$2,133,600	\$4,976,900





Portable Building 18: Systems Summary				
Address	7750 Linares Ave. Jurupa Valley, CA 92509			
Constructed/Renovated	1987			
Building Size	960 SF			
Number of Stories	1			
System	Description	Condition		
Structure	Conventional wood frame structure on concrete slab	Fair		
Façade	Wood siding with steel windows	Fair		
Roof	Primary: Flat construction with modified bituminous finish	Fair		
Interiors	Walls: Painted Fiberboard Floors: Carpet Ceilings: ACT	Fair		
Elevators	None	-		
Plumbing	None			

Portable Building 18:	Systems Summary	
HVAC	Wall mounted heat pumps	Poor
Fire Suppression	Fire extinguishers	Fair
Electrical	Source & Distribution: Main Fed from electrical panel on site with copper wiring Interior Lighting: LED	Fair
Fire Alarm	smoke detectors, alarms, strobes, pull stations connected to Main Building	Fair
Equipment/Special	None	
Accessibility	Presently it does not appear an accessibility study is needed for this property.	
Key Issues and Findings	Building lacks fire suppression, Due to the condition and age of the units, the diadvising replacement of units for energy efficiency purposes	istrict is

Systems Expendit	ure Forecast					
System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL
Facade	-	\$4,000	\$11,900	\$6,500	\$7,700	\$30,100
Roofing	-	\$13,600	-	-	-	\$13,600
Interiors	-	\$4,100	-	\$8,200	\$37,500	\$49,900
Fire Suppression	-	-	\$3,600	\$200	\$300	\$4,100
HVAC	-	\$6,300	-	-	-	\$6,300
Electrical	-	-	-	\$17,500	\$14,400	\$31,900
Fire Alarm & Comm	-	-	\$4,800	-	-	\$4,800
Pavement	-	-	-	-	-	-
TOTALS	-	\$28,000	\$20,300	\$32,400	\$59,900	\$140,700





Portable Building 19	: Systems Summary	
Address	7750 Linares Ave. Jurupa Valley, CA 92509	
Constructed/Renovated	1987	
Building Size	960 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood frame structure on concrete slab	Fair
Façade	Wood siding with steel windows	Fair
Roof	Primary: Flat construction with modified bituminous finish	Fair
Interiors	Walls: Painted Fiberboard Floors: Carpet Ceilings: ACT	Fair
Elevators	None	
Plumbing	None	

Portable Building 19:	Systems Summary	
HVAC	Wall mounted heat pumps	Poor
Fire Suppression	Fire extinguishers	Fair
Electrical	Source & Distribution: Main Fed from electrical panel on site with copper wiring Interior Lighting: LED	Fair
Fire Alarm	smoke detectors, alarms, strobes, pull stations connected to Main Building	Fair
Equipment/Special	None	
Accessibility	Presently it does not appear an accessibility study is needed for this property.	
Key Issues and Findings	Building lacks fire suppression, Due to the condition and age of the units, the diadvising replacement of units for energy efficiency purposes	istrict is

Systems Expenditu	ure Forecast					
System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL
Facade	-	\$4,000	\$11,900	\$6,500	\$7,700	\$30,100
Roofing	-	\$13,600	-	-	-	\$13,600
Interiors	-	\$4,100	-	\$8,200	\$37,500	\$49,900
Fire Suppression	-	-	\$3,600	\$200	\$300	\$4,100
HVAC	-	\$6,300	-	-	-	\$6,300
Electrical	-	-	-	\$17,500	\$14,400	\$31,900
Fire Alarm & Comm	-	-	\$4,800	-	-	\$4,800
Pavement	-	-	-	-	-	-
TOTALS	-	\$28,000	\$20,300	\$32,400	\$59,900	\$140,700





Portable Building 20	e: Systems Summary	
Address	7750 Linares Ave. Jurupa Valley, CA 92509	
Constructed/Renovated	1987	
Building Size	960 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood frame structure on concrete slab	Fair
Façade	Wood siding with steel windows	Fair
Roof	Primary: Flat construction with modified bituminous finish	Fair
Interiors	Walls: Painted Fiberboard Floors: Carpet Ceilings: ACT	Fair
Elevators	None	
Plumbing	None	

Portable Building 20:	Systems Summary	
HVAC	Wall mounted heat pumps	Poor
Fire Suppression	Fire extinguishers	Fair
Electrical	Source & Distribution: Main Fed from electrical panel on site with copper wiring Interior Lighting: LED	Fair
Fire Alarm	smoke detectors, alarms, strobes, pull stations connected to Main Building	Fair
Equipment/Special	None	
Accessibility	Presently it does not appear an accessibility study is needed for this property.	
Key Issues and Findings	Building lacks fire suppression, reported roof leaks, Due to the condition and a units, the district is advising replacement of units for energy efficiency purposes	

Systems Expenditu	ire Forecast					
System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL
Facade	-	\$4,000	\$11,900	\$6,500	\$7,700	\$30,100
Roofing	-	\$12,900	-	-	-	\$12,900
Interiors	-	\$4,100	-	\$8,200	\$37,500	\$49,900
Fire Suppression	-	-	\$3,600	\$200	\$300	\$4,100
HVAC	-	\$6,300	-	-	-	\$6,300
Electrical	-	-	-	\$17,500	\$14,400	\$31,900
Fire Alarm & Comm	-	-	\$4,800	-	-	\$4,800
Pavement	-	-	-	-	-	-
TOTALS	-	\$27,300	\$20,300	\$32,400	\$59,900	\$140,000





Address	7750 Linares Ave. Jurupa Valley, CA 92509	
Constructed/Renovated	1987	
Building Size	640 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood frame structure on concrete slab	Fair
Façade	Wood siding with steel windows	Fair
Roof	Primary: Flat construction with modified bituminous finish	Fair
Interiors	Walls: Painted Fiberboard Floors: Carpet Ceilings: ACT	Fair
Elevators	None	
Plumbing	None	

Portable Building 21:	Systems Summary	
HVAC	Wall mounted heat pumps	Poor
Fire Suppression	Fire extinguishers	Fair
Electrical	Source & Distribution: Main Fed from electrical panel on site with copper wiring Interior Lighting: LED	Fair
Fire Alarm	smoke detectors, alarms, strobes, pull stations connected to Main Building	Fair
Equipment/Special	None	
Accessibility	Presently it does not appear an accessibility study is needed for this property.	
Key Issues and Findings	Building lacks fire suppression, reported roof leaks, Due to the condition and a units, the district is advising replacement of units for energy efficiency purposes	

Systems Expendit	ure Forecast					
System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL
Facade	-	\$4,000	\$11,900	\$6,500	\$7,700	\$30,100
Roofing	-	\$12,900	-	-	-	\$12,900
Interiors	-	\$4,100	-	\$8,200	\$37,500	\$49,900
Fire Suppression	-	-	\$3,600	\$200	\$300	\$4,100
HVAC	-	\$6,300	-	-	-	\$6,300
Electrical	-	-	-	\$17,500	\$14,400	\$31,900
Fire Alarm & Comm	-	-	\$4,800	-	-	\$4,800
Pavement	-	-	-	-		-
TOTALS	-	\$27,300	\$20,300	\$32,400	\$59,900	\$140,000





Portable Building 22: Systems Summary				
Address	7750 Linares Ave. Jurupa Valley, CA 92509			
Constructed/Renovated	1987			
Building Size	960 SF			
Number of Stories	1			
System	Description	Condition		
Structure	Conventional wood frame structure on concrete slab	Fair		
Façade	Wood siding with steel windows	Fair		
Roof	Primary: Flat construction with modified bituminous finish	Fair		
Interiors	Walls: Painted Fiberboard Floors: Carpet Ceilings: ACT	Fair		
Elevators	None	-		
Plumbing	None			

Portable Building 22:	Systems Summary	
HVAC	Wall mounted heat pumps	Poor
Fire Suppression	Fire extinguishers	Fair
Electrical	Source & Distribution: Main Fed from electrical panel on site with copper wiring Interior Lighting: LED	Fair
Fire Alarm	smoke detectors, alarms, strobes, pull stations connected to Main Building	Fair
Equipment/Special	None	
Accessibility	Presently it does not appear an accessibility study is needed for this property.	
Key Issues and Findings	Building lacks fire suppression, Due to the condition and age of the units, the diadvising replacement of units for energy efficiency purposes	strict is

Systems Expenditure Forecast							
System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL	
Facade	-	\$4,000	\$11,900	\$6,500	\$7,700	\$30,100	
Roofing	-	\$13,600	-	-	-	\$13,600	
Interiors	-	\$4,100	-	\$8,200	\$37,500	\$49,900	
Fire Suppression	-	-	\$3,600	\$200	\$300	\$4,100	
HVAC	-	\$6,300	-	-	-	\$6,300	
Electrical	-	-	-	\$17,500	\$14,400	\$31,900	
Fire Alarm & Comm	-	-	\$4,800	-	-	\$4,800	
Pavement	-	-	-	-	-	-	
TOTALS	-	\$28,000	\$20,300	\$32,400	\$59,900	\$140,700	





Portable Building 23	: Systems Summary	
Address	7750 Linares Ave. Jurupa Valley, CA 92509	
Constructed/Renovated	1987	
Building Size	960 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood frame structure on concrete slab	Fair
Façade	Wood siding with steel windows	Fair
Roof	Primary: Flat construction with modified bituminous finish	Fair
Interiors	Walls: Painted Fiberboard Floors: Carpet Ceilings: ACT	Fair
Elevators	None	
Plumbing	None	

Portable Building 23: Systems Summary					
HVAC	Wall mounted heat pumps	Poor			
Fire Suppression	Fire extinguishers	Fair			
Electrical	Source & Distribution: Main Fed from electrical panel on site with copper wiring Interior Lighting: LED	Fair			
Fire Alarm	smoke detectors, alarms, strobes, pull stations connected to Main Building	Fair			
Equipment/Special	None				
Accessibility	Presently it does not appear an accessibility study is needed for this property.				
Key Issues and Findings	Building lacks fire suppression, Due to the condition and age of the units, the diadvising replacement of units for energy efficiency purposes	istrict is			

Systems Expenditure Forecast								
System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL		
Facade	-	\$4,000	\$11,900	\$6,500	\$7,700	\$30,100		
Roofing	-	-	-	\$20,600	-	\$20,600		
Interiors	-	\$4,100	-	\$8,200	\$37,500	\$49,900		
Fire Suppression	-	-	\$3,600	\$200	\$300	\$4,100		
HVAC	-	\$6,300	-	-	-	\$6,300		
Electrical	-	-	-	\$17,500	\$14,400	\$31,900		
Fire Alarm & Comm	-	-	\$4,800	-	-	\$4,800		
Pavement	-	-	-	-	-	-		
TOTALS	-	\$14,400	\$20,300	\$53,000	\$59,900	\$147,700		





Portable Building 24:	Systems Summary	
Address	7750 Linares Ave. Jurupa Valley, CA 92509	
Constructed/Renovated	1987	
Building Size	960 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood frame structure on concrete slab	Fair
Façade	Wood siding with steel windows	Fair
Roof	Primary: Flat construction with modified bituminous finish	Fair
Interiors	Walls: Painted Fiberboard Floors: Carpet Ceilings: ACT	Fair
Elevators	None	
Plumbing	None	

Portable Building 24: Systems Summary					
HVAC	Wall mounted heat pumps	Poor			
Fire Suppression	Fire extinguishers	Fair			
Electrical	Source & Distribution: Main Fed from electrical panel on site with copper wiring Interior Lighting: LED	Fair			
Fire Alarm	smoke detectors, alarms, strobes, pull stations connected to Main Building	Fair			
Equipment/Special	None				
Accessibility	Presently it does not appear an accessibility study is needed for this property.				
Key Issues and Findings	Building lacks fire suppression, Due to the condition and age of the units, the diadvising replacement of units for energy efficiency purposes	strict is			

Systems Expenditure Forecast								
System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL		
Facade	-	\$4,000	\$11,900	\$6,500	\$7,700	\$30,100		
Roofing	-	\$13,600	-	-	-	\$13,600		
Interiors	-	\$4,100	-	\$8,200	\$37,500	\$49,900		
Fire Suppression	-	-	\$3,600	\$200	\$300	\$4,100		
HVAC	-	\$6,300	-	-	-	\$6,300		
Electrical	-	-	-	\$17,500	\$14,400	\$31,900		
Fire Alarm & Comm	-	-	\$4,800	-	-	\$4,800		
Pavement	-	-	-	-	-	-		
TOTALS	-	\$28,000	\$20,300	\$32,400	\$59,900	\$140,700		





Portable Buildings 2	6: Systems Summary	
Address	7750 Linares Ave. Jurupa Valley, CA 92509	
Constructed/Renovated	1987	
Building Size	960 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood frame structure on concrete slab	Fair
Façade	Wood siding with steel windows	Fair
Roof	Primary: Flat construction with modified bituminous finish	Fair
Interiors	Walls: Painted Fiberboard Floors: Carpet Ceilings: ACT	Fair
Elevators	None	
Plumbing	None	

Portable Buildings 26: Systems Summary					
HVAC	Wall Mount Heat pump	Poor			
Fire Suppression	Fire extinguishers	Fair			
Electrical	Source & Distribution: Main Fed from electrical panel on site with copper wiring Interior Lighting: LED	Fair			
Fire Alarm	smoke detectors, alarms, strobes, pull stations connected to Main Building	Fair			
Equipment/Special	None				
Accessibility	Presently it does not appear an accessibility study is needed for this property.				
Key Issues and Findings	Building lacks fire suppression, Due to the condition and age of the units, the di advising replacement of units for energy efficiency purposes	strict is			

See Appendix D for the Component Condition Table.

Systems Expenditure Forecast						
System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL
Facade	-	\$4,100	\$11,900	\$6,500	\$7,700	\$30,300
Roofing	-	-		\$16,800		\$16,800
Interiors	75	9	\$4,300	\$8,200	\$37,500	\$50,100
Fire Suppression	-	-	\$3,600	\$400	\$500	\$4,500
HVAC	-	\$6,300	1	- 2-	×	\$6,300
Electrical	+	15	+	\$17,500	\$14,400	\$31,900
Fire Alarm & Comm	-	-	\$4,800	+		\$4,800
Pavement	-	1000	÷ .		\$1,600	\$1,600
TOTALS	-	\$10,400	\$24,600	\$49,400	\$61,700	\$146,300





Portable Buildings 27	': Systems Summary	
Address	7750 Linares Ave. Jurupa Valley, CA 92509	
Constructed/Renovated	1987	
Building Size	960 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood frame structure on concrete slab	Fair
Façade	Wood siding with steel windows	Fair
Roof	Primary: Flat construction with modified bituminous finish	Fair
Interiors	Walls: Painted Fiberboard	Fair
	Floors: Carpet	
	Ceilings: ACT	
Elevators	None	
Plumbing	None	

Portable Buildings 27: Systems Summary				
HVAC	Wall Mount Heat pump	Poor		
Fire Suppression	Fire extinguishers	Fair		
Electrical	Source & Distribution: Main Fed from electrical panel on site with copper wiring Interior Lighting: LED	Fair		
Fire Alarm	smoke detectors, alarms, strobes, pull stations connected to Main Building	Fair		
Equipment/Special	None			
Accessibility	Presently it does not appear an accessibility study is needed for this property.			
Key Issues and Findings	Building lacks fire suppression, reported roof leak, Due to the condition and age units, the district is advising replacement of units for energy efficiency purposes			

See Appendix D for the Component Condition Table.

Systems Expenditure Forecast						
System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL
Facade	-	\$4,100	\$11,900	\$6,500	\$7,700	\$30,300
Roofing	-	\$12,900	~	y.	*	\$12,900
Interiors	-	9	\$4,300	\$8,200	\$37,500	\$50,100
Fire Suppression	-	-	\$3,600	\$200	\$300	\$4,100
HVAC	-	\$6,300	1	2		\$6,300
Electrical	+	-	+	\$17,500	\$14,400	\$31,900
Fire Alarm & Comm	1-	~	\$4,800	+	- 4	\$4,800
Pavement	÷	l e		7 P	\$1,600	\$1,600
TOTALS		\$23,300	\$24,600	\$32,400	\$61,500	\$142,000





Portable Buildings 2	8: Systems Summary	
Address	7750 Linares Ave. Jurupa Valley, CA 92509	
Constructed/Renovated	2002	
Building Size	960 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood frame structure on concrete slab/ with raised floor	Fair
Façade	Wood siding with steel windows	Fair
Roof	Primary: Flat construction with metal finish	Fair
Interiors	Walls: Painted Fiberboard Floors: Carpet Ceilings: ACT	Fair
Elevators	None	
Plumbing	None	

Portable Buildings 28	: Systems Summary	
HVAC	Wall mounted heat pumps	Poor
Fire Suppression	Fire extinguishers	Fair
Electrical	Source & Distribution: Main Fed from electrical panel on site with copper wiring Interior Lighting: LED	Fair
Fire Alarm	smoke detectors, alarms, strobes, pull stations connected to Main Building	Fair
Equipment/Special	None	
Accessibility	Presently it does not appear an accessibility study is needed for this property.	
Key Issues and Findings	Building lacks fire suppression, Due to the condition and age of the units, the diadvising replacement of units for energy efficiency purposes	strict is

See Appendix D for the Component Condition Table.

Systems Expenditure Forecast						
System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL
Facade	-	\$4,600	-	-	\$27,300	\$32,000
Roofing	-	-	-	-	-	-
Interiors	-	-	-	\$14,200	\$12,800	\$27,000
Fire Suppression	-	-	-	\$200	\$300	\$500
HVAC	-	\$6,300	-	-	-	\$6,300
Electrical	-	\$200	-	-	\$14,100	\$14,300
Fire Alarm & Comm	-	-	\$4,800	-	-	\$4,800
Pavement	_	-	-	-		-
TOTALS		\$11,100	\$4,800	\$14,400	\$54,500	\$84,900





Portable Buildings 2	9: Systems Summary	
Address	7750 Linares Ave. Jurupa Valley, CA 92509	
Constructed/Renovated	2002	
Building Size	1,920 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood frame structure on concrete slab/ with raised floor	Fair
Façade	Wood siding with steel windows	Fair
Roof	Primary: Flat construction with metal finish	Fair
Interiors	Walls: Painted Fiberboard Floors: Carpet Ceilings: ACT	Fair
Elevators	None	
Plumbing	None	

Portable Buildings 29: Systems Summary				
HVAC	Wall mounted heat pumps	Poor		
Fire Suppression	Fire extinguishers	Fair		
Electrical	Source & Distribution: Main Fed from electrical panel on site with copper wiring Interior Lighting: LED	Fair		
Fire Alarm	smoke detectors, alarms, strobes, pull stations connected to Main Building	Fair		
Equipment/Special	None			
Accessibility	Presently it does not appear an accessibility study is needed for this property.			
Key Issues and Findings	Building lacks fire suppression, Due to the condition and age of the units, the di advising replacement of units for energy efficiency purposes	istrict is		

See Appendix D for the Component Condition Table.

Systems Expenditure Forecast						
System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL
Facade	-	\$4,600	-	-	\$27,300	\$32,000
Roofing	-	-	-	-	-	-
Interiors	-	-	-	\$14,200	\$12,800	\$27,000
Fire Suppression	-	-	-	\$200	\$300	\$500
HVAC	-	\$6,300	-	-	-	\$6,300
Electrical	-	\$200	-	-	\$14,100	\$14,300
Fire Alarm & Comm	-	-	\$4,800	-	-	\$4,800
Pavement	_	-	-	-		-
TOTALS		\$11,100	\$4,800	\$14,400	\$54,500	\$84,900

14. Portable Buildings 30





Portable Buildings 30	: Systems Summary	
Address	7750 Linares Ave. Jurupa Valley, CA 92509	
Constructed/Renovated	2002	
Building Size	960 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood frame structure on concrete slab	Fair
Façade	Wood siding with steel windows	Fair
Roof	Primary: Flat construction with metal finish	Fair
Interiors	Walls: Painted Fiberboard Floors: Carpet Ceilings: ACT	Fair
Elevators	None	
Plumbing	None	

Portable Buildings 30	: Systems Summary	
HVAC	Wall Mounted heat pumps	Poor
Fire Suppression	Fire extinguisher	Fair
Electrical	Source & Distribution: Main Fed from electrical panel on site with copper wiring Interior Lighting: LED	Fair
Fire Alarm	smoke detectors, alarms, strobes, pull stations connected to Main Building	Fair
Equipment/Special	None	
Accessibility	Presently it does not appear an accessibility study is needed for this property.	
Key Issues and Findings	Building lacks fire suppression, Due to the condition and age of the units, the diadvising replacement of units for energy efficiency purposes	strict is

See Appendix D for the Component Condition Table.

Systems Expenditure Forecast							
System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL	
Structure	-	-	-	-	-	\$100	
Facade	-	\$11,600	-	\$5,700	\$13,200	\$30,500	
Roofing	-	-	-	-	-	-	
Interiors	-	-	-	\$14,500	\$13,200	\$27,700	
Fire Suppression	-	-	\$3,600	\$200	\$300	\$4,100	
HVAC	-	\$6,300	-	-	-	\$6,300	
Electrical	-	\$200	-	-	\$14,400	\$14,600	
Fire Alarm & Comm	-	-	\$4,800	-		\$4,800	
TOTALS	-	\$18,100	\$8,400	\$20,400	\$41,100	\$88,100	

15. Portable Buildings 31





Portable Buildings 31	I: Systems Summary	
Address	7750 Linares Ave. Jurupa Valley, CA 92509	
Constructed/Renovated	2002	
Building Size	960 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood frame structure on concrete slab	Fair
Façade	Wood siding with steel windows	Fair
Roof	Primary: Flat construction with metal finish	Fair
Interiors	Walls: Painted Fiberboard Floors: Carpet Ceilings: ACT	Fair
Elevators	None	
Plumbing	None	

Portable Buildings 31	: Systems Summary	
HVAC	Wall Mounted heat pumps	Poor
Fire Suppression	Fire extinguisher	Fair
Electrical	Source & Distribution: Main Fed from electrical panel on site with copper wiring Interior Lighting: LED	Fair
Fire Alarm	smoke detectors, alarms, strobes, pull stations connected to Main Building	Fair
Equipment/Special	None	
Accessibility	Presently it does not appear an accessibility study is needed for this property.	
Key Issues and Findings	Building lacks fire suppression, Due to the condition and age of the units, the diadvising replacement of units for energy efficiency purposes	istrict is

See Appendix D for the Component Condition Table.

Systems Expenditure Forecast							
System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL	
Structure	-	-	-	-	-	\$100	
Facade	-	\$11,600	-	\$5,700	\$13,200	\$30,500	
Roofing	-	-	-	-	-	-	
Interiors	-	-	-	\$14,500	\$13,200	\$27,700	
Fire Suppression	-	-	\$3,600	\$200	\$300	\$4,100	
HVAC	-	\$6,300	-	-	-	\$6,300	
Electrical	-	\$200	-	-	\$14,100	\$14,300	
Fire Alarm & Comm	-	-	\$4,800	-	-	\$4,800	
TOTALS		\$18,100	\$8,400	\$20,400	\$40,800	\$87,800	

16. Portable Buildings 32





Portable Buildings 3	2: Systems Summary	
Address	7750 Linares Ave. Jurupa Valley, CA 92509	
Constructed/Renovated	2002	
Building Size	960 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood frame structure on concrete slab	Fair
Façade	Wood siding with steel windows	Fair
Roof	Primary: Flat construction with metal finish	Fair
Interiors	Walls: Painted Fiberboard Floors: Carpet Ceilings: ACT	Fair
Elevators	None	
Plumbing	None	

Portable Buildings 32	: Systems Summary	
HVAC	Wall Mounted heat pumps	Poor
Fire Suppression	Fire extinguisher	Fair
Electrical	Source & Distribution: Main Fed from electrical panel on site with copper wiring Interior Lighting: LED	Fair
Fire Alarm	smoke detectors, alarms, strobes, pull stations connected to Main Building	Fair
Equipment/Special	None	
Accessibility	Presently it does not appear an accessibility study is needed for this property.	
Key Issues and Findings	Building lacks fire suppression, Due to the condition and age of the units, the diadvising replacement of units for energy efficiency purposes	istrict is

See Appendix D for the Component Condition Table.

Systems Expenditure Forecast							
System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL	
Structure	-	-	-	-	-	\$100	
Facade	-	\$11,600	-	\$5,700	\$13,200	\$30,500	
Roofing	-	-	-	-	-	-	
Interiors	-	-	-	\$14,500	\$13,200	\$27,700	
Fire Suppression	-	-	\$3,600	\$200	\$300	\$4,100	
HVAC	-	\$6,300	-	-	-	\$6,300	
Electrical	-	\$200	-	-	\$14,100	\$14,300	
Fire Alarm & Comm	-	-	\$4,800	-	-	\$4,800	
TOTALS	-	\$18,100	\$8,400	\$20,400	\$40,800	\$87,800	

17. Portable Buildings 33





Portable Buildings 33	3: Systems Summary	
Address	7750 Linares Ave. Jurupa Valley, CA 92509	
Constructed/Renovated	2002	
Building Size	960 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood frame structure on concrete slab	Fair
Façade	Wood siding with steel windows	Fair
Roof	Primary: Flat construction with metal finish	Fair
Interiors	Walls: Painted Fiberboard Floors: Carpet Ceilings: ACT	Fair
Elevators	None	
Plumbing	None	

Portable Buildings 33	: Systems Summary	
HVAC	Wall Mounted heat pumps	Poor
Fire Suppression	Fire extinguisher	Fair
Electrical	Source & Distribution: Main Fed from electrical panel on site with copper wiring Interior Lighting: LED	Fair
Fire Alarm	smoke detectors, alarms, strobes, pull stations connected to Main Building	Fair
Equipment/Special	None	
Accessibility	Presently it does not appear an accessibility study is needed for this property.	
Key Issues and Findings	Building lacks fire suppression, Due to the condition and age of the units, the diadvising replacement of units for energy efficiency purposes	strict is

See Appendix D for the Component Condition Table.

Systems Expenditure Forecast						
System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL
Structure	-	-	-	-	-	\$100
Facade	-	\$11,600	-	\$5,700	\$13,200	\$30,500
Roofing	-	-	-	-	-	-
Interiors	-	-	-	\$14,500	\$13,200	\$27,700
Fire Suppression	-	-	\$3,600	\$200	\$300	\$4,100
HVAC	-	\$6,300	-	-	-	\$6,300
Electrical	-	\$200	-	-	\$14,400	\$14,600
Fire Alarm & Comm	_	-	\$4,800	-		\$4,800
TOTALS		\$18,100	\$8,400	\$20,400	\$41,100	\$88,100

18. Portable Buildings 34





Portable Buildings	34: Systems Summary	
Address	7750 Linares Ave. Jurupa Valley, CA 92509	
Constructed/Renovated	2002	
Building Size	960 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood frame structure on concrete slab	Fair
Façade	Wood siding with steel windows	Fair
Roof	Primary: Flat construction with metal finish	Fair
Interiors	Walls: Painted Fiberboard Floors: Carpet Ceilings: ACT	Fair
Elevators	None	
Plumbing	None	

Portable Buildings 34	: Systems Summary	
HVAC	Wall Mounted heat pumps	Poor
Fire Suppression	Fire extinguisher	Fair
Electrical	Source & Distribution: Main Fed from electrical panel on site with copper wiring Interior Lighting: LED	Fair
Fire Alarm	smoke detectors, alarms, strobes, pull stations connected to Main Building	Fair
Equipment/Special	None	
Accessibility	Presently it does not appear an accessibility study is needed for this property.	
Key Issues and Findings	Building lacks fire suppression, Due to the condition and age of the units, the diadvising replacement of units for energy efficiency purposes	strict is

See Appendix D for the Component Condition Table.

Systems Expenditure Forecast						
System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL
Structure	-	-	-	-	-	\$100
Facade	-	\$11,600	-	\$5,700	\$13,200	\$30,500
Roofing	-	-	-	-	-	-
Interiors	-	-	-	\$14,500	\$13,200	\$27,700
Fire Suppression	-	-	\$3,600	\$200	\$300	\$4,100
HVAC	-	\$6,300	-	-	-	\$6,300
Electrical	-	\$200	-	\$17,500	\$14,100	\$31,800
Fire Alarm & Comm	-	-	\$4,800	-	-	\$4,800
TOTALS	-	\$18,100	\$8,400	\$37,900	\$40,800	\$105,300

19. Site Restrooms





Site Restrooms: Sys	stems Summary	
Address	7750 Linares Ave. Jurupa Valley, CA 92509	
Constructed/Renovated	2003	
Building Size	528 SF	
Number of Stories	1	
System	Description	Condition
Structure	Conventional wood frame structure on concrete slab	Fair
Façade	Wood siding with No windows	Fair
Roof	Primary: Flat construction with single-ply TPO/PVC membrane	Fair
Interiors	Walls: FRP Floors: Linoleum Ceilings: ACT	Fair
Elevators	None	
Plumbing	Copper supply and cast-iron waste & venting Toilets, urinals, and sinks in all restrooms	Fair


Site Restrooms: Syste	ems Summary	
HVAC	None	
Fire Suppression	None	
Electrical	Source & Distribution: Main Fed from electrical panel on site with copper wiring Interior Lighting: LED	Fair
Fire Alarm	None	
Equipment/Special	None	
Accessibility	Presently it does not appear an accessibility study is needed for this property.	
Key Issues and Findings	Building lacks fire suppression	

See Appendix D for the Component Condition Table.

Systems Expendi	ture Forecast					
System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL
Facade	-	-	-	\$4,500	\$18,700	\$23,200
Roofing	-	-	\$11,200	-	-	\$11,200
Interiors	-	-	\$5,600	\$2,700	\$30,000	\$38,300
Plumbing	-	-	-	-	\$36,200	\$36,200
Fire Suppression	-	-	\$2,000	-	-	\$2,000
Electrical	-	-	-	-	\$1,000	\$1,000
Fire Alarm & Comm	-	-	\$2,600	-	-	\$2,600
Pavement	-	-	-	-		-
TOTALS	•	-	\$21,400	\$7,200	\$85,900	\$114,500

20. Site Summary





Site Information		
Lot Size	10.3 acres (estimated)	
Parking Spaces	50 total spaces all in open lots; 3 of which are accessible	
System	Description	Condition
Pavement/Flatwork	Asphalt lots with areas of concrete and concrete sidewalks, curbs, ramps, and stairs	Fair
Site Development	Building-mounted and Property entrance signage, chain link and metal tube fencing, CMU dumpster enclosures Playgrounds and sports courts Limited picnic tables	Fair
Landscaping and Topography	Heavy landscaping features Irrigation present	Fair
Utilities	Municipal water and sewer Local utility-provided electric and natural gas	Fair
Site Lighting	Building-mounted: LED	Fair
Ancillary Structures	Metal Canopy structure	Fair
Key Issues and Findings	Civil Engineering study, Inadequate irrigation coverage throughout the property, kindergarten playground asphalt surface worn	

Systems Expenditure Forecast

	Immediate	Short Term	Near Term	Med Term	Long Term	
System		(3 yr)	(5 yr)	(10 yr)	(20 yr)	TOTAL
Structure	-	-	-	-	\$1,500	\$1,500
Plumbing	-	-	\$23,100	-	\$36,000	\$59,100
Electrical	-	\$23,500	\$7,500	\$63,100	-	\$94,100
Site Development	\$21,600	\$119,400	\$278,500	\$144,800	\$187,500	\$751,700
Pavement	-	\$21,700	-	\$25,100	\$529,200	\$576,000
Site Lighting	-	-	-	-	\$23,100	\$23,100
Landscaping	\$174,400	-	-	-	-	\$174,400
Follow-up Studies	\$7,700	-	-	-	- <u> </u>	\$7,700
TOTALS	\$203,700	\$164,600	\$309,100	\$233,000	\$777,300	\$1,687,600

21. ADA Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of "areas of public accommodations" and "public facilities" on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG).

A public entity (i.e. city governments) shall operate each service, program, or activity so that the service, program, or activity, when viewed in its entirety, is readily accessible to and usable by individuals with disabilities.

However, this does not:

- 1. Necessarily require a public entity to make each of its existing facilities accessible to and usable by individuals with disabilities;
- Require a public entity to take any action that would threaten or destroy the historic significance of an historic property; or
- 3. Require a public entity to take any action that it can demonstrate would result in a fundamental alteration in the nature of a service, program, or activity or in undue financial and administrative burdens. In those circumstances where personnel of the public entity believe that the proposed action would fundamentally alter the service, program, or activity or would result in undue financial and administrative burdens, a public entity has the burden of proving that compliance with 35.150(a) of this part would result in such alteration or burdens. The decision that compliance would result in such alteration or burdens must be made by the head of a public entity or his or her designee after considering all resources available for use in the funding and operation of the service, program, or activity, and must be accompanied by a written statement of the reasons for reaching that conclusion. If an action would result in such an alteration or such burdens, a public entity shall take any other action that would not result in such an alteration or such burdens but would nevertheless ensure that individuals with disabilities receive the benefits or services provided by the public entity.

During the FCA, EMG performed a limited high-level accessibility review of the facility non-specific to any local regulations or codes. The scope of the visual observation was limited to those areas and categories set forth in the tables throughout this report. It is understood by the Client that the limited observations described herein do not comprise a full ADA Compliance Survey, and that such a survey is beyond the scope of EMG's undertaking. Only a representative sample of areas was observed, and actual measurements were not taken to verify compliance.

The facility was originally constructed in 1987. The facility was not subsequently renovated. Complaints about accessibility issues have not been received by the property management. The property does not have associated prior litigation related to existing barriers or previously removed barriers.

An accessibility study has not been performed at the site. Although no significant issues were identified, a comprehensive ADA Compliance Survey would reveal specific aspects of the property that are not in full compliance.

The table below is intended to be used as a general reference guide to help differentiate the orders of magnitude between some of the more commonly observed accessibility issues. The table is not intended to be all-inclusive, and boxes checked in the tables above do not necessarily mean those specific problems or shortcomings cited as examples below exist at the subject buildings and sites. Reference the photolog (in the appendix) and/or *Key Findings* section for visuals and/or more specifics about the subject site conditions.

Main Building: Accessibility Issues						
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues			
Exterior Path of Travel						
Interior Path of Travel						
Public Use Restrooms						
Kitchens/Kitchenettes						

Portable Buildings 18: Accessibility Issues						
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues			
Exterior Path of Travel			\boxtimes			
Interior Path of Travel			\boxtimes			
Portable Buildings 1	9: Accessibility Issues					
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues			
Exterior Path of Travel			\boxtimes			
Interior Path of Travel						
Portable Buildings 2	0: Accessibility Issues					
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues			
Exterior Path of Travel			\boxtimes			
Interior Path of Travel						
Portable Buildings 2	1: Accessibility Issues					
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues			
Exterior Path of Travel			\boxtimes			
Interior Path of Travel						
Portable Buildings 22: Accessibility Issues						
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues			
Exterior Path of Travel			\boxtimes			
Interior Path of Travel	П	П	\boxtimes			

Portable Buildings 23: Accessibility Issues						
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues			
Exterior Path of Travel			\boxtimes			
Interior Path of Travel						
Portable Buildings 24: Accessibility Issues						
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues			
Exterior Path of Travel			\boxtimes			
Interior Path of Travel						
Portable Buildings 26: Accessibility Issues						
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues			
Exterior Path of Travel			\boxtimes			
Interior Path of Travel						
Portable Buildings 2	7: Accessibility Issues					
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues			
Exterior Path of Travel			\boxtimes			
Interior Path of Travel			\boxtimes			
Portable Buildings 2	8: Accessibility Issues					
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues			
Exterior Path of Travel			\boxtimes			
Interior Path of Travel			\boxtimes			

Portable Buildings 29: Accessibility Issues						
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues			
Exterior Path of Travel			\boxtimes			
Interior Path of Travel						
Portable Buildings 30: Accessibility Issues						
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues			
Exterior Path of Travel			\boxtimes			
Interior Path of Travel						
Portable Buildings 31: Accessibility Issues						
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues			
Exterior Path of Travel			\boxtimes			
Interior Path of Travel						
Portable Buildings 3	2: Accessibility Issues					
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues			
Exterior Path of Travel			\boxtimes			
Interior Path of Travel						
Portable Buildings 33: Accessibility Issues						
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues			
Exterior Path of Travel			\boxtimes			
Interior Path of Travel						

Portable Buildings 34: Accessibility Issues				
	Major Issues (ADA study recommended)	Moderate Issues (ADA study recommended)	Minor/No Issues	
Exterior Path of Travel			\boxtimes	
Interior Path of Travel			\boxtimes	
Site Restrooms: Accessibility Issues				
	Major Issues	Moderate Issues	Minor/No Issues	
	(ADA study recommended)	(ADA study recommended)		
Exterior Path of Travel			\boxtimes	
Interior Path of Travel			\boxtimes	
Public Use Restrooms			\boxtimes	
Kitchens/Kitchenettes				
Site: Accessibility Issues				
	Major Issues	Moderate Issues	Minor/No Issues	
	(ADA study recommended)	(ADA study recommended)		
Parking				
Exterior Path of Travel	П		\square	

Removal of barriers to accessibility should be addressed from a liability standpoint in order to comply with federal law, but the barriers may or may not be building code violations. The Americans with Disabilities Act Accessibility Guidelines are part of the ADA federal civil rights law pertaining to the disabled and are not a construction code. State and local jurisdictions have adopted the ADA Guidelines or have adopted other standards for accessibility as part of their construction codes.

Reference Guide			
	Major Issues	Moderate Issues	Minor/No Issues
	(ADA study recommended)	(ADA study recommended)	
Parking	 Needs full reconstruction Excessive slopes over 3% require major re-grading No level locations to add required spaces 	 No or non-compliant curb cuts Moderate difficulty to add required accessible spaces Slopes close to compliant 	Painting of markings neededSignage height non-compliantSignage missing

Reference Guide			
	Major Issues	Moderate Issues	Minor/No Issues
	(ADA study recommended)	(ADA study recommended)	
Exterior Path of Travel	 - Large areas of sidewalks with excessive slopes - No ramp when needed - Ramps with excessive slopes 	 Ramps need rails Ramps need rail extensions Need significant # of lever handles All or most entrance door exterior maneuvering clearance areas with excessive slopes 	 One entrance door exterior maneuvering clearance area with excessive slope A few doorknobs instead of lever handles Non-compliant signage
Interior Path of Travel	- All or most interior doors appear less than 32" wide - Corridors less than 36" wide - No ramp when needed - Ramps with excessive slopes - Non-compliant treads/risers at means of egress stairways	- Single height drinking fountains - Drinking fountain too high or protrudes into accessible route - Ramps need rails - Ramps need rail extensions - Need significant # of lever handles - Non-compliant rail extensions at egress stairways - All/most door thresholds high	- One door threshold too high - A few doorknobs instead of lever handles - Non-compliant door pressures - Non-compliant signage - Switches not within reach range
Public Use Restrooms	No ADA RR on each accessible floor Restroom(s) too small Entire restroom(s) requires renovation Water closet clearance requires moving walls	 Interior doors appear less than 32" wide Missing or non-compliant grab bars Easily fixable clearance issues 	 Minor height adjustments required Non-compliant door pressures Missing a visual strobe (only required if audible fire alarm already present) Missing lavatory pipe wraps Signage not compliant
Elevators	No elevator present when required Elevator cab too small	 Panel control buttons not at compliant height No hands-free emergency communication system Elevator only has mechanical stops 	- Audible/visual signals at every floor may be lacking - Minor signage / Braille issues
Kitchens/Kitchenettes	Clear space for each appliance not present Clearance between opposing counters too narrow	 Sink and counter too high Sink knee and toe clearance not provided where required (built-in) Less than 50% of cabinetry within reach range 	 Dispensers not within reach range Switches not within reach range Missing sink pipe wraps if knee and toe clearance required

22. Purpose and Scope

Purpose

EMG was retained by the client to render an opinion as to the Property's current general physical condition on the day of the site visit.

Based on the observations, interviews and document review outlined below, this report identifies significant deferred maintenance issues, existing deficiencies, and material code violations of record, which affect the Property's use. Opinions are rendered as to its structural integrity, building system condition and the Property's overall condition. The report also notes building systems or components that have realized or exceeded their typical expected useful lives.

The physical condition of building systems and related components are typically defined as being in one of five condition ratings. For the purposes of this report, the following definitions are used:

Condition Ratings	
Excellent	New or very close to new; component or system typically has been installed within the past year, sound and performing its function. Eventual repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Good	Satisfactory as-is. Component or system is sound and performing its function, typically within the first third of its lifecycle. However, it may show minor signs of normal wear and tear. Repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Fair	Showing signs of wear and use but still satisfactory as-is, typically near the median of its estimated useful life. Component or system is performing adequately at this time but may exhibit some signs of wear, deferred maintenance, or evidence of previous repairs. Repair or replacement will be required due to the component or system's condition and/or its estimated remaining useful life.
Poor	Component or system is significantly aged, flawed, functioning intermittently or unreliably; displays obvious signs of deferred maintenance; shows evidence of previous repair or workmanship not in compliance with commonly accepted standards; has become obsolete; or exhibits an inherent deficiency. The present condition could contribute to or cause the deterioration of contiguous elements or systems. Either full component replacement is needed, or repairs are required to restore to good condition, prevent premature failure, and/or prolong useful life.
Failed	Component or system has ceased functioning or performing as intended. Replacement, repair, or other significant corrective action is recommended or required.
Not Applicable	Assigning a condition does not apply or make logical sense, most commonly due to the item in question not being present.

Scope

The standard scope of the Facility Condition Assessment includes the following:

- Visit the Property to evaluate the general condition of the building and site improvements, review available construction documents in order to familiarize ourselves with, and be able to comment on, the in-place construction systems, life safety, mechanical, electrical, and plumbing systems, and the general built environment.
- Identify those components that are exhibiting deferred maintenance issues and provide cost estimates for Immediate Costs and Replacement Reserves based on observed conditions, maintenance history and industry standard useful life estimates. This will include the review of documented capital improvements completed within the last five-year period and work currently contracted for, if applicable.
- Provide a full description of the Property with descriptions of in-place systems and commentary on observed conditions.
- Provide a high-level categorical general statement regarding the subject Property's compliance to Title III of the Americans
 with Disabilities Act. This will not constitute a full ADA survey, but will help identify exposure to issues and the need for
 further review.
- Obtain background and historical information about the facility from a building engineer, property manager, maintenance staff, or other knowledgeable source. The preferred methodology is to have the client representative or building occupant complete a Pre-Survey Questionnaire (PSQ) in advance of the site visit. Common alternatives include a verbal interview just prior to or during the walk-through portion of the assessment.
- Review maintenance records and procedures with the in-place maintenance personnel.
- Observe a representative sample of the interior spaces/units, including vacant spaces/units, to gain a clear understanding
 of the property's overall condition. Other areas to be observed include the exterior of the property, the roofs, interior
 common areas, and the significant mechanical, electrical and elevator equipment rooms.
- Provide recommendations for additional studies, if required, with related budgetary information.
- Provide an Executive Summary at the beginning of this report, which highlights key findings and includes a Facility Condition Index as a basis for comparing the relative conditions of the buildings within the portfolio.



23. Opinions of Probable Costs

Cost estimates are attached throughout this report, with the Replacement Reserves in the appendix.

These estimates are based on Invoice or Bid Document/s provided either by the Owner/facility and construction costs developed by construction resources such as *R.S. Means, CBRE Whitestone*, and *Marshall & Swift*, EMG's experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions.

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs most probably will vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing or bundling of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, use of subcontractors, and whether competitive pricing is solicited, etc. Certain opinions of probable costs cannot be developed within the scope of this guide without further study. Opinions of probable cost for further study should be included in the FCA.

Methodology

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, EMG opines as to when a system or component will most probably necessitate replacement. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its *effective age*, whether explicitly or implicitly stated. Projections of Remaining Useful Life (RUL) are based primarily on age and condition with the presumption of continued use and maintenance of the Property similar to the observed and reported past use and maintenance practices, in conjunction with the professional judgment of EMG's assessors. Significant changes in occupants and/or usage may affect the service life of some systems or components.

Where quantities could not be or were not derived from an actual construction document take-off or facility walk-through, and/or where systemic costs are more applicable or provide more intrinsic value, budgetary square foot and gross square foot costs are used. Estimated costs are based on professional judgment and the probable or actual extent of the observed defect, inclusive of the cost to design, procure, construct and manage the corrections.

Definitions

Immediate Needs

Immediate Needs are line items that require immediate action as a result of: (1) material existing or potential unsafe conditions, (2) failed or imminent failure of mission critical building systems or components, or (3) conditions that, if not addressed, have the potential to result in, or contribute to, critical element or system failure within one year or will most probably result in a significant escalation of its remedial cost.

For database and reporting purposes the line items with RUL=0, and commonly associated with *Safety* or *Performance/Integrity* Plan Types, are considered Immediate Needs.

Replacement Reserves

Cost line items traditionally called Replacement Reserves (equivalently referred to as Lifecycle/Renewals) are for recurring probable renewals or expenditures, which are not classified as operation or maintenance expenses. The replacement reserves should be budgeted for in advance on an annual basis. Replacement Reserves are reasonably predictable both in terms of frequency and cost. However, Replacement Reserves may also include components or systems that have an indeterminable life but, nonetheless, have a potential for failure within an estimated time period.



Replacement Reserves generally exclude systems or components that are estimated to expire after the reserve term and are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that are not deemed to have a material effect on the use of the Property are also excluded. Costs that are caused by acts of God, accidents, or other occurrences that are typically covered by insurance, rather than reserved for, are also excluded.

Replacement costs are solicited from ownership/property management, EMG's discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by the ownership's or property management's maintenance staff are also considered.

EMG's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the assessment period. The assessment period is defined as the effective age plus the reserve term. Additional information concerning system's or component's respective replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Replacement Reserves Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined as Immediate Needs.

For the purposes of 'bucketizing' the System Expenditure Forecasts in this report, the Replacement Reserves have been subdivided and grouped as follows: Short Term (years 1-3), Near Term (years 4-5), Medium Term (years 6-10), and Long Term (years 11-20).

Key Findings

In an effort to highlight the most significant cost items and not be overwhelmed by the Replacement Reserves report in its totality, a subsection of Key Findings is included within the Executive Summary section of this report. Key Findings typically include repairs or replacements of deficient items within the first five-year window, as well as the most significant high-dollar line items that fall anywhere within the ten-year term. Note that while there is some subjectivity associated with identifying the Key Findings, the Immediate Needs are always included as a subset.

Exceedingly Aged

A fairly common scenario encountered during the assessment process, and a frequent source of debate, occurs when classifying and describing "very old" systems or components that are still functioning adequately and do not appear nor were reported to be in any way deficient. To help provide some additional intelligence on these items, such components will be tagged in the database as Exceedingly Aged. This designation will be reserved for mechanical or electrical systems or components that have aged well beyond their industry standard lifecycles, typically at least 15 years beyond and/or twice their Estimated Useful Life (EUL). In tandem with this designation, these items will be assigned a Remaining Useful Life (RUL) not less than two years but not greater than 1/3 of their standard EUL. As such the recommended replacement time for these components will reside outside the typical Short-Term window but will not be pushed 'irresponsibly' (too far) into the future.



24. Certification

HMC Architects (the Client) retained EMG to perform this Facility Condition Assessment in connection with its Facility Master Planning effort for the Jurupa Unified School District at Indian Hills Elementary School, 7750 Linares Avenue, Jurupa Valley, California 92509, the "Property". It is our understanding that the primary interest of the Client is to locate and evaluate materials and building system defects that might significantly affect the value of the property and to determine if the present Property has conditions that will have a significant impact on its continued operations.

The conclusions and recommendations presented in this report are based on the brief review of the plans and records made available to our Project Manager during the site visit, interviews of available property management personnel and maintenance contractors familiar with the Property, appropriate inquiry of municipal authorities, our Project Manager's walk-through observations during the site visit, and our experience with similar properties.

No testing, exploratory probing, dismantling or operating of equipment or in-depth studies were performed unless specifically required under the *Purpose and Scope* section of this report. This assessment did not include engineering calculations to determine the adequacy of the Property's original design or existing systems. Although walk-through observations were performed, not all areas may have been observed (see Section 1 for specific details). There may be defects in the Property, which were in areas not observed or readily accessible, may not have been visible, or were not disclosed by management personnel when questioned. The report describes property conditions at the time that the observations and research were conducted.

This report has been prepared on behalf of and exclusively for the use of the Client for the purpose stated within the *Purpose and Scope* section of this report. The report, or any excerpt thereof, shall not be used by any party other than the Client or for any other purpose than that specifically stated in our agreement or within the *Purpose and Scope* section of this report without the express written consent of EMG.

Any reuse or distribution of this report without such consent shall be at the Client and the recipient's sole risk, without liability to EMG.

Prepared by: Tony Worthy,

Project Manager

Reviewed by:

Kathleen Sullivan Technical Report Reviewer for Mark Surdam

Program Manager

msurdam@emgcorp.com 800.733.0660 x6251

Kathleen Sulleran

25. Appendices

Appendix A: Photographic Record

Appendix B: Site Plan

Appendix C: Pre-Survey Questionnaire

Appendix D: Component Condition Report

Appendix E: Replacement Reserves

Appendix F: Equipment Inventory List

Appendix A: Photographic Record



#1 FRONT ELEVATION



#2 LEFT ELEVATION



#3 REAR ELEVATION

#5



RIGHT ELEVATION

#4



BUILDING MOUNTED PROPERTY SIGNAGE



#6 EXTERIOR METAL DOOR, EXTERIOR METAL WINDOW



#7 SINGLE-PLY TPO/PVC ROOFING



#8 METAL ROOFING





#9 ASPHALT SHINGLE ROOFING



MODIFIED BITUMINOUS ROOFING, PORTABLE BUILDINGS

#10







#13 CLASSROOM



#14 HALLWAY



#15 MULTI-PURPOSE ROOM



#16 RESTROOM



#17 WATER HEATER



#18 TANKLESS TOILET



#19 VITREOUS CHINA URINAL



#20 VITREOUS CHINA SINK



#21 FLOOR SERVICE SINK



#22 ENAMELED STEEL SINK



#23 ROOFTOP PACKAGE UNIT



#24 WALL MOUNT HEAT PUMP



#25 ROOFTOP EXHAUST FAN



#26 SWITCHBOARD

#28



#27 OUTDOOR ELECTRICAL PANEL



INDOOR ELECTRICAL PANEL



#30 INTERIOR LIGHTING SYSTEM



#31 EXTERIOR BUILDING LIGHT



#32 SITE POLE LIGHT FIXTURE, EXTERIOR CONCRETE STAIR



#33 FIRE CONTROL PANEL



#34 EXIT SIGN



#35 FIRE EXTINGUISHER



#36 FIRE PULL STATION



#37 2-DOOR FREEZER



#38 1-DOOR REFRIGERATOR



#39 GARBAGE DISPOSAL



#40 EXTERIOR RAMP



#41 SITE IRRIGATION SYSTEM



#42 METAL CANOPY STRUCTURE



#43 KINDERGARTEN PLAYGROUND



#44 SITE METAL TUBE FENCING



#45 SITE METAL CHAIN LINK FENCING



PEELING AND CRACKING EXTERIOR WOOD FACADE



#47 PLAYGROUND



#48 PARKING LOT

#46

EMG PROJECT NO.: 139069.19R000-007.354

Appendix B: Site Plan

Site Plan



SOURCE:

Google Earth



Appendix C: Pre-Survey Questionnaire



This questionnaire must be completed by the property owner, the owner's designated representative, or someone knowledgeable about the subject property. If the form is not completed, EMG's Project Manager will require *additional time* during the on-site visit with such a knowledgeable person in order to complete the questionnaire. During the site visit, EMG's Field Observer may ask for details associated with selected questions. This questionnaire will be utilized as an exhibit in EMG's final report.

NAME OF INSTITUTION: JURUPA UNIFIED SCHOOL DISTRICT

Name of School/Facility: Indian Hills ES

No. of Buildings: (1) bldg.. - 4 sections;

(17) portables

Name of person completing questionnaire: Dana Toland/ Pablo Ponce

Length of Association With the Property: 3yrs./ 19 yrs. Phone Number: 909 758-6447

SITE INFORMATION								
Year of Construction: 1987	Built:	Renovated:	Historical: N					
No. of Stories: single		Floor(s)						
Total Site Area: 10.3		Acres						
Total Building Area: 44,594		Sq. ft.						

Building Replacement Value: \$ UNK

INSPECTIONS	DATE OF LAST REPLACEMENT	DATE OF LAST INSPECTION	LIST OF ANY OUTSTANDING REPAIRS
1. Elevators	None		
2. HVAC	2002	PM 2019	
3. Plumbing System/Fixtures	Original		
4. Electrical System/Lighting	2016		Lighting LED, transformers
Life-Safety/Fire	2010	2019	Main Panel upgrade only
6. Roofs	Original		

KEY QUESTIONS	RESPONSE
Major Capital Improvements in Last 3 yrs.	Repaved parkin lots; paint ext. (9) portables; admin. casework, re-carpeted all rooms
Planned Capital Expenditure For Next Year?	Paint exterior? New playground structure and matting
Age of the Roof?	1987, re-shingled sections 2005
What bldg. Systems Are Responsibilities of Tenants? (HVAC/Roof/Interior/Exterior/Paving)	NA

	QUESTION	Υ	N	UNK	NA	COMMENTS				
	ZONING, BUILDING, DESIGN AND LIFE SAFETY ISSUES									
1	Are there any unresolved building, fire, or zoning code issues?		N							
2	Is there any pending litigation concerning the property?		N							
3	Are there any other significant issues/hazards with the property?		N							



	QUESTION	Υ	N	UNK	NA	COMMENTS
	ZONING, BU	JILDIN	G, DE	SIGN A	ND LIFE	E SAFETY ISSUES
	Are there any unresolved					
4	construction defects at the property?		N			
5	Has any part of the property ever contained visible suspect mold growth?	Υ				P21, Repair/remediation made
6	Have there been indoor air quality or mold related complaints from occupants?	Y				Test came back clear
7	Is there a mold Operations and Maintenance Plan?		N			
8	Are there any Asbestos Containing Building Materials in the building?	Υ				
9	Is there an Asbestos Operations and Maintenance Plan? (AHERA?)	Υ				
10	Are there any recalled fire sprinkler heads (Star, GEM, Central, and Omega)?			UN		
			GEI	NERAL	SITE	
11	Are there any problems with erosion, storm water drainage or areas of paving that do not drain?		N			
12	Are there any problems with the landscape irrigation systems?	Υ				Coverage issues
		В	JILDIN	NG STR	UCTUF	RE
13	Are there any problems with foundations or structures?		N			
14	Is there any water infiltration in basements or crawl spaces?		N			
15	Has a termite/wood boring insect inspection been performed within the last year?		N			
16	Are there any wall, or window leaks?		N			



	QUESTION	Υ	N	UNK	NA	COMMENTS
		E	BUILD	ING EN	VELO	PE
17	Are there any roof leaks?	Υ				Portables only P21, P20, P27, P31
18	Is the roofing covered by a warranty or bond?		N			
19	Are there any poorly insulated areas?		N			
20	Is Fire Retardant Treated (FRT) plywood used?		N			
21	Is exterior insulation and finish system (EIFS) or a synthetic stucco finish used?		N			
		BUILD	ING H	IVAC &	ELEC	TRICAL
22	Do any parts of the building have inadequate heating? Comment on location using room numbers		N			
23	Do any parts of the building have inadequate cooling? Comment on location using room numbers		N			
24	Does any part of the electrical system use aluminum wiring?		N			
25	Are there any problems with the utilities, such as inadequate capacities?		N			
			P	LUMBII	NG	
26	Is the property served by private water well?		N			
27	Is the property served by a private septic system or other waste treatment systems?		N			
28	Does the sanitary sewer system back-up? If so, provide locations in comments		N			
29	Is polybutylene piping used?		N			
30	Is galvanized piping used?		N			
31	Are there any plumbing leaks or water pressure problems?		N			



	QUESTION	Υ	N	UNK	NA	COMMENTS
				ADA		
32	Has the management previously completed an ADA review?		N			
33	Have any ADA improvements been made to the property?		N			
34	Does a Barrier Removal Plan exist for the property?		N			
35	Has the Barrier Removal Plan been approved by an arms-length third party?		N			
36	Has building ownership or management received any ADA related complaints?		N			
37	Does elevator equipment require upgrades to meet ADA standards?				NA	No elevator
	ADDITIONAL ISSUES O	R CO	NCER	NS TH	AT EM	G SHOULD KNOW ABOUT?
1 F	Playground structure is original met	al stru	uctures	3		
2						
3						
	ITEM	S PR	OVIDE	D TO E	EMG A	UDITORS
			YES	NO	NA	ADDITIONAL COMMENTS
Acces	ss to All Mechanical Spaces		Χ			
Acces	ss to Roof/Attic Space		Χ			
	ss to Building As-Built Drawings		Χ			
-	plan with bldg., roads, parking and features		Χ□			
	act Details for Mech, Elevator, Roo Contractors:	f,		Χ□		
List o	f Commercial Tenants in the erty				Χ□	
	ous reports pertaining to the physical tion of property.	cal		Χ□		
	survey and status of improvements mented.	8		Χ□		



ITEMS PROVIDED TO EMG AUDITORS											
	YES	NO	NA	ADDITIONAL COMMENTS							
Current / pending litigation related to property condition.		Χ□									
Any brochures or marketing information.			Χ□								
Dana Toland/ Pablo Ponce				9/12/19							
Signature of person interviewed or completing form				Date							

Appendix D: Component Condition Report

Component Condition Report

Indian Hills Elementary School / Main Building

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						
B2011	Main Building Exterior	Fair	Exterior Wall, Stucco, 1-2 Stories	10,580 SF	18	1434290
B2011	Main Building Exterior	Poor	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	2,460 SF	1	1434268
B2011	Main Building Exterior	Fair	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories	2,460 SF	3	1434098
B2011	Main Building Exterior	Fair	Exterior Wall, Stucco, 1-2 Stories, Prep & Fog Coat or Paint	10,580 SF	2	1434109
B2021	Main Building Exterior	Fair	Window, 24 SF	149	5	1434309
B2032	Main Building Exterior	Fair	Exterior Door, Steel	31	8	1434229
B2034	Main Building Kitchen	Fair	Overhead Door, 56 SF	1	21	1434154
Roofing						
B3011	Main Building Roof	Fair	Roof, Asphalt Shingle 30-Year	17,270 SF	16	1434224
B3011	Main Building Roof	Fair	Roof, Single-Ply TPO/PVC Membrane	18,710 SF	3	1434208
Interiors						
C1012	Main Building	Fair	Movable Partitions, Fabric Office 6' Height	30 LF	3	1434249
C1017	Main Building	Fair	Interior Window, 24 SF	80	8	1434292
C1021	Main Building	Fair	Interior Aluminum-Framed Partially-Glazed Door, Aluminum-Framed Partially-Glazed	20	8	1434121
C1021	Main Building	Fair	Interior Door, Wood Solid-Core	17	8	1434160
C1031	Main Building Restroom	Fair	Toilet Partitions, Metal	17	4	1434301
C3012	Main Building	Fair	Interior Wall Finish, Wood Paneling	1,722 SF	4	1434126
C3012	Main Building	Fair	Interior Wall Finish, Ceramic Tile	3,445 SF	8	1440641
C3012	Main Building	Fair	Interior Wall Finish, Wallpaper	37,892 SF	2	1434139
C3024	Main Building	Fair	Interior Floor Finish, Vinyl Tile (VCT)	6,602 SF	4	1434202
C3024	Main Building Kitchen	Fair	Interior Floor Finish, Quarry Tile	281 SF	18	1434247
C3024	Main Building	Fair	Interior Floor Finish, Composite Floor Tile	2,871 SF	12	1434142
C3024	Main Building	Fair	Interior Floor Finish, Linoleum	861 SF	3	1434248
C3024	Main Building	Fair	Interior Floor Finish, Ceramic Tile	861 SF	8	1434270
C3025	Main Building	Fair	Interior Floor Finish, Carpet Commercial Tile	17,224 SF	6	1434165
C3031	Main Building	Fair	Interior Ceiling Finish, Wood	3,732 SF	4	1434168
C3031	Main Building	Fair	Interior Ceiling Finish, any flat surface, Prep & Paint	1,148 SF	4	1434250
C3032	Main Building	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	23,252 SF	4	1434304
Plumbing						
D2011	Main Building Restroom	Fair	Toilet, Commercial Water Closet	18	6	1434221
D2012	Main Building Restroom	Fair	Urinal, Standard	5	6	1434192
D2014	Main Building	Fair	Sink/Lavatory, Vanity Top, Enameled Steel	8	4	1434213
D2014	Main Building	Fair	Service Sink, Floor	1	3	1434173
D2014	Main Building Restroom	Fair	Sink/Lavatory, Wall-Hung, Vitreous China	13	6	1434112
D2014	Main Building Kitchen	Fair	Commercial Kitchen Sink, Stainless Steel, 2-Bowl	1	4	1434161

Indian Hills Elementary School / Main Building

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D2014	Main Building Exterior	Fair	Service Sink, Floor	1	3	1434215
D2018	Main Building Exterior	Fair	Drinking Fountain, Outside/Site Style	2	5	1434164
D2023	Main Building Exterior Utility Closet	Fair	Water Heater, 6 GAL	1	2	1434148
D2023	Main Building	Fair	Water Heater, 50 GAL	1	3	1434283
D2023	Main Building Supply Closet	Fair	Water Heater, 10 GAL	1	3	1434170
D2029	Main Building	Fair	Plumbing System, Supply & Sanitary, Medium Density (excl fixtures)	28,706 SF	8	1479693
Fire Suppress	sion					
D4019	Main Building	NA	Sprinkler System, Full Retrofit, Medium Density/Complexity, Renovate	28,706 SF	4	1441146
D4031	Main Building	Fair	Fire Extinguisher, Type ABC, up to 20 LB	25	6	1434284
HVAC						
D3041	Main Building	Fair	HVAC System Ductwork, High Density	1,295 SF	5	1434228
D3042	Main Building Roof	Fair	Exhaust Fan, 75 CFM	1	11	1434227
D3042	Main Building Roof	Fair	Exhaust Fan, 75 CFM	1	11	1434156
D3042	Main Building Roof	Fair	Exhaust Fan, 75 CFM	1	11	1434264
D3042	Main Building Roof	Fair	Exhaust Fan, 75 CFM	1	11	1434188
D3042	Main Building Roof	Fair	Exhaust Fan, 75 CFM	1	11	1434246
D3042	Main Building Roof	Fair	Exhaust Fan, 75 CFM	1	11	1434169
D3042	Main Building Roof	Fair	Exhaust Fan, 75 CFM	1	11	1434269
D3042	Main Building Roof	Fair	Exhaust Fan, 75 CFM	1	11	1434275
D3042	Main Building Roof	Fair	Exhaust Fan, 75 CFM	1	11	1434230
D3042	Main Building Roof	Fair	Exhaust Fan, 75 CFM	1	11	1434253
D3052	Main Building Roof	Poor	Packaged Unit (RTU), 7.5 TON	1	1	1434104
D3052	Main Building Roof	Fair	Packaged Unit (RTU), 4 TON [RM-17]	1	13	1434295
D3052	Main Building Roof	Poor	Packaged Unit (RTU), 7.5 TON	1	1	1434117
D3052	Main Building Roof	Fair	Packaged Unit (RTU), 4 TON [ACT RM 15]	1	13	1434167
D3052	Main Building Roof	Fair	Packaged Unit (RTU), 3 TON [RSP]	1	13	1434258
D3052	Main Building Roof	Poor	Packaged Unit (RTU), 12.5 TON	1	1	1434162
D3052	Main Building Roof	Fair	Packaged Unit (RTU), 4 TON [RM-14]	1	13	1434286
D3052	Main Building Roof	Fair	Packaged Unit (RTU), 4 TON [RM-10]	1	13	1434176
D3052	Main Building Roof	Fair	Packaged Unit (RTU), 3 TON [HALL 1-5]	1	13	1434254
D3052	Main Building Roof	Fair	Packaged Unit (RTU), 4 TON [RM-6]	1	13	1434155
D3052	Main Building Roof	Fair	Packaged Unit (RTU), 3 TON [HALL 10-13]	1	13	1434239
D3052	Main Building Roof	Poor	Packaged Unit (RTU), 7.5 TON	1	1	1434153
D3052	Main Building Roof	Fair	Packaged Unit (RTU), 4 TON [RM-3]	1	13	1434195
D3052	Main Building Roof	Fair	Packaged Unit (RTU), 4 TON [HALL 14-17]	1	13	1434218
D3052	Main Building Roof	Fair	Packaged Unit (RTU), 4 TON [RM-8]	1	13	1434189
D3052	Main Building Roof	Fair	Packaged Unit (RTU), 4 TON [RM-12]	1	13	1434211
D3052	Main Building Roof	Fair	Packaged Unit (RTU), 4 TON [RM-7]	1	13	1434099

Indian Hills Elementary School / Main Building

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D3052	Main Building Roof	Poor	Packaged Unit (RTU), 7.5 TON	1	1	1434127
D3052	Main Building Roof	Fair	Packaged Unit (RTU), 4 TON [RM-5]	1	13	1434308
D3052	Main Building Roof	Poor	Packaged Unit (RTU), 10 TON	1	1	1434240
D3052	Main Building Roof	Fair	Packaged Unit (RTU), 3 TON [HALL 6-9]	1	13	1434303
D3052	Main Building Roof	Poor	Packaged Unit (RTU), 7.5 TON	1	1	1434271
D3052	Main Building Roof	Poor	Packaged Unit (RTU), 7.5 TON	1	1	1434241
D3052	Main Building Roof	Poor	Packaged Unit (RTU), 7.5 TON	1	1	1434252
D3052	Main Building Roof	Fair	Packaged Unit (RTU), 4 TON [RM-4]	1	13	1434314
D3052	Main Building Roof	Fair	Packaged Unit (RTU), 4 TON [RM-9]	1	13	1434209
D3052	Main Building Roof	Poor	Packaged Unit (RTU), 7.5 TON	1	1	1434251
Electrical						
D5012	Main Building	Fair	Main Distribution Panel-225 AMP, 225 AMP [HB]	1	4	1434135
D5012	Main Building Roof	Fair	Secondary Transformer, 45 kVA [T1/PNL LA]	1	27	1434274
D5012	Main Building Roof	Fair	Secondary Transformer, 45 kVA [T2/PNL LB]	1	27	1434134
D5012	Main Building Electrical room	Fair	Building/Main Switchboard, 600 AMP	1	8	1434266
D5012	Main Building	Fair	Main Distribution Panel-225 AMP, 225 AMP [HP]	1	4	1434105
D5012	Main Building Roof	Fair	Secondary Transformer, 45 kVA [T3/PNL LC]	1	27	1434143
D5019	Main Building	Fair	Electrical Wiring & Switches, High Density/Complexity	28,706 SF	8	1434256
D5022	Main Building Exterior	Fair	Light Fixture, 250 WATT	10	16	1434120
D5022	Main Building Exterior	Fair	Light Fixture, 100 WATT	15	17	1434141
D5029	Main Building	Fair	Lighting System, Interior, High Density & Standard Fixtures	28,706 SF	17	1434222
D5092	Main Building	Fair	Exit Sign Light Fixture, LED	30	3	1434125
D5092	Main Building	Fair	Emergency Light, 2-Head w/ Battery	12	3	1434174
Fire Alarm &	Comm					
D5037	Main Building Electrical room	Fair	Fire Alarm Control Panel, Addressable	1	6	1434123
Equipment/S	pecial					
E1093	Main Building Kitchen	Fair	Commercial Kitchen, Garbage Disposal, 1 to 3 HP	1	13	1434194
E1093	Main Building Kitchen	Fair	Commercial Kitchen, Refrigerator, 1-Door Reach-In	1	2	1434312
E1093	Main Building Kitchen	Fair	Commercial Kitchen, Food Warmer	1	4	1434245
E1093	Main Building Kitchen	Fair	Commercial Kitchen, Dairy Cooler/Wells	1	6	1434282
E1093	Main Building Kitchen	Fair	Commercial Kitchen, Food Warmer	1	4	1434115
E1093	Main Building Kitchen	Fair	Commercial Kitchen, Food Warmer	1	4	1434151
E1093	Main Building Kitchen	Fair	Commercial Kitchen, Freezer, 2-Door Reach-In	1	2	1434140
E2012	Main Building	Fair	Kitchen Cabinetry, Stock Hardwood	520 LF	4	1434279
Pavement						
G2035	Main Building	Fair	Exterior Stairs & Ramps, Concrete (per LF of Nosing)	32 LF	18	1434166

Undian dheills E	lementantiSnhool / Portable Classroom #18	Condition	Asset/Component/Repair	Quantity	RUL	ID
UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						
B2011	Portable Building 18 Exterior	Fair	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories	1,278 SF	4	1434206
B2011	Portable Building 18 Exterior	Excellent	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	1,278 SF	10	1434311
B2021	Portable Building 18 Exterior	Fair	Single-Pane Exterior Window, 24 SF	2	2	1434181
B2032	Portable Building 18 Exterior	Fair	Exterior Door, Steel	1	8	1434129
Roofing						
B3011	Portable Building 18 Roof	Fair	Roof, Modified Bituminous	1,128 SF	3	1434185
Interiors						
C1011	Portable Building 18	Fair	Interior Fiberboard Panel Wall Construction, Fiberboard Panel	1,170 SF	18	1434183
C3025	Portable Building 18	Fair	Interior Floor Finish, Carpet Commercial Tile	960 SF	6	1434288
C3032	Portable Building 18	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	960 SF	3	1434310
Fire Suppressi	ion					
D4019	Portable Buildings 18	NA	Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	960 SF	4	1441149
D4031	Portable Building 18	Fair	Fire Extinguisher, Type ABC, up to 20 LB	1	6	1434210
HVAC						
D3052	Portable Building 18 Exterior	Poor	Heat Pump, Wall-Mounted, 3.5 to 4 Ton [#18]	1	1	1434262
Electrical						
D5019	Portable Building 18	Fair	Full Electrical System Upgrade, Low Density/Complexity	960 SF	8	1479697
D5022	Portable Building 18 Exterior	Fair	Light Fixture, 150 WATT	1	17	1434214
D5029	Portable Building 18	Fair	Lighting System, Interior, Medium Density & Standard Fixtures	960 SF	17	1434287
Fire Alarm & C	omm					
D5037	Portable Building 18	Fair	Fire Alarm System, Standard Addressable, Install	960 SF	4	1479699
Pavement						
G2035	Portable Building 18 Exterior	Fair	Exterior Ramps, Concrete (per LF of Nosing)	20 LF	37	1434193
Indian Hills E	lementary School / Portable Classroom #19					
UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						
B2011	Portable Building 19 Exterior	Fair	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories	1,278 SF	4	1445539
B2011	Portable Building 19 Exterior	Excellent	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	1,278 SF	10	1445541
B2021	Portable Building 19 Exterior	Fair	Single-Pane Exterior Window, 24 SF	2	2	1445545
B2032	Portable Building 19 Exterior	Fair	Exterior Door, Steel	1	8	1445542
Roofing						
B3011	Portable Building 19 Roof	Fair	Roof, Modified Bituminous	1,128 SF	3	1445546
Interiors						
C1011	Portable Building 19	Fair	Interior Fiberboard Panel Wall Construction, Fiberboard Panel	1,170 SF	18	1445536
C3025	Portable Building 19	Fair	Interior Floor Finish, Carpet Commercial Tile	960 SF	6	1445537

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
C3032	Portable Building 19	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	960 SF	3	1445535
Fire Suppression	on					
D4019	Portable Buildings 19	NA	Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	960 SF	4	1445547
D4031	Portable Building 19	Fair	Fire Extinguisher, Type ABC, up to 20 LB	1	6	1445534
HVAC						
D3052	Portable Building 19 Exterior	Poor	Heat Pump, Wall-Mounted, 3.5 to 4 Ton [#19]	1	1	1434180
Electrical						
D5019	Portable Building 19	Fair	Full Electrical System Upgrade, Low Density/Complexity	960 SF	8	1479700
D5022	Portable Building 19 Exterior	Fair	Light Fixture, 150 WATT	1	17	1445540
D5029	Portable Building 19	Fair	Lighting System, Interior, Medium Density & Standard Fixtures	960 SF	17	1445538
Fire Alarm & Co	omm					
D5037	Portable Building 19	Fair	Fire Alarm System, Standard Addressable, Install	960 SF	4	1479701
Pavement						
G2035	Portable Building 19 Exterior	Fair	Exterior Ramps, Concrete (per LF of Nosing)	20 LF	37	1445544

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						
B2011	Portable Building 20 Exterior	Fair	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories	1,278 SF	4	1445553
B2011	Portable Building 20 Exterior	Excellent	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	1,278 SF	10	1445555
B2021	Portable Building 20 Exterior	Fair	Single-Pane Exterior Window, 24 SF	2	2	1445559
B2032	Portable Building 20 Exterior	Fair	Exterior Door, Steel	1	8	1445556
Roofing						
B3011	Portable Building 20 Roof	Poor	Roof, Modified Bituminous	1,128 SF	1	1445560
Interiors						
C1011	Portable Building 20	Fair	Interior Fiberboard Panel Wall Construction, Fiberboard Panel	1,170 SF	18	1445550
C3025	Portable Building 20	Fair	Interior Floor Finish, Carpet Commercial Tile	960 SF	6	1445551
C3032	Portable Building 20	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	960 SF	3	1445549
Fire Suppressio	on .					
D4019	Portable Buildings 20	NA	Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	960 SF	4	1445561
D4031	Portable Building 20	Fair	Fire Extinguisher, Type ABC, up to 20 LB	1	6	1445548
HVAC						
D3052	Portable Building 20 Exterior	Poor	Heat Pump, Wall-Mounted, 3.5 to 4 Ton [#20]	1	1	1445557
Electrical						
D5019	Portable Building 20	Fair	Full Electrical System Upgrade, Low Density/Complexity	960 SF	8	1479702
D5022	Portable Building 20 Exterior	Fair	Light Fixture, 150 WATT	1	17	1445554
D5029	Portable Building 20	Fair	Lighting System, Interior, Medium Density & Standard Fixtures	960 SF	17	1445552
Fire Alarm & Co	omm					

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D5037	Portable Building 20	Fair	Fire Alarm System, Standard Addressable, Install	960 SF	4	1479703
Pavement						
G2035	Portable Building 20 Exterior	Fair	Exterior Ramps, Concrete (per LF of Nosing)	20 LF	37	1445558

Indian Hills Elementary School / Portable Classroom #21

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						
B2011	Portable Building 21 Exterior	Fair	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories	1,278 SF	4	1445567
B2011	Portable Building 21 Exterior	Excellent	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	1,278 SF	10	1445569
B2021	Portable Building 21 Exterior	Fair	Single-Pane Exterior Window, 24 SF	2	2	1445573
B2032	Portable Building 21 Exterior	Fair	Exterior Door, Steel	1	8	1445570
Roofing						
B3011	Portable Building 21 Roof	Poor	Roof, Modified Bituminous	1,128 SF	1	1445574
Interiors						
C1011	Portable Building 21	Fair	Interior Fiberboard Panel Wall Construction, Fiberboard Panel	1,170 SF	18	1445564
C3025	Portable Building 21	Fair	Interior Floor Finish, Carpet Commercial Tile	960 SF	6	1445565
C3032	Portable Building 21	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	960 SF	3	1445563
Fire Suppressi	on					
D4019	Portable Buildings 21	NA	Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	960 SF	4	1445575
D4031	Portable Building 21	Fair	Fire Extinguisher, Type ABC, up to 20 LB	1	6	1445562
HVAC						
D3052	Portable Building 21 Exterior	Poor	Heat Pump, Wall-Mounted, 3.5 to 4 Ton [#21]	1	1	1445571
Electrical						
D5019	Portable Building 21	Fair	Full Electrical System Upgrade, Low Density/Complexity	960 SF	8	1479704
D5022	Portable Building 21 Exterior	Fair	Light Fixture, 150 WATT	1	17	1445568
D5029	Portable Building 21	Fair	Lighting System, Interior, Medium Density & Standard Fixtures	960 SF	17	1445566
Fire Alarm & C	omm					
D5037	Portable Building 21	Fair	Fire Alarm System, Standard Addressable, Install	960 SF	4	1479705
Pavement						
G2035	Portable Building 21 Exterior	Fair	Exterior Ramps, Concrete (per LF of Nosing)	20 LF	37	1445572

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						
B2011	Portable Building 22 Exterior	Fair	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories	1,278 SF	4	1445581
B2011	Portable Building 22 Exterior	Excellent	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	1,278 SF	10	1445583
B2021	Portable Building 22 Exterior	Fair	Single-Pane Exterior Window, 24 SF	2	2	1445587
B2032	Portable Building 22 Exterior	Fair	Exterior Door, Steel	1	8	1445584

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Roofing						
B3011	Portable Building 22 Roof	Fair	Roof, Modified Bituminous	1,128 SF	3	1445588
Interiors						
C1011	Portable Building 22	Fair	Interior Fiberboard Panel Wall Construction, Fiberboard Panel	1,170 SF	18	1445578
C3025	Portable Building 22	Fair	Interior Floor Finish, Carpet Commercial Tile	960 SF	6	1445579
C3032	Portable Building 22	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	960 SF	3	1445577
Fire Suppressi	on					
D4019	Portable Buildings 22	NA	Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	960 SF	4	1445589
D4031	Portable Building 22	Fair	Fire Extinguisher, Type ABC, up to 20 LB	1	6	1445576
HVAC						
D3052	Portable Building 22 Exterior	Poor	Heat Pump, Wall-Mounted, 3.5 to 4 Ton [#22]	1	1	1445585
Electrical						
D5019	Portable Building 22	Fair	Full Electrical System Upgrade, Low Density/Complexity	960 SF	8	1479706
D5022	Portable Building 22 Exterior	Fair	Light Fixture, 150 WATT	1	17	1445582
D5029	Portable Building 22	Fair	Lighting System, Interior, Medium Density & Standard Fixtures	960 SF	17	1445580
Fire Alarm & C	omm					
D5037	Portable Building 22	Fair	Fire Alarm System, Standard Addressable, Install	960 SF	4	1479707
Pavement						
G2035	Portable Building 22 Exterior	Fair	Exterior Ramps, Concrete (per LF of Nosing)	20 LF	37	1445586

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						
B2011	Portable Building 23 Exterior	Excellent	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	1,278 SF	10	1445597
B2011	Portable Building 23 Exterior	Fair	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories	1,278 SF	4	1445595
B2021	Portable Building 23 Exterior	Fair	Single-Pane Exterior Window, 24 SF	2	2	1445601
B2032	Portable Building 23 Exterior	Fair	Exterior Door, Steel	1	8	1445598
Roofing						
B3011	Portable Building 23 Roof	Fair	Roof, Metal	1,128 SF	8	1434291
Interiors						
C1011	Portable Building 23	Fair	Interior Fiberboard Panel Wall Construction, Fiberboard Panel	1,170 SF	18	1445592
C3025	Portable Building 23	Fair	Interior Floor Finish, Carpet Commercial Tile	960 SF	6	1445593
C3032	Portable Building 23	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	960 SF	3	1445591
Fire Suppress	ion					
D4019	Portable Buildings 23	NA	Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	960 SF	4	1445603
D4031	Portable Building 23	Fair	Fire Extinguisher, Type ABC, up to 20 LB	1	6	1445590
HVAC						
D3052	Portable Building 23 Exterior	Poor	Heat Pump, Wall-Mounted, 3.5 to 4 Ton [#23]	1	1	1445599

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Electrical						
D5019	Portable Building 23	Fair	Full Electrical System Upgrade, Low Density/Complexity	960 SF	8	147970
5022	Portable Building 23 Exterior	Fair	Light Fixture, 150 WATT	1	17	144559
5029	Portable Building 23	Fair	Lighting System, Interior, Medium Density & Standard Fixtures	960 SF	17	144559
ire Alarm & C	omm					
5037	Portable Building 23	Fair	Fire Alarm System, Standard Addressable, Install	960 SF	4	147970
Pavement						
G2035	Portable Building 23 Exterior	Fair	Exterior Ramps, Concrete (per LF of Nosing)	20 LF	37	144560
		W0.4				
	lementary School / Portable Classroom #					
IF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
acade						
2011	Portable Building 24 Exterior	Excellent	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	1,278 SF	10	144561
2011	Portable Building 24 Exterior	Fair	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories	1,278 SF	4	144560
2021	Portable Building 24 Exterior	Fair	Single-Pane Exterior Window, 24 SF	2	2	144561
2032	Portable Building 24 Exterior	Fair	Exterior Door, Steel	1	8	144561
Roofing						
3011	Portable Building 24 Roof	Fair	Roof, Modified Bituminous	1,128 SF	3	144561
nteriors						
1011	Portable Building 24	Fair	Interior Fiberboard Panel Wall Construction, Fiberboard Panel	1,170 SF	18	144560
3025	Portable Building 24	Fair	Interior Floor Finish, Carpet Commercial Tile	960 SF	6	144560
3032	Portable Building 24	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	960 SF	3	144560
ire Suppressi	on					
4019	Portable Buildings 24	NA	Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	960 SF	4	144561
4031	Portable Building 24	Fair	Fire Extinguisher, Type ABC, up to 20 LB	1	6	144560
VAC						
3052	Portable Building 24 Exterior	Poor	Heat Pump, Wall-Mounted, 3.5 to 4 Ton [#24]	1	1	144561
lectrical						
5019	Portable Building 24	Fair	Full Electrical System Upgrade, Low Density/Complexity	960 SF	8	147971
5022	Portable Building 24 Exterior	Fair	Light Fixture, 150 WATT	1	17	144561
5029	Portable Building 24	Fair	Lighting System, Interior, Medium Density & Standard Fixtures	960 SF	17	144560
ire Alarm & C	omm					
5037	Portable Building 24	Fair	Fire Alarm System, Standard Addressable, Install	960 SF	4	14797
avement						
32035	Portable Building 24 Exterior	Fair	Exterior Ramps, Concrete (per LF of Nosing)	20 LF	37	14456

or code Eccation Condition Assertioniponent/Kepan Quantity Kot ID	UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
---	---------	----------	-----------	------------------------	----------	-----	----

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						
B2011	Portable Building 26 Exterior	Fair	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories	1,278 SF	4	1434219
B2011	Portable Building 26 Exterior	Excellent	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	1,278 SF	10	1434186
B2021	Portable Building 26 Exterior	Fair	Single-Pane Exterior Window, 24 SF	2	3	1434234
B2032	Portable Building 26 Exterior	Fair	Exterior Door, Steel	1	8	1434122
Roofing						
B3011	Portable Building 26 Roof	Fair	Roof, Modified Bituminous	1,128 SF	10	1434296
Interiors						
C1011	Portable Building 26	Fair	Interior Fiberboard Panel Wall Construction, Fiberboard Panel	1,170 SF	18	1434220
C3025	Portable Building 26	Fair	Interior Floor Finish, Carpet Commercial Tile	960 SF	6	1434101
C3032	Portable Building 26	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	960 SF	5	1434124
Fire Suppressi	ion					
D4019	Portable Building 26	NA	Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	960 SF	4	1441183
D4031	Portable Building 26	Fair	Fire Extinguisher, Wet Chemical/CO2	1	6	1434132
HVAC						
D3052	Portable Building 26	Poor	Heat Pump, Wall-Mounted, 3.5 to 4 Ton [#26]	1	1	1434190
Electrical						
D5019	Portable Building 26	Fair	Full Electrical System Upgrade, Low Density/Complexity	960 SF	8	1479712
D5022	Portable Building 26 Exterior	Fair	Light Fixture, 150 WATT	1	17	1434260
D5029	Portable Building 26	Fair	Lighting System, Interior, Medium Density & Standard Fixtures	960 SF	17	1434261
Fire Alarm & C	Comm					
D5037	Portable Building 26	Fair	Fire Alarm System, Standard Addressable, Install	960 SF	4	1479713
Pavement						
G2035	Portable Building 26 Exterior	Fair	Exterior Stairs & Ramps, Concrete (per LF of Nosing)	20 LF	18	1434244

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						
B2011	Portable Building 27 Exterior	Excellent	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	1,278 SF	10	1445636
B2011	Portable Building 27 Exterior	Fair	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories	1,278 SF	4	1445635
B2021	Portable Building 27 Exterior	Fair	Single-Pane Exterior Window, 24 SF	2	3	1445634
B2032	Portable Building 27 Exterior	Fair	Exterior Door, Steel	1	8	1445637
Roofing						
B3011	Portable Building 27	Poor	Roof, Modified Bituminous	1,128 SF	1	1479766
Interiors						
C1011	Portable Building 27	Fair	Interior Fiberboard Panel Wall Construction, Fiberboard Panel	1,170 SF	18	1445628
C3025	Portable Building 27	Fair	Interior Floor Finish, Carpet Commercial Tile	960 SF	6	1445629
C3032	Portable Building 27	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	960 SF	5	1445625

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Fire Suppress	ion					
D4019	Portable Building 27	NA	Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	960 SF	4	1445631
D4031	Portable Building 27	Fair	Fire Extinguisher, Type ABC, up to 20 LB	1	6	1445630
HVAC						
D3052	Portable Building 27 Exterior	Poor	Heat Pump, Wall-Mounted, 3.5 to 4 Ton [#27]	1	1	1434119
Electrical						
D5019	Portable Building 27	Fair	Full Electrical System Upgrade, Low Density/Complexity	960 SF	8	1479714
D5022	Portable Building 27 Exterior	Fair	Light Fixture, 150 WATT	1	17	1445633
D5029	Portable Building 27	Fair	Lighting System, Interior, Medium Density & Standard Fixtures	960 SF	17	1445627
Fire Alarm & C	omm					
D5037	Portable Building 27	Fair	Fire Alarm System, Standard Addressable, Install	960 SF	4	1479715
Pavement						
G2035	Portable Building 27 Exterior	Fair	Exterior Stairs & Ramps, Concrete (per LF of Nosing)	20 LF	18	1445632

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade						,
B2011	Portable Building 28 Exterior	Fair	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	1,278 SF	3	1434267
B2011	Portable Building 28 Exterior	Fair	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories	1,278 SF	13	1434307
B2021	Portable Building 28 Exterior	Fair	Single-Pane Exterior Window, 24 SF	2	13	1434128
B2032	Portable Building 28 Exterior	Fair	Exterior Door, Steel	1	21	1434263
Roofing						
B3011	Portable Building 28 Roof	Fair	Roof, Metal	1,128 SF	23	1434159
Interiors						
C1011	Portable Building 28	Fair	Interior Fiberboard Panel Wall Construction, Fiberboard Panel	1,170 SF	33	1434137
C3025	Portable Building 28	Fair	Interior Floor Finish, Carpet Commercial Standard	960 SF	6	1434302
C3032	Portable Building 28	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	960 SF	8	1434212
Fire Suppression	on					
D4031	Portable Building 28	Fair	Fire Extinguisher, Type ABC, up to 20 LB	1	6	1434102
HVAC						
D3052	Portable Building 28 Exterior	Poor	Heat Pump, Wall-Mounted, 3.5 to 4 Ton [#28]	1	1	1434277
Electrical						
D5019	Portable Building 28	Fair	Full Electrical System Upgrade, Low Density/Complexity	960 SF	23	1479716
D5022	Portable Building 28 Exterior	Fair	Light Fixture, 150 WATT	1	3	1434152
D5029	Portable Building 28	Fair	Lighting System, Interior, Medium Density & Standard Fixtures	960 SF	17	1434172
Fire Alarm & Co	omm					
D5037	Portable Building 28	Fair	Fire Alarm System, Standard Addressable, Install	960 SF	4	1479717
Pavement						

Indian Hills Elementary School / Portable Classroom #28 **UF Code** Location Condition Asset/Component/Repair Quantity RUL ID 38 G2035 Portable Building 28 Exterior Fair Exterior Ramps, Concrete (per LF of Nosing) 20 LF 1434238 Indian Hills Elementary School / Portable Classroom #29 RUL ID **UF Code** Condition Location Asset/Component/Repair Quantity Facade B2011 Portable Building 29 Exterior Fair Exterior Wall, Wood Shakes/Shingles, 1-2 Stories 1,278 SF 13 1445646 1,278 SF B2011 Portable Building 29 Exterior Fair Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint 3 1445645 2 B2021 Portable Building 29 Exterior Fair Single-Pane Exterior Window, 24 SF 13 1445649 B2032 Portable Building 29 Exterior Fair 21 Exterior Door, Steel 1 1445644 Roofing B3011 Portable Building 29 Roof Fair Roof, Metal 1,128 SF 23 1445650 Interiors Portable Building 29 Fair Interior Fiberboard Panel Wall Construction, Fiberboard Panel 1,170 SF C1011 33 1445643 C3025 Portable Building 29 Fair Interior Floor Finish, Carpet Commercial Standard 960 SF 6 1445642 C3032 Portable Building 29 Interior Ceiling Finish, Suspended Acoustical Tile (ACT) Fair 960 SF 8 1445640 **Fire Suppression** D4031 Portable Building 29 Fair Fire Extinguisher, Type ABC, up to 20 LB 1 6 1445639 **HVAC** D3052 Portable Building 29 Exterior Poor Heat Pump, Wall-Mounted, 3.5 to 4 Ton [#29] 1 1 1434147 **Electrical** D5019 Portable Building 29 Fair Full Electrical System Upgrade, Low Density/Complexity 960 SF 23 1479718 Portable Building 29 Exterior 3 D5022 Fair Light Fixture, 150 WATT 1 1445647 D5029 Portable Building 29 Fair Lighting System, Interior, Medium Density & Standard Fixtures 960 SF 17 1445641 Fire Alarm & Comm D5037 Portable Building 29 Fair Fire Alarm System, Standard Addressable, Install 960 SF 4 1479719 **Pavement** G2035 Portable Building 29 Exterior Fair Exterior Ramps, Concrete (per LF of Nosing) 20 LF 38 1445648 Indian Hills Elementary School / Portable Classroom #30 **UF Code** Condition Asset/Component/Repair Quantity **RUL** ID Location Structure B1015 Portable Building 30 Exterior Fair Exterior Stair/Ramp Rails, Wood, Refinish 20 LF 3 1434197 Facade Portable Building 30 Exterior Fair Exterior Wall, Wood Shakes/Shingles, 1-2 Stories 1,278 SF 3 B2011 1434231 1,278 SF B2011 Portable Building 30 Exterior Fair Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint 10 1434243 2 B2021 Portable Building 30 Exterior Fair Single-Pane Exterior Window, 24 SF 13 1434257

23

1434103

1

B2032

Roofing

Portable Building 30 Exterior

Fair

Exterior Door, Steel

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
B3011	Portable Building 30 Roof	Fair	Roof, Metal	1,128 SF	23	1434237
Interiors						
C1011	Portable Building 30	Fair	Interior Fiberboard Panel Wall Construction, Fiberboard Panel	1,170 SF	33	1434097
C3025	Portable Building 30	Fair	Interior Floor Finish, Carpet Commercial Standard	960 SF	7	1434149
C3032	Portable Building 30	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	960 SF	8	1434171
Fire Suppress	ion					
D4019	Portable Buildings 30	NA	Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	960 SF	4	1441196
D4031	Portable Building 30	Fair	Fire Extinguisher, Type ABC, up to 20 LB	1	6	1479789
HVAC						
D3052	Portable Building 30 Exterior	Poor	Heat Pump, Wall-Mounted, 3.5 to 4 Ton [#30]	1	1	1434158
Electrical						
D5019	Portable Building 30	Fair	Full Electrical System Upgrade, Low Density/Complexity	960 SF	23	1479720
D5022	Portable Building 30 Exterior	Fair	Light Fixture, 150 WATT	1	3	1434157
D5022	Portable Building 30	Fair	Light Fixture, 150 WATT	1	17	1434226
D5029	Portable Building 30	Fair	Lighting System, Interior, Medium Density & Standard Fixtures	960 SF	17	1434110
Fire Alarm & C	comm					
D5037	Portable Building 30	Fair	Fire Alarm System, Standard Addressable, Install	960 SF	4	1479721

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Portable Building 31 Exterior	Fair	Exterior Stair/Ramp Rails, Wood, Refinish	20 LF	3	1445659
Facade						
B2011	Portable Building 31 Exterior	Fair	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories	1,278 SF	3	1445657
B2011	Portable Building 31 Exterior	Fair	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	1,278 SF	10	1445658
B2021	Portable Building 31 Exterior	Fair	Single-Pane Exterior Window, 24 SF	2	13	1445660
B2032	Portable Building 31 Exterior	Fair	Exterior Door, Steel	1	23	1445661
Roofing						
B3011	Portable Building 31 Roof	Fair	Roof, Metal	1,128 SF	23	1445662
Interiors						
C1011	Portable Building 31	Fair	Interior Fiberboard Panel Wall Construction, Fiberboard Panel	1,170 SF	33	1445653
C3025	Portable Building 31	Fair	Interior Floor Finish, Carpet Commercial Standard	960 SF	7	1445655
C3032	Portable Building 31	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	960 SF	8	1445654
Fire Suppressi	ion					
D4019	Portable Buildings 31	NA	Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	960 SF	4	1445663
D4031	Portable Building 31	Fair	Fire Extinguisher, Type ABC, up to 20 LB	1	6	1479793
HVAC						
D3052	Portable Building 31 Exterior	Poor	Heat Pump, Wall-Mounted, 3.5 to 4 Ton [#31]	1	1	1434136

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Electrical						
D5019	Portable Building 31	Fair	Full Electrical System Upgrade, Low Density/Complexity	960 SF	23	1479722
D5022	Portable Building 31 Exterior	Fair	Light Fixture, 150 WATT	1	3	1445656
D5022	Portable Building 31	Fair	Light Fixture, 150 WATT	1	17	1445652
D5029	Portable Building 31	Fair	Lighting System, Interior, Medium Density & Standard Fixtures	960 SF	17	1445651
Fire Alarm & Co	omm					
D5037	Portable Building 31	Fair	Fire Alarm System, Standard Addressable, Install	960 SF	4	1479723
Indian Hilla El	lamantani, Sahaal / Dartahla Classicam #22					
	lementary School / Portable Classroom #32	Condition	Accet/Component/Denois	Quantity	DIII	ID.
UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure	Destable Duilding 22 Estavion	Fair	Estavion Otain/Daran Baila Waad Bafiniah	20.15		4445070
B1015	Portable Building 32 Exterior	Fair	Exterior Stair/Ramp Rails, Wood, Refinish	20 LF	3	1445672
Facade	Destable Building 00 Federica	Freellant	Estados Well and Daintad Ourface A O Otarias Dans 9 Daint	4.070.05	40	1115071
B2011	Portable Building 32 Exterior	Excellent	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	1,278 SF	10	1445671
B2011	Portable Building 32 Exterior	Fair	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories	1,278 SF	3	1445670
B2021	Portable Building 32 Exterior	Fair	Single-Pane Exterior Window, 24 SF	2	13	1445673
B2032	Portable Building 32 Exterior	Fair	Exterior Door, Steel	1	23	1445674
Roofing						
B3011	Portable Building 32 Roof	Fair	Roof, Metal	1,128 SF	23	1445675
Interiors				4.470.07		
C1011	Portable Building 32	Fair	Interior Wall Construction, Fiberglass Panel	1,170 SF	33	1445666
C3025	Portable Building 32	Fair	Interior Floor Finish, Carpet Commercial Standard	960 SF	7	1445668
C3032	Portable Building 32	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	960 SF	8	1445667
Fire Suppression						
D4019	Portable Buildings 32	NA	Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	960 SF	4	1445676
D4031	Portable Building 30	Fair	Fire Extinguisher, Type ABC, up to 20 LB	1	6	1479790
HVAC						
D3052	Portable Building 32 Exterior	Poor	Heat Pump, Wall-Mounted, 3.5 to 4 Ton [#32]	1	1	1434199
Electrical						
D5019	Portable Building 18	Fair	Full Electrical System Upgrade, Low Density/Complexity	960 SF	23	1479724
D5022	Portable Building 32 Exterior	Fair	Light Fixture, 150 WATT	1	3	1445669
D5029	Portable Building 32	Fair	Lighting System, Interior, Medium Density & Standard Fixtures	960 SF	17	1445664
Fire Alarm & Co	omm					
D5037	Portable Building 18	Fair	Fire Alarm System, Standard Addressable, Install	960 SF	4	1479725
Indian Hills E	lementary School / Portable Classroom #33					
UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
B1015	Portable Building 33 Exterior	Fair	Exterior Stair/Ramp Rails, Wood, Refinish	20 LF	3	1445685
Facade						
B2011	Portable Building 33 Exterior	Fair	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories	1,278 SF	3	1445683
B2011	Portable Building 33 Exterior	Fair	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	1,278 SF	10	1445684
B2021	Portable Building 33 Exterior	Fair	Single-Pane Exterior Window, 24 SF	2	13	1445686
B2032	Portable Building 33 Exterior	Fair	Exterior Door, Steel	1	23	1445687
Roofing						
B3011	Portable Building 33 Roof	Fair	Roof, Metal	1,128 SF	23	1445688
Interiors						
C1011	Portable Building 33	Fair	Interior Fiberboard Panel Wall Construction, Fiberboard Panel	1,170 SF	33	1445679
C3025	Portable Building 33	Fair	Interior Floor Finish, Carpet Commercial Standard	960 SF	7	1445681
C3032	Portable Building 33	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	960 SF	8	1445680
Fire Suppressi	ion					
D4019	Portable Buildings 33	NA	Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	960 SF	4	1445689
D4031	Portable Building 33	Fair	Fire Extinguisher, Type ABC, up to 20 LB	1	6	1479791
HVAC						
D3052	Portable Building 33 Exterior	Poor	Heat Pump, Wall-Mounted, 3.5 to 4 Ton [#33]	1	1	1434272
Electrical						
D5019	Portable Building 33	Fair	Full Electrical System Upgrade, Low Density/Complexity	960 SF	23	1479726
D5022	Portable Building 33 Exterior	Fair	Light Fixture, 150 WATT	1	3	1445682
D5022	Portable Building 33	Fair	Light Fixture, 150 WATT	1	17	1445678
D5029	Portable Building 33	Fair	Lighting System, Interior, Medium Density & Standard Fixtures	960 SF	17	1445677
Fire Alarm & C	omm					
D5037	Portable Building 33	Fair	Fire Alarm System, Standard Addressable, Install	960 SF	4	1479727

Quantity	RUL	ID
20 LF	3	1445698
1,278 SF	10	1445697
1,278 SF	3	1445696
2	13	1445699
1	23	1445700
1,178 SF	23	1445701
1,170 SF	33	1445692

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
C3025	Portable Building 34	Fair	Interior Floor Finish, Carpet Commercial Standard	960 SF	7	1445694
C3032	Portable Building 34	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	960 SF	8	1445693
Fire Suppressi	on					
D4019	Portable Buildings 34	NA	Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	960 SF	4	1445702
D4031	Portable Building 34	Fair	Fire Extinguisher, Type ABC, up to 20 LB	1	6	1479792
HVAC						
D3052	Portable Building 34 Exterior	Poor	Heat Pump, Wall-Mounted, 3.5 to 4 Ton [#34]	1	1	1434289
Electrical						
D5019	Portable Building 34	Fair	Full Electrical System Upgrade, Low Density/Complexity	960 SF	8	1479728
D5022	Portable Building 34 Exterior	Fair	Light Fixture, 150 WATT	1	3	1445695
D5029	Portable Building 34	Fair	Lighting System, Interior, Medium Density & Standard Fixtures	960 SF	17	1445690
Fire Alarm & C	omm					
D5037	Portable Building 34	Fair	Fire Alarm System, Standard Addressable, Install	960 SF	4	1479729

Indian Hills Elementary School / Site

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Structure						
B1015	Site	Fair	Exterior Stairs, Masonry	20 SF	18	1441193
B1022	Site	Fair	Roof Structure, Pitched, Steel Framing	1,200 SF	43	1434233
Plumbing						
D2018	Site	Fair	Drinking Fountain, Outside/Site Style	5	5	1434203
Electrical						
D5012	Site	Fair	Secondary Transformer, 150 kVA	1	2	1434138
D5012	Site	Fair	Main Distribution Panel-400 AMP, 400 AMP	1	4	1434187
D5012	Site	Fair	Building/Main Switchboard, 600 AMP [DB-1]	1	8	1434294
D5012	Site	Fair	Secondary Transformer, Dry, 45 kVA	1	27	1434298
Pavement						
G2022	Site	Good	Parking Lots, Asphalt Pavement, Mill & Overlay	40,985 SF	22	1434242
G2022	Site	Fair	Parking Lots, Asphalt Pavement, Seal & Stripe	40,985 SF	2	1434281
G2031	Site	Fair	Pedestrian Pavement, Sidewalk, Concrete Large Areas	26,562 SF	18	1434144
G2035	Site	Fair	Exterior Stairs & Ramps, Concrete (per LF of Nosing)	200 LF	18	1434107
Site Developme	ent					
G2041	Site	Fair	Fences & Gates, Chain Link, 6' High	3,316 LF	8	1434201
G2041	Site	Fair	Fences & Gates, Metal Tube, 6' High	450 LF	8	1434196
G2044	Site	Fair	Signage, Property, Monument/Pylon	1	11	1480139
G2044	Site	Fair	Signage, Property, Monument/Pylon, Replace/Install	1	3	1434133
G2045	Site	Fair	Site Furnishings, Picnic Table, Plastic-Coated Concrete	15	4	1434182
G2045	Site	Fair	Site Furnishings, Picnic Table, Plastic-Coated Metal	6	16	1434273

Indian Hills Elementary School / Site

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
G2047	Playground	Fair	Play Surfaces & Sports Courts, Asphalt, Seal & Stripe	30,375 SF	2	1434255
G2047	Kindergarten Playground	Fair	Play Structure, Swing Set only, 4 Seats	1	6	1434100
G2047	Kindergarten playground	Poor	Play Surfaces & Sports Courts, Asphalt	2,998 SF	0	1434236
G2047	Playground	Fair	Play Structure, Swing Set only, 4 Seats	3	4	1434146
G2047	Playground	Fair	Play Surfaces & Sports Courts, Poured-in-place Rubber	6,640 SF	5	1434108
G2047	Site	Fair	Sports Apparatus, Basketball Backstop	8	3	1434150
G2047	Kindergarten Playground	Fair	Play Surfaces & Sports Courts, Poured-in-place Rubber	2,325 SF	4	1443305
G2047	Playground	Fair	Play Structure, Medium	1	16	1434118
G2047	Playground	Fair	Play Structure, Large	1	16	1434216
G2048	Site	Fair	Flagpole, Metal	1	5	1434106
G2049	Site	Fair	Dumpster Accessories, Enclosures, Concrete Block (CMU), 8' High	50 LF	15	1443297
Landscaping						
G2057	Site	Poor	Irrigation System, Replace/Install	45,000 SF	0	1434163
Site Lighting						
G4021	Site	Fair	Site Pole Light, 1000 WATT, Replace/Install	3	17	1434265
Follow-up Stud	ies					
P000X	Site	Poor	Engineer, Civil, Landscaping	1	0	1480140

Indian Hills Elementary School / Site Restrooms

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Facade					,	
B2011	Site Restroom Exterior	Fair	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	1,008 SF	10	1434191
B2011	Site Restroom Exterior	Fair	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories	1,008 SF	14	1434313
B2032	Site Restroom Exterior	Fair	Exterior Door, Steel	4	24	1434113
Roofing						
B3011	Site Restroom Roof	Fair	Roof, Single-Ply TPO/PVC Membrane	528 SF	4	1434278
Interiors						
C1031	Site Restroom	Fair	Toilet Partitions, Plastic/Laminate	6	4	1434306
C3012	Site Restroom	Fair	Interior Wall Finish, Laminated Paneling (FRP)	1,008 SF	14	1434299
C3024	Site Restroom	Fair	Interior Floor Finish, Linoleum	528 SF	13	1434179
C3032	Site Restroom	Fair	Interior Ceiling Finish, Suspended Acoustical Tile (ACT)	528 SF	9	1434225
Plumbing						
D2011	Site Restroom	Fair	Toilet, Commercial Water Closet	8	14	1434232
D2012	Site Restroom	Fair	Urinal, Standard	2	14	1434285
D2014	Site Restroom	Fair	Sink/Lavatory, Wall-Hung, Vitreous China	6	14	1434178
D2029		Fair	Plumbing System, Supply & Sanitary, Medium Density (excl fixtures)	528 SF	24	1480103
Fire Suppressi	on					
D4019	Site Restrooms	NA	Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	528 SF	4	1441195

Indian Hills Elementary School / Site Restrooms

UF Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
Electrical						
D5019	Site Restroom	Fair	Full Electrical System Upgrade, Low Density/Complexity	528 SF	24	1479730
D5022	Site Restroom Exterior	Fair	Light Fixture, 100 WATT	4	11	1434175
Fire Alarm & C	Comm					
D5037	Site Restroom	Fair	Fire Alarm System, Standard Addressable, Install	528 SF	4	1479731
Pavement						
G2035	Site Restroom Exterior	Fair	Exterior Stairs & Ramps, Concrete (per LF of Nosing)	64 LF	34	1434096

1

Appendix E: Replacement Reserves



10/22/2019

10/22/2019

Indian Hills Elementary School

* Markup/LocationFactor (1.107) has been included in unit costs.

Iniformat CodeID		Lifespan (EUL)EAge	RUL	Quantity	yUnit	Unit Cost	t * Subtota	al 2019	2020	2021	2022	2023	2024	2025	2026	2027 202	8 2029	2030	2031	2032 2033	2034 203	5 2036	2037	2038 203	39 Deficiency Repair Esti
2011 143426	68 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	9	1	2460	SF	\$3.3	32 \$8,17	70	\$8,170									\$8,170							\$16
32011 143410	09 Exterior Wall, Stucco, 1-2 Stories, Prep & Fog Coat or Paint	10	8	2	10580	SF	\$3.	54 \$37,47	79		\$37,479								:	\$37,479						\$74
B2011 143409	98 Exterior Wall, Wood Shakes/Shingles, 1-2 Stories, Replace	30	27	3	2460	SF	\$8.3	30 \$20,42	24			\$20,424														\$20
32011 143429	90 Exterior Wall, Stucco, 1-2 Stories, Replace	50	32	18	10580	SF	\$22.	14 \$234,24	41															\$234,241		\$234
B2021 143430	09 Window, 24 SF, Replace	30	25	5	149	EA	\$1,051.6	65 \$156,69	96				:	\$156,696												\$156
B2032 14342	29 Exterior Door, Steel, Replace	40	32	8	31	EA	\$664.2	20 \$20,59	90							\$20	590									\$20
B3011 143420	08 Roof, Single-Ply TPO/PVC Membrane, Replace	20	17	3	18710	SF	\$18.8	82 \$352,10	03		\$	352,103														\$352
B3011 14342	24 Roof, Asphalt Shingle 30-Year, Replace	30	14	16	17270	SF	\$6.0	09 \$105,14	48													\$105,14	8			\$105
C1012 143424	49 Movable Partitions, Fabric Office 6' Height, Replace	25	22	3	30	LF	\$32.	55 \$97	76			\$976														
C1017 143429	92 Interior Window, 24 SF, Replace	40	32	8	80	EA	\$940.9	95 \$75,27	76							\$75	276									\$75
C1021 143412	21 Interior Aluminum-Framed Partially-Glazed Door, Aluminum-Framed Partially-Glazed, Replace	40	32	8	20	EA	\$1,439.	10 \$28,78	82							\$28	782									\$28
C1021 143410	60 Interior Door, Wood Solid-Core, Replace	40	32	8	17	EA	\$774.9	90 \$13,17	73							\$13	173									\$13
C1031 143430	01 Toilet Partitions, Metal, Replace	20	16	4	17	EA	\$940.9	95 \$15,99	96				\$15,996													\$15
C3012 14341:	39 Interior Wall Finish, Wallpaper, Replace	15	13	2	37892	SF	\$2.4	44 \$92,28	82		\$92,282												\$92,282			\$184
C3012 143412	26 Interior Wall Finish, Wood Paneling, Replace	30	26	4	1722	SF	\$29.8	89 \$51,46	.69				\$51,469													\$51
C3012 144064	41 Interior Wall Finish, Ceramic Tile, Replace	40	32	8	3445	SF	\$19.9	93 \$68,64	45							\$68	645									\$68
C3024 143424	48 Interior Floor Finish, Linoleum, Replace	15	12	3	861	SF	\$3.8	87 \$3,33	36			\$3,336												\$3,336		\$6
	02 Interior Floor Finish, Vinyl Tile (VCT), Replace	15	11	4	6602	SF	\$5.	54 \$36,54	42				\$36,542												\$36,542	\$73
C3024 14342	70 Interior Floor Finish, Ceramic Tile, Replace	40	32	8	861	SF	\$19.9	93 \$17,15	56							\$17	156									\$17
C3024 143414	42 Interior Floor Finish, Composite Floor Tile, Replace	15	3	12	2871	SF	\$9.9	96 \$28,60	04											\$28,604						\$28
C3024 143424	47 Interior Floor Finish, Quarry Tile, Replace	50	32	18	281	SF	\$28.	78 \$8,08	88															\$8,088		\$8
C3025 143416	65 Interior Floor Finish, Carpet Commercial Tile, Replace	10	4	6	17224	SF	\$7.:	20 \$123,93	35						\$123,935							\$123,93	5			\$247
	68 Interior Ceiling Finish, Wood, Replace	30	26	4	3732	SF		50 \$57,83					\$57,839													\$57
	50 Interior Ceiling Finish, any flat surface, Prep & Paint	10	6	4	1148	SF		21 \$2,54					\$2,542								\$2,542					\$5
	04 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	21	4	23252	SF		87 \$90,09					\$90,090								, , , , ,					\$90
	21 Toilet, Commercial Water Closet, Replace	30	24	6	18	EA	-	10 \$25,90					***,***		\$25,904											\$25
	92 Urinal, Standard, Replace	30	24	6	5	EA		70 \$6,08							\$6,089											\$6
	73 Service Sink, Floor, Replace	35	32	3	1	EA						\$886			ψ0,000											
	115 Service Sink, Floor, Replace	35	32	3	1	EA	\$885.0					\$886														
	13 Sink/Lavatory, Vanity Top, Enameled Steel, Replace	30	26	4	8	EA	· ·					φοσσ	\$9,742													\$9
	61 Commercial Kitchen Sink, Stainless Steel, 2-Bowl, Replace	30	26	4	1	EA							\$2,325													\$2
	12 Sink/Lavatory, Wall-Hung, Vitreous China, Replace	30	24	6	13	EA		50 \$21,58					ΨΖ,525		\$21,587											\$21
	64 Drinking Fountain, Outside/Site Style, Replace	15	10	5	2	EA								\$7,970	Ψ21,507										\$7,97	
	48 Water Heater, 6 GAL, Replace	15	13	2	1	EA					\$609			φ1,910									\$609		φ1,51	\$13
	83 Water Heater, 50 GAL, Replace		12				· ·				\$009	\$996											\$609	\$996		·
		15	12	3	1	EA						\$609														\$1
	70 Water Heater, 10 GAL, Replace	15	12	3	1 00700	EA	-	85 \$60				\$009				C040	550							\$609		\$1
	93 Plumbing System, Supply & Sanitary, Medium Density (excl fixtures), Replace	40	32	8	28706			18 \$349,55						#0.004		\$349	,553									\$349
	28 HVAC System Ductwork, High Density, Replace	30	25	5	1295	SF		64 \$8,60						\$8,601												\$8
	27 Exhaust Fan, 75 CFM, Replace	20	9	11	1	EA	-												\$1,328							\$1
	56 Exhaust Fan, 75 CFM, Replace	20	9	11	1	EA													\$1,328							\$1
	64 Exhaust Fan, 75 CFM, Replace	20	9		1	EA	_	40 \$1,32											\$1,328							\$1
	88 Exhaust Fan, 75 CFM, Replace	20	9	11	1		\$1,328.4												\$1,328							\$1
	46 Exhaust Fan, 75 CFM, Replace	20	9	11	1	-	\$1,328.4												\$1,328							\$1
D3042 143416	69 Exhaust Fan, 75 CFM, Replace	20	9	11	1	EA	\$1,328.4	40 \$1,32	28										\$1,328							\$1
D3042 143426	69 Exhaust Fan, 75 CFM, Replace	20	9	11	1	EA	\$1,328.4	40 \$1,32	28										\$1,328							\$1
D3042 14342	75 Exhaust Fan, 75 CFM, Replace	20	9	11	1	EA	\$1,328.4	40 \$1,32	28										\$1,328							\$1
D3042 143423	Exhaust Fan, 75 CFM, Replace	20	9	11	1	EA	\$1,328.4	40 \$1,32	28										\$1,328							\$1
D3042 143425	53 Exhaust Fan, 75 CFM, Replace	20	9	11	1	EA	\$1,328.4	40 \$1,32	28										\$1,328							\$1

https://www.assetcalc.net/Reports/ReplacementReserve.aspx

Uniformat Cod	eID Cost Description	Lifespan (EUL	\EA==	RUL	Ougstit	d Init	Unit C	`aat * 6.	ubtotal 2010	2020	. 2024 20	122 202	2 2024	2025 20	26 2027	2020 20	20 2020	2024	2032 2033	2024 20	25 202	6 2027	2020	2020 Deficien	ıcy Repair Estimate
D3052	1434104 Packaged Unit (RTU), 7.5 TON, Replace	20	-)⊏Age 19	1	Quantit 1	EA			ubtotal 2019 \$16,605	\$16,605	2021 20	022 202:	3 2024	2025 20	26 2027	2026 20	29 2030	2031	2032 2033	2034 20	35 2036	, 2037	2036	2039 Deficien	stimate \$16,605
D3052	1434117 Packaged Unit (RTU), 7.5 TON, Replace	20	19	1	1	EA			\$16,605	\$16,605															\$16,605
D3052	1434162 Packaged Unit (RTU), 12.5 TON, Replace	20	19	1	1	EA			\$27,675	\$27,675															\$27,675
D3052	1434153 Packaged Unit (RTU), 7.5 TON, Replace	20	19	1	1	EA	-		\$16,605	\$16,605															\$16,605
D3052	1434127 Packaged Unit (RTU), 7.5 TON, Replace	20	19	1	1	EA			\$16,605	\$16,605															\$16,605
D3052	1434240 Packaged Unit (RTU), 10 TON, Replace	20	19	1	1				\$22,140	\$22,140											-	-			\$22,140
D3052	1434271 Packaged Unit (RTU), 7.5 TON, Replace	20	19	1	1				\$16,605	\$16,605											-				\$16,605
D3052	1434241 Packaged Unit (RTU), 7.5 TON, Replace	20	19	1	1				\$16,605	\$16,605															\$16,605
D3052	1434252 Packaged Unit (RTU), 7.5 TON, Replace	20	19	1	'				\$16,605	\$16,605															\$16,605
D3052	1434251 Packaged Unit (RTU), 7.5 TON, Replace	20	19	1	' 1				\$16,605	\$16,605															\$16,605
D3052	1434295 Packaged Unit (RTU), 7.3 TON, Replace	20	7	13	'	EA			\$9,963	\$10,005									\$9,963						\$10,003
D3052	1434167 Packaged Unit (RTU), 4 TON, Replace	20	7	13	'	EA			\$9,963										\$9,963						\$9,963
			-		1																				
D3052	1434258 Packaged Unit (RTU), 3 TON, Replace	20	7	13		EA			\$8,303										\$8,303						\$8,303
D3052	1434286 Packaged Unit (RTU), 4 TON, Replace	20	7	13	1	EA			\$9,963										\$9,963						\$9,963
D3052	1434176 Packaged Unit (RTU), 4 TON, Replace	20	7	13	1	EA	- 1		\$9,963										\$9,963						\$9,963
D3052	1434254 Packaged Unit (RTU), 3 TON, Replace	20	7	13	1	EA			\$8,303										\$8,303						\$8,303
D3052	1434155 Packaged Unit (RTU), 4 TON, Replace	20	7	13	1	EA			\$9,963										\$9,963						\$9,963
D3052	1434239 Packaged Unit (RTU), 3 TON, Replace	20	7	13	1	EA			\$8,303										\$8,303						\$8,303
D3052	1434195 Packaged Unit (RTU), 4 TON, Replace	20	7	13	1	EA			\$9,963										\$9,963						\$9,963
D3052	1434218 Packaged Unit (RTU), 4 TON, Replace	20	7	13	1	EA			\$9,963										\$9,963						\$9,963
D3052	1434189 Packaged Unit (RTU), 4 TON, Replace	20	7	13	1	EA	- 1		\$9,963										\$9,963						\$9,963
D3052	1434211 Packaged Unit (RTU), 4 TON, Replace	20	7	13	1	EA			\$9,963										\$9,963						\$9,963
D3052	1434099 Packaged Unit (RTU), 4 TON, Replace	20	7	13	1	EA	\$9,9	963.00	\$9,963										\$9,963						\$9,963
D3052	1434308 Packaged Unit (RTU), 4 TON, Replace	20	7	13	1	EA	\$9,9	963.00	\$9,963										\$9,963						\$9,963
D3052	1434303 Packaged Unit (RTU), 3 TON, Replace	20	7	13	1	EA	\$8,3	302.50	\$8,303										\$8,303						\$8,303
D3052	Packaged Unit (RTU), 4 TON, Replace	20	7	13	1	EA	\$9,9	963.00	\$9,963										\$9,963						\$9,963
D3052	Packaged Unit (RTU), 4 TON, Replace	20	7	13	1	EA	\$9,9	963.00	\$9,963										\$9,963						\$9,963
D4019	1441146 Sprinkler System, Full Retrofit, Medium Density/Complexity, Renovate	40	36	4	28706	SF		\$5.54 \$	5158,888			\$158,888	3												\$158,888
D4031	1434284 Fire Extinguisher, Type ABC, up to 20 LB, Replace	10	4	6	25	EA	. \$1	166.05	\$4,151				\$4	4,151						\$4,1	<i>j</i> 1				\$8,303
D5012	1434135 Main Distribution Panel-225 AMP, 225 AMP, Replace	30	26	4	1	EA	\$3,3	321.00	\$3,321			\$3,321													\$3,321
D5012	1434105 Main Distribution Panel-225 AMP, 225 AMP, Replace	30	26	4	1	EA	\$3,3	321.00	\$3,321			\$3,321													\$3,321
D5012	1434266 Building/Main Switchboard, 600 AMP, Replace	40	32	8	1	EA	\$44,2	280.00	\$44,280						\$44,280										\$44,280
D5019	1434256 Electrical Wiring & Switches, High Density/Complexity, Replace	40	32	8	28706	SF		\$4.43 \$	127,110						\$127,110										\$127,110
D5022	1434120 Light Fixture, 250 WATT, Replace	20	4	16	10	EA	. \$2	243.54	\$2,435											\$2,43	35				\$2,435
D5022	1434141 Light Fixture, 100 WATT, Replace	20	3	17	15	EA	. \$2	210.33	\$3,155												\$3,155	ı			\$3,155
D5029	1434222 Lighting System, Interior, High Density & Standard Fixtures, Replace	20	3	17	28706	SF	\$	\$14.39 \$	3413,108												\$413,108	,			\$413,108
D5037	1434123 Fire Alarm Control Panel, Addressable, Replace	15	9	6	1	EA	\$16,6	805.00	\$16,605				\$16	6,605											\$16,605
D5092	1434125 Exit Sign Light Fixture, LED, Replace	10	7	3	30	EA	. \$2	243.54	\$7,306		\$7,3	06							\$7,306						\$14,612
D5092	1434174 Emergency Light, 2-Head w/ Battery, Replace	10	7	3	12	EA	. \$2	243.54	\$2,922		\$2,9	122							\$2,922						\$5,845
E1093	1434312 Commercial Kitchen, Refrigerator, 1-Door Reach-In, Replace	15	13	2	1	EA	\$2,9	988.90	\$2,989		\$2,989										\$2,989				\$5,978
E1093	1434140 Commercial Kitchen, Freezer, 2-Door Reach-In, Replace	15	13	2	1	EA	\$5,6	345.70	\$5,646		\$5,646										\$5,646	ı			\$11,291
E1093	1434245 Commercial Kitchen, Food Warmer, Replace	15	11	4	1	EA	\$1,8	381.90	\$1,882			\$1,882	2										\$1,882		\$3,764
E1093	1434115 Commercial Kitchen, Food Warmer, Replace	15	11	4	1	EA	\$1,8	381.90	\$1,882			\$1,882	2										\$1,882		\$3,764
E1093	1434151 Commercial Kitchen, Food Warmer, Replace	15	11	4	1	EA	\$1,8	881.90	\$1,882			\$1,882	2										\$1,882		\$3,764
E1093	1434282 Commercial Kitchen, Dairy Cooler/Wells, Replace	15	9	6	1	EA	\$3,9	985.20	\$3,985				\$3	3,985											\$3,985
E1093	1434194 Commercial Kitchen, Garbage Disposal, 1 to 3 HP, Replace	15	2	13	1	EA	\$4,2	206.60	\$4,207										\$4,207						\$4,207
E2012	1434279 Kitchen Cabinetry, Stock Hardwood, Replace	20	16	4	520	LF	\$3	332.10 \$	6172,692			\$172,692	2												\$172,692
G2035	1434166 Exterior Stairs & Ramps, Concrete (per LF of Nosing), Replace	50	32	18	32	LF	\$	646.49	\$1,488													\$1,488			\$1,488
Totals, Unesc	alated									\$0 \$190,825	139,004 \$390,4	45 \$610,411	\$173,268 \$202	2,256	\$0 \$744,566	\$0	\$0 \$21,454	\$66,082	\$177,164 \$2,542	\$0 \$235,6	70 \$517,789	\$248,758	\$42,188	\$7,970	\$3,770,391
Totals, Escala	ted (3.0% inflation, compounded annually)									\$0 \$196.549 \$	147,470 \$426,6	50 \$687.023	\$200.865 \$241	1,504	\$0 \$943,194	\$0	\$0 \$29.697	\$94,218	\$260,172 \$3,845	\$0 \$378.1	82 \$855,826	\$423,494	\$73.977	14.395	\$4,977,058

I IIIII LI	onientar j	y School / Lottable Classicolli #10																										
Uniformat Cod	le ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost *Su	btotal 2019	2020	2021	2022	2023	2024 2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039 Deficiency Repair Estir
B2011	143420	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories, Replace	30	26	4	1278	SF	\$8.30 \$1	0,611			\$10	611															\$10
B2011	14343	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	0	10	1278	SF	\$3.32 \$	4,244									\$4,244										\$4,244
B2021	143418	Single-Pane Exterior Window, 24 SF, Replace	30	28	2	2	EA	\$1,881.90 \$	3,764		\$3,764																	\$3

Uniformat CodeID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	/Unit	Unit Cost *Subt	otal 2019	2020	2021 20	22 202	23 20	24 2025	2026 20	27 202	28 2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039 Def	ficiency Repair Estima
B2032 1	434129 Exterior Door, Steel, Replace	40	32	8	1	EA	\$664.20 \$	664						\$66	64												\$60
B3011 1	434185 Roof, Modified Bituminous, Replace	20	17	3	1128	SF	\$11.07 \$12,	487		\$12,4	87																\$12,48
C1011 1	434183 Interior Fiberboard Panel Wall Construction, Fiberboard Panel, Replace	50	32	18	1170	SF	\$13.28 \$15,	542																\$15,542			\$15,54
C3025 1	434288 Interior Floor Finish, Carpet Commercial Tile, Replace	10	4	6	960	SF	\$7.20 \$6,	908					\$6,908									6,908					\$13,81
C3032 1	434310 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	22	3	960	SF	\$3.87 \$3,	720		\$3,7	20																\$3,72
D3052 1	434262 Heat Pump, Wall-Mounted, 3.5 to 4 Ton, Replace	20	19	1	1	EA	\$6,088.50 \$6,	089	\$6,089																		\$6,08
D4019 1	441149 Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	40	36	4	960	SF	\$3.32 \$3,	188			\$3,18	8															\$3,18
D4031 1	434210 Fire Extinguisher, Type ABC, up to 20 LB, Replace	10	4	6	1	EA	\$166.05 \$	166					\$166									\$166					\$33
D5019 1	479697 Full Electrical System Upgrade, Low Density/Complexity, Replace	40	32	8	960	SF	\$14.39 \$13,	815						\$13,81	15												\$13,81
D5022 1	434214 Light Fixture, 150 WATT, Replace	20	3	17	1	EA	\$188.19 \$	188															\$188				\$18
D5029 1	434287 Lighting System, Interior, Medium Density & Standard Fixtures, Replace	e 20	3	17	960	SF	\$8.86 \$8,	502															\$8,502				\$8,50
D5037 1	479699 Fire Alarm System, Standard Addressable, Install	20	16	4	960	SF	\$4.43 \$4,	251			\$4,25	1															\$4,25
Totals, Unescalat	ted							\$	0 \$6,089 \$	3,764 \$16,2	06 \$18,05	0	\$0 \$7,074	\$0 \$14,48	30 \$	0 \$4,244	\$0	\$0	\$0	\$0	\$0	7,074	\$8,690	\$15,542	\$0	\$4,244	\$105,45
Totals, Escalated	(3.0% inflation, compounded annually)							\$	0 \$6,271 \$	3,993 \$17,7	09 \$20,31	5	\$0 \$8,446	\$0 \$18,34	12 \$	0 \$5,704	\$0	\$0	\$0	\$0	\$0 \$	11,351 \$	14,363	\$26,460	\$0	\$7,666	\$140,62

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Uniformat CodeID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost *	Subtotal 20	19	2020	2021	2022 2023	2024	2025	2026 202	7 2028	3 2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039 Def	ficiency Repair Estimate
B2011 1-	445539 Exterior Wall, Wood Shakes/Shingles, 1-2 Stories, Replace	30	26	4	1278	SF	\$8.30	\$10,611				\$10,611																\$10,611
B2011 1-	445541 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	0	10	1278	SF	\$3.32	\$4,244									\$4,244										\$4,244	\$8,488
B2021 1-	445545 Single-Pane Exterior Window, 24 SF, Replace	30	28	2	2	EA	\$1,881.90	\$3,764		5	\$3,764																	\$3,764
B2032 1-	445542 Exterior Door, Steel, Replace	40	32	8	1	EA	\$664.20	\$664							\$66	4												\$664
B3011 1-	445546 Roof, Modified Bituminous, Replace	20	17	3	1128	SF	\$11.07	\$12,487				\$12,487																\$12,487
C1011 1-	445536 Interior Fiberboard Panel Wall Construction, Fiberboard Panel, Replace	e 50	32	18	1170	SF	\$13.28	\$15,542																	\$15,542			\$15,542
C3025 14	445537 Interior Floor Finish, Carpet Commercial Tile, Replace	10	4	6	960	SF	\$7.20	\$6,908					\$6	,908									\$6,908					\$13,815
C3032 1-	1445535 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	22	3	960	SF	\$3.87	\$3,720				\$3,720																\$3,720
D3052 14	434180 Heat Pump, Wall-Mounted, 3.5 to 4 Ton, Replace	20	19	1	1	EA	\$6,088.50	\$6,089	9	6,089																		\$6,089
D4019 14	445547 Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	40	36	4	960	SF	\$3.32	\$3,188				\$3,188																\$3,188
D4031 1-	445534 Fire Extinguisher, Type ABC, up to 20 LB, Replace	10	4	6	1	EA	\$166.05	\$166					\$	166									\$166					\$332
D5019 1-	479700 Full Electrical System Upgrade, Low Density/Complexity, Replace	40	32	8	960	SF	\$14.39	\$13,815							\$13,81	5												\$13,815
D5022 1	445540 Light Fixture, 150 WATT, Replace	20	3	17	1	EA	\$188.19	\$188																\$188				\$188
D5029 1-	445538 Lighting System, Interior, Medium Density & Standard Fixtures, Replace	e 20	3	17	960	SF	\$8.86	\$8,502																\$8,502				\$8,502
D5037 14	479701 Fire Alarm System, Standard Addressable, Install	20	16	4	960	SF	\$4.43	\$4,251				\$4,251																\$4,251
Totals, Unescalat	ed								\$0 \$	6,089	\$3,764	\$16,206 \$18,050	\$0 \$7	,074	\$0 \$14,48	\$0	\$4,244	\$0	\$0	\$0	\$0	\$0	\$7,074	\$8,690	\$15,542	\$0	\$4,244	\$105,456
Totals, Escalated	(3.0% inflation, compounded annually)								\$0 \$	6,271	\$3,993	\$17,709 \$20,315	\$0 \$8	,446	\$0 \$18,34	2 \$0	\$5,704	\$0	\$0	\$0	\$0	\$0	\$11,351	14,363	\$26,460	\$0	\$7,666	\$140,621

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Indian Hills Elementary School / Portable Classroom #20

Uniformat (CodeID Cost Description	Lifespan (EUL))EAge	RUL	Quantity	yUnit	Unit Cost *Subtotal 201	19 2020 202	1 202	22 2023	2024 2025	2026	2027 2	2028 202	29 2030	2031	2032	2033	2034	2035	2036 2037	2038	8 2039 Deficiency	Repair Estima
B2011	1445553 Exterior Wall, Wood Shakes/Shingles, 1-2 Stories, Replace	30	26	4	1278	SF	\$8.30 \$10,611			\$10,611														\$10,61
B2011	1445555 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	0	10	1278	SF	\$3.32 \$4,244							\$4,24	4								\$4,244	\$8,48
B2021	1445559 Single-Pane Exterior Window, 24 SF, Replace	30	28	2	2	EA	\$1,881.90 \$3,764	\$3,764																\$3,76
B2032	1445556 Exterior Door, Steel, Replace	40	32	8	1	EA	\$664.20 \$664						\$664											\$66
B3011	1445560 Roof, Modified Bituminous, Replace	20	19	1	1128	SF	\$11.07 \$12,487	\$12,487																\$12,48
C1011	1445550 Interior Fiberboard Panel Wall Construction, Fiberboard Panel, Replace	50	32	18	1170	SF	\$13.28 \$15,542														\$15,542			\$15,54
C3025	1445551 Interior Floor Finish, Carpet Commercial Tile, Replace	10	4	6	960	SF	\$7.20 \$6,908				\$6,908									6,908				\$13,81
C3032	1445549 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	22	3	960	SF	\$3.87 \$3,720		\$3,72	0														\$3,72
D3052	1445557 Heat Pump, Wall-Mounted, 3.5 to 4 Ton, Replace	20	19	1	1	EA	\$6,088.50 \$6,089	\$6,089																\$6,08
D4019	1445561 Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	40	36	4	960	SF	\$3.32 \$3,188			\$3,188														\$3,18
D4031	1445548 Fire Extinguisher, Type ABC, up to 20 LB, Replace	10	4	6	1	EA	\$166.05 \$166				\$166									\$166				\$33
D5019	1479702 Full Electrical System Upgrade, Low Density/Complexity, Replace	40	32	8	960	SF	\$14.39 \$13,815					\$13	,815											\$13,81
D5022	1445554 Light Fixture, 150 WATT, Replace	20	3	17	1	EA	\$188.19 \$188														\$188			\$18
D5029	1445552 Lighting System, Interior, Medium Density & Standard Fixtures, Replace	20	3	17	960	SF	\$8.86 \$8,502														\$8,502			\$8,50
D5037	1479703 Fire Alarm System, Standard Addressable, Install	20	16	4	960	SF	\$4.43 \$4,251			\$4,251														\$4,25
Totals, Une	escalated							\$0 \$18,575 \$3,764	\$3,72	0 \$18,050	\$0 \$7,074	\$0 \$14	,480	\$0 \$4,24	4 \$0	\$0	\$0	\$0	\$0 \$	7,074	\$8,690 \$15,542	\$0	\$4,244	\$105,45
Totals, Esc	alated (3.0% inflation, compounded annually)							\$0 \$19,133 \$3,993	\$4,06	4 \$20,315	\$0 \$8,446	\$0 \$18	3,342	\$0 \$5,70	4 \$0	\$0	\$0	\$0	\$0 \$	11,351	\$14,363 \$26,460	\$0	\$7,666	\$139,83

3/9

dian	Hillo	Flomonton	Cobool /	Dortoblo	Classroom	#21
lulali		Elementary	SCHOOL /	Portable	Classiconi	#21

Uniformat Code	D Cost Description	Lifespan (EUL)	EAge	RUL	Quantit	yUnit	Unit Cost	*Subtotal 2019	202	0 202	1 202	2 2023	2024	2025 20	026 2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039 Deficiency	Repair Estimate
B2011	1445567 Exterior Wall, Wood Shakes/Shingles, 1-2 Stories, Replace	30	26	4	1278	SF	\$8.30	\$10,611				\$10,611																\$10,611
B2011	1445569 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	0	10	1278	SF	\$3.32	\$4,244									\$4,244										\$4,244	\$8,488
B2021	1445573 Single-Pane Exterior Window, 24 SF, Replace	30	28	2	2	EA	\$1,881.90	\$3,764		\$3,764	4																	\$3,764
B2032	1445570 Exterior Door, Steel, Replace	40	32	8	1	EA	\$664.20	\$664							\$664													\$664
B3011	1445574 Roof, Modified Bituminous, Replace	20	19	1	1128	SF	\$11.07	\$12,487	\$12,487	7																		\$12,487
C1011	1445564 Interior Fiberboard Panel Wall Construction, Fiberboard Panel, Replace	50	32	18	1170	SF	\$13.28	\$15,542																\$1	15,542			\$15,542
C3025	1445565 Interior Floor Finish, Carpet Commercial Tile, Replace	10	4	6	960	SF	\$7.20	\$6,908					\$	6,908								S	6,908					\$13,815
C3032	1445563 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	22	3	960	SF	\$3.87	\$3,720			\$3,72	0																\$3,720
D3052	1445571 Heat Pump, Wall-Mounted, 3.5 to 4 Ton, Replace	20	19	1	1	EA	\$6,088.50	\$6,089	\$6,089	9																		\$6,089
D4019	1445575 Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	40	36	4	960	SF	\$3.32	\$3,188				\$3,188																\$3,188
D4031	1445562 Fire Extinguisher, Type ABC, up to 20 LB, Replace	10	4	6	1	EA	\$166.05	\$166						\$166									\$166					\$332
D5019	1479704 Full Electrical System Upgrade, Low Density/Complexity, Replace	40	32	8	960	SF	\$14.39	\$13,815							\$13,815													\$13,815
D5022	1445568 Light Fixture, 150 WATT, Replace	20	3	17	1	EA	\$188.19	\$188																\$188				\$188
D5029	1445566 Lighting System, Interior, Medium Density & Standard Fixtures, Replace	20	3	17	960	SF	\$8.86	\$8,502																\$8,502				\$8,502
D5037	1479705 Fire Alarm System, Standard Addressable, Install	20	16	4	960	SF	\$4.43	\$4,251				\$4,251																\$4,251
Totals, Unescala	ated								\$0 \$18,575	\$3,764	4 \$3,72	0 \$18,050	\$0 \$	7,074	\$0 \$14,480	\$0	\$4,244	\$0	\$0	\$0	\$0	\$0 \$	7,074	\$8,690 \$1	15,542	\$0	\$4,244	\$105,456
Totals, Escalate	d (3.0% inflation, compounded annually)								\$0 \$19,133	\$3,993	3 \$4,06	4 \$20,315	\$0 \$	8,446	\$0 \$18,342	\$0	\$5,704	\$0	\$0	\$0	\$0	\$0 \$1	1,351 \$	\$14,363 \$2	26,460	\$0	\$7,666	\$139,837

Indian Hills Elementary School / Portable Classroom #22

Jniformat Code	eID Cost Description	Lifespan (EUL))EAge	RUL	Quantity	/Unit	Unit Cost *Su	ubtotal 201	9 2020	2021	1 2022	2023	2024 2025	2026	2027 2	028 2	029 2	030 20	31 203	2 203	3 2034	2035	2036	2037	2038	2039 Deficiency I	Repair Estima
B2011	1445581 Exterior Wall, Wood Shakes/Shingles, 1-2 Stories, Replace	30	26	4	1278	SF	\$8.30 \$	10,611				\$10,611															\$10,61
B2011	1445583 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	0	10	1278	SF	\$3.32	\$4,244								\$4,	244									\$4,244	\$8,48
B2021	1445587 Single-Pane Exterior Window, 24 SF, Replace	30	28	2	2	EA	\$1,881.90	\$3,764		\$3,764																	\$3,76
B2032	1445584 Exterior Door, Steel, Replace	40	32	8	1	EA	\$664.20	\$664							\$664												\$66
B3011	1445588 Roof, Modified Bituminous, Replace	20	17	3	1128	SF	\$11.07 \$	12,487			\$12,487																\$12,48
C1011	1445578 Interior Fiberboard Panel Wall Construction, Fiberboard Panel, Replace	50	32	18	1170	SF	\$13.28 \$1	15,542																\$15,542			\$15,54
C3025	1445579 Interior Floor Finish, Carpet Commercial Tile, Replace	10	4	6	960	SF	\$7.20	\$6,908					\$6,908									\$6,908					\$13,81
C3032	1445577 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	22	3	960	SF	\$3.87	\$3,720			\$3,720																\$3,72
D3052	1445585 Heat Pump, Wall-Mounted, 3.5 to 4 Ton, Replace	20	19	1	1	EA	\$6,088.50	\$6,089	\$6,089																		\$6,08
D4019	1445589 Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	40	36	4	960	SF	\$3.32	\$3,188				\$3,188															\$3,18
D4031	1445576 Fire Extinguisher, Type ABC, up to 20 LB, Replace	10	4	6	1	EA	\$166.05	\$166					\$166									\$166					\$33
D5019	1479706 Full Electrical System Upgrade, Low Density/Complexity, Replace	40	32	8	960	SF	\$14.39 \$1	13,815							\$13,815												\$13,81
D5022	1445582 Light Fixture, 150 WATT, Replace	20	3	17	1	EA	\$188.19	\$188															\$188				\$18
D5029	1445580 Lighting System, Interior, Medium Density & Standard Fixtures, Replace	e 20	3	17	960	SF	\$8.86	\$8,502															\$8,502				\$8,50
D5037	1479707 Fire Alarm System, Standard Addressable, Install	20	16	4	960	SF	\$4.43	\$4,251				\$4,251															\$4,25
Totals, Unesca	alated								\$0 \$6,089	\$3,764	\$16,206	\$18,050	\$0 \$7,074	\$0	\$14,480	\$0 \$4,	244	\$0	50 \$	\$0	\$0	\$7,074	\$8,690	\$15,542	\$0	\$4,244	\$105,45
Totals, Escalat	ted (3.0% inflation, compounded annually)								\$0 \$6,271	\$3,993	\$17,709	\$20,315	\$0 \$8,446	\$0	\$18,342	\$0 \$5,	704	\$0	50 \$) \$(\$0	\$11,351	\$14,363	\$26,460	\$0	\$7,666	\$140,62

* Markup/LocationFactor (1.107) has been included in unit costs.

Uniformat Code	ID	Cost Description	Lifespan (EUL))EAge	RUL	Quantit	yUnit	Unit Cost	*Subtotal 2019	2020	2021	2022 202	3 2024 202	5 2026	6 202	7 202	8 2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039 Deficiency Re	epair Estimat
B2011	1445595	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories, Replace	30	26	4	1278	SF	\$8.3	0 \$10,611			\$10,61	1															\$10,61 ⁻
B2011	1445597	7 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	0	10	1278	SF	\$3.3	2 \$4,244								\$4,244										\$4,244	\$8,48
B2021	1445601	1 Single-Pane Exterior Window, 24 SF, Replace	30	28	2	2	EA	\$1,881.9	0 \$3,764		\$3,764																	\$3,76
B2032	1445598	3 Exterior Door, Steel, Replace	40	32	8	1	EA	\$664.2	0 \$664						\$664	4												\$664
B3011	1434291	Roof, Metal, Replace	40	32	8	1128	SF	\$14.3	9 \$16,233						\$16,233	3												\$16,23
C1011	1445592	Interior Fiberboard Panel Wall Construction, Fiberboard Panel, Repla	ace 50	32	18	1170	SF	\$13.2	8 \$15,542															\$	15,542			\$15,54
C3025	1445593	Interior Floor Finish, Carpet Commercial Tile, Replace	10	4	6	960	SF	\$7.2	0 \$6,908				\$6,90	3								:	6,908					\$13,81
C3032	1445591	Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	22	3	960	SF	\$3.8	7 \$3,720		\$3	3,720																\$3,72
D3052	1445599	Heat Pump, Wall-Mounted, 3.5 to 4 Ton, Replace	20	19	1	1	EA	\$6,088.5	0 \$6,089	\$6,089																		\$6,08
D4019	1445603	3 Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	40	36	4	960	SF	\$3.3	2 \$3,188			\$3,18	8															\$3,18
D4031	1445590	Fire Extinguisher, Type ABC, up to 20 LB, Replace	10	4	6	1	EA	\$166.0	5 \$166				\$16	3									\$166					\$33

Uniformat Co	deID Cost Description	Lifespan (E	UL)EAge	RU	IL C	Quantity	/Unit	Unit Cost *	Subtotal 2019)	2020	2021	2022	2023	2024	2025	2026 2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039 Deficiency R	tepair Estimate
D5019	1479708 Full Electrical System Upgrade, Low Density/Complexity, Replace	40	32		8	960	SF	\$14.39	\$13,815								\$13,815													\$13,815
D5022	1445596 Light Fixture, 150 WATT, Replace	20	3		17	1	EA	\$188.19	\$188																	\$188				\$188
D5029	1445594 Lighting System, Interior, Medium Density & Standard Fixtures, Repla	ce 20	3		17	960	SF	\$8.86	\$8,502																\$	\$8,502				\$8,502
D5037	1479709 Fire Alarm System, Standard Addressable, Install	20	16		4	960	SF	\$4.43	\$4,251					\$4,251																\$4,251
Totals, Unes	calated									\$0 \$	6,089	3,764	\$3,720	\$18,050	\$0 \$	7,074	\$0 \$30,713	\$0	\$4,244	\$0	\$0	\$0	\$0	\$0 \$7	,074 \$	\$8,690 \$	15,542	\$0	\$4,244	\$109,202
Totals, Esca	ated (3.0% inflation, compounded annually)									\$0 \$	\$6,271	3,993	\$4,064	\$20,315	\$0 \$	8,446	\$0 \$38,906	\$0	\$5,704	\$0	\$0	\$0	\$0	\$0 \$11	,351 \$1	14,363 \$2	26,460	\$0	\$7,666	\$147,539

ndian Hills	Elementary	School /	Portable	Classroom #	#24

Jniformat Code	ID Cost Descripti	ion	Lifespan (EUL)E	Age	RUL	Quantity	Unit	Unit Cost *5	Subtotal 2019	202	202	1 202	2 2023	2024 2025	2026 2	027	2028 2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039 Deficiency Re	pair Estimat
B2011	1445609 Exterior Wall, \	Wood Shakes/Shingles, 1-2 Stories, Replace	30	26	4	1278	SF	\$8.30	\$10,611				\$10,611															\$10,61
B2011	1445611 Exterior Wall, a	any Painted Surface, 1-2 Stories, Prep & Paint	10	0	10	1278	SF	\$3.32	\$4,244								\$4,244									\$4	-,244	\$8,48
B2021	1445615 Single-Pane E	xterior Window, 24 SF, Replace	30	28	2	2	EA	\$1,881.90	\$3,764		\$3,764	4																\$3,764
B2032	1445612 Exterior Door,	Steel, Replace	40	32	8	1	EA	\$664.20	\$664						\$6	664												\$664
B3011	1445616 Roof, Modified	Bituminous, Replace	20	17	3	1128	SF	\$11.07	\$12,487			\$12,48	7															\$12,487
C1011	1445606 Interior Fiberbo	oard Panel Wall Construction, Fiberboard Panel, Replace	50	32	18	1170	SF	\$13.28	\$15,542																\$15,542			\$15,542
C3025	1445607 Interior Floor F	Finish, Carpet Commercial Tile, Replace	10	4	6	960	SF	\$7.20	\$6,908					\$6,908									\$6,908					\$13,815
C3032	1445605 Interior Ceiling	Finish, Suspended Acoustical Tile (ACT), Replace	25	22	3	960	SF	\$3.87	\$3,720			\$3,72)															\$3,720
D3052	1445613 Heat Pump, W	/all-Mounted, 3.5 to 4 Ton, Replace	20	19	1	1	EA	\$6,088.50	\$6,089	\$6,089	•																	\$6,089
D4019	1445617 Sprinkler Syste	em, Full Retrofit, Low Density/Complexity, Renovate	40	36	4	960	SF	\$3.32	\$3,188				\$3,188															\$3,188
D4031	1445604 Fire Extinguish	her, Type ABC, up to 20 LB, Replace	10	4	6	1	EA	\$166.05	\$166					\$166									\$166					\$332
D5019	1479710 Full Electrical	System Upgrade, Low Density/Complexity, Replace	40	32	8	960	SF	\$14.39	\$13,815						\$13,8	815												\$13,815
D5022	1445610 Light Fixture, 1	150 WATT, Replace	20	3	17	1	EA	\$188.19	\$188															\$188				\$188
D5029	1445608 Lighting System	m, Interior, Medium Density & Standard Fixtures, Replace	20	3	17	960	SF	\$8.86	\$8,502															\$8,502				\$8,502
D5037	1479711 Fire Alarm Sys	stem, Standard Addressable, Install	20	16	4	960	SF	\$4.43	\$4,251				\$4,251															\$4,251
Totals, Unescal	ated									\$0 \$6,089	\$3,764	4 \$16,20	\$18,050	\$0 \$7,074	\$0 \$14,4	480	\$0 \$4,244	\$0	\$0	\$0	\$0	\$0	\$7,074	\$8,690	\$15,542	\$0 \$4	,244	\$105,456
Totals, Escalate	d (3.0% inflation, comp	oounded annually)								\$0 \$6,27	\$3,993	3 \$17,70	\$20,315	\$0 \$8,446	\$0 \$18,3	342	\$0 \$5,704	\$0	\$0	\$0	\$0	\$0	\$11,351	\$14,363	\$26,460	\$0 \$7	,666	\$140,621

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Indian Hills Elementary School / Portable Classroom #26

Uniformat Code	ID Cost Description	Lifespan (EUL	.)EAge	RUL	Quantity	yUnit	Unit Cost *Su	ubtotal 201	9 2020	2021	2022	2023	2024 202	5 202	6 2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038 2039	39Deficiency Re	pair Estimate
B2011	1434219 Exterior Wall, Wood Shakes/Shingles, 1-2 Stories, Replace	30	26	4	1278	SF	\$8.30 \$	10,611				\$10,611																\$10,611
B2011	1434186 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	0	10	1278	SF	\$3.32	\$4,244									\$4,244									\$4,244	4	\$8,488
B2021	1434234 Single-Pane Exterior Window, 24 SF, Replace	30	27	3	2	EA	\$1,881.90	\$3,764			\$3,764																	\$3,764
B2032	1434122 Exterior Door, Steel, Replace	40	32	8	1	EA	\$664.20	\$664							\$664													\$664
B3011	1434296 Roof, Modified Bituminous, Replace	20	10	10	1128	SF	\$11.07 \$1	12,487									\$12,487											\$12,487
C1011	1434220 Interior Fiberboard Panel Wall Construction, Fiberboard Panel, Replace	50	32	18	1170	SF	\$13.28 \$1	15,542																	\$15,542			\$15,542
C3025	1434101 Interior Floor Finish, Carpet Commercial Tile, Replace	10	4	6	960	SF	\$7.20	\$6,908					\$6,90	8								\$	6,908					\$13,815
C3032	1434124 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	20	5	960	SF	\$3.87	\$3,720					\$3,720															\$3,720
D3052	1434190 Heat Pump, Wall-Mounted, 3.5 to 4 Ton, Replace	20	19	1	1	EA	\$6,088.50	\$6,089	\$6,089																			\$6,089
D4019	1441183 Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	40	36	4	960	SF	\$3.32	\$3,188				\$3,188																\$3,188
D4031	1434132 Fire Extinguisher, Wet Chemical/CO2, Replace	10	4	6	1	EA	\$332.10	\$332					\$33	2									\$332					\$664
D5019	1479712 Full Electrical System Upgrade, Low Density/Complexity, Replace	40	32	8	960	SF	\$14.39 \$1	13,815							\$13,815													\$13,815
D5022	1434260 Light Fixture, 150 WATT, Replace	20	3	17	1	EA	\$188.19	\$188																\$188				\$188
D5029	1434261 Lighting System, Interior, Medium Density & Standard Fixtures, Replace	20	3	17	960	SF	\$8.86	\$8,502															\$1	8,502				\$8,502
D5037	1479713 Fire Alarm System, Standard Addressable, Install	20	16	4	960	SF	\$4.43	\$4,251				\$4,251																\$4,251
G2035	1434244 Exterior Stairs & Ramps, Concrete (per LF of Nosing), Replace	50	32	18	20	LF	\$46.49	\$930																	\$930			\$930
Totals, Unescal	ated								\$0 \$6,089	\$0	\$3,764	\$18,050	\$3,720 \$7,24	0 \$	0 \$14,480	\$0	\$16,731	\$0	\$0	\$0	\$0	\$0 \$	7,240 \$8	8,690	\$16,472	\$0 \$4,244	4	\$106,718
Totals, Escalate	ed (3.0% inflation, compounded annually)								\$0 \$6,271	\$0	\$4,113	\$20,315	\$4,312 \$8,64	5 \$	0 \$18,342	\$0	\$22,485	\$0	\$0	\$0	\$0	\$0 \$1	1,618 \$14	4,363	\$28,043	\$0 \$7,666	,6	\$146,172

* Markup/LocationFactor (1.107) has been included in unit costs.

Uniformat Cod	deID Cost Description	Lifespan (EUL)EA	ge RU	IL C	QuantityU	Jnit Unit C	Cost *Subtotal 2019	9 2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039 Deficiency Repair	r Estimate
B2011	1445635 Exterior Wall, Wood Shakes/Shingles, 1-2 Stories, Replace	30	26	4	1278	SF :	\$8.30 \$10,611			\$	310,611																	\$10,611
B2011	1445636 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	0	10	1278	SF :	\$3.32 \$4,244										\$4,244										\$4,244	\$8,488
B2021	1445634 Single-Pane Exterior Window, 24 SF, Replace	30	27	3	2	EA \$1,88	881.90 \$3,764			\$3,764																		\$3,764

Jniformat Co	deID Cost Description	Lifespan (EUL)EAge	RUL	Quantity	/Unit	Unit Cost *5	Subtotal 2019	2020	2021	2022	2023	2024 2025	202	6 2027 2	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039 Deficiency R	tepair Estimat
B2032	1445637 Exterior Door, Steel, Replace	40	32	8	1	EA	\$664.20	\$664							\$664													\$66
B3011	1479766 Roof, Modified Bituminous, Replace	20	19	1	1128	SF	\$11.07	\$12,487	\$12,487																			\$12,487
C1011	1445628 Interior Fiberboard Panel Wall Construction, Fiberboard Panel, Replace	50	32	18	1170	SF	\$13.28	\$15,542																	\$15,542			\$15,542
C3025	1445629 Interior Floor Finish, Carpet Commercial Tile, Replace	10	4	6	960	SF	\$7.20	\$6,908					\$6,908										\$6,908					\$13,815
C3032	1445625 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	20	5	960	SF	\$3.87	\$3,720					\$3,720															\$3,720
D3052	1434119 Heat Pump, Wall-Mounted, 3.5 to 4 Ton, Replace	20	19	1	1	EA	\$6,088.50	\$6,089	\$6,089																			\$6,089
D4019	1445631 Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	40	36	4	960	SF	\$3.32	\$3,188				\$3,188																\$3,188
D4031	1445630 Fire Extinguisher, Type ABC, up to 20 LB, Replace	10	4	6	1	EA	\$166.05	\$166					\$166										\$166					\$332
D5019	1479714 Full Electrical System Upgrade, Low Density/Complexity, Replace	40	32	8	960	SF	\$14.39	\$13,815							\$13,815													\$13,815
D5022	1445633 Light Fixture, 150 WATT, Replace	20	3	17	1	EA	\$188.19	\$188																\$188				\$188
D5029	1445627 Lighting System, Interior, Medium Density & Standard Fixtures, Replace	20	3	17	960	SF	\$8.86	\$8,502																\$8,502				\$8,502
D5037	1479715 Fire Alarm System, Standard Addressable, Install	20	16	4	960	SF	\$4.43	\$4,251				\$4,251																\$4,251
G2035	1445632 Exterior Stairs & Ramps, Concrete (per LF of Nosing), Replace	50	32	18	20	LF	\$46.49	\$930																	\$930			\$930
Totals, Unes	calated								\$0 \$18,575	\$0	\$3,764 \$	18,050	\$3,720 \$7,074	\$0	\$14,480	\$0	\$4,244	\$0	\$0	\$0	\$0	\$0	\$7,074	\$8,690	\$16,472	\$0	\$4,244	\$106,386
Totals, Escal	ated (3,0% inflation, compounded annually)								\$0 \$19,133	\$0	\$4,113 \$	20,315	\$4,312 \$8,446	\$0	\$18,342	\$0	\$5,704	\$0	\$0	\$0	\$0	\$0 \$	11,351	\$14,363	\$28,043	\$0	\$7,666	\$141,788

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Uniformat Codel	ID	Cost Description	Lifespan (EUL)EA	Age F	RUL	QuantityU	Jnit	Unit Cost *S	Subtotal 201	9	2020	2021	2022 20	3 2024 2	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039 Defic	ciency Repair Estimat
B2011	1434267	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	7	3	1278	SF	\$3.32	\$4,244				\$4,244									\$4,244								\$8,488
B2011	1434307	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories, Replace	30	17	13	1278	SF	\$8.30	\$10,611													\$10,611								\$10,61
B2021	1434128	Single-Pane Exterior Window, 24 SF, Replace	30	17	13	2	EA	\$1,881.90	\$3,764													\$3,764								\$3,764
C3025	1434302	Interior Floor Finish, Carpet Commercial Standard, Replace	10	4	6	960	SF	\$8.30	\$7,970					\$7	,970									5	\$7,970					\$15,94°
C3032	1434212	Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	17	8	960	SF	\$3.87	\$3,720							\$3	3,720													\$3,720
D3052	1434277	Heat Pump, Wall-Mounted, 3.5 to 4 Ton, Replace	20	19	1	1	EA	\$6,088.50	\$6,089		\$6,089																			\$6,089
D4031	1434102	Fire Extinguisher, Type ABC, up to 20 LB, Replace	10	4	6	1	EA	\$166.05	\$166					\$	166										\$166					\$332
D5022	1434152	Light Fixture, 150 WATT, Replace	20	17	3	1	EA	\$188.19	\$188				\$188																	\$188
D5029	1434172	Lighting System, Interior, Medium Density & Standard Fixtures, Replace	e 20	3	17	960	SF	\$8.86	\$8,502																	\$8,502				\$8,502
D5037	1479717	Fire Alarm System, Standard Addressable, Install	20	16	4	960	SF	\$4.43	\$4,251				\$4,25	1																\$4,25
Totals, Unescala	lated									\$0	\$6,089	\$0	\$4,432 \$4,25	1 \$0 \$8	,136	\$0 \$:	3,720	\$0	\$0	\$0	\$0	\$18,619	\$0	\$0 \$	\$8,136	\$8,502	\$0	\$0	\$0	\$61,88
Totals, Escalate	ed (3.0%	inflation, compounded annually)								\$0	\$6,271	\$0	\$4,843 \$4,78	4 \$0 \$9	,715	\$0 \$4	4,712	\$0	\$0	\$0	\$0	\$27,342	\$0	\$0 \$1	13,057 \$	14,052	\$0	\$0	\$0	\$84,777

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Indian Hills Elementary School / Portable Classroom #29

Uniformat Codel	D	Cost Description	Lifespan (EUL)EA	\ge	RUL	Quantity	/Unit	Unit Cost *Subtota	12019	2020	2021 2022	2023	2024 2025	2026	2027	2028	2029	2030	2031	2032	2033	2034 2	35 20	036 20	2037	2038	2039 Deficiency Re	pair Estimat
B2011	1445645	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	7	3	1278	SF	\$3.32 \$4,244	4		\$4,244									\$4,244								\$8,48
B2011	1445646	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories, Replace	30	17	13	1278	SF	\$8.30 \$10,61	1										\$	10,611								\$10,61
B2021	1445649	Single-Pane Exterior Window, 24 SF, Replace	30	17	13	2	EA	\$1,881.90 \$3,764	4											\$3,764								\$3,764
C3025	1445642	Interior Floor Finish, Carpet Commercial Standard, Replace	10	4	6	960	SF	\$8.30 \$7,970)				\$7,970									\$7,9	70					\$15,94 ⁻
C3032	1445640	Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	17	8	960	SF	\$3.87 \$3,720)						\$3,720													\$3,72
D3052	1434147	Heat Pump, Wall-Mounted, 3.5 to 4 Ton, Replace	20	19	1	1	EA	\$6,088.50 \$6,089	9	\$6,089																		\$6,08
D4031	1445639	Fire Extinguisher, Type ABC, up to 20 LB, Replace	10	4	6	1	EA	\$166.05 \$166	3				\$166									\$1	66					\$33
D5022	1445647	Light Fixture, 150 WATT, Replace	20	17	3	1	EA	\$188.19 \$188	3		\$188																	\$188
D5029	1445641	Lighting System, Interior, Medium Density & Standard Fixtures, Replace	e 20	3	17	960	SF	\$8.86 \$8,502	2														\$8,5	02				\$8,502
D5037	1479719	Fire Alarm System, Standard Addressable, Install	20	16	4	960	SF	\$4.43 \$4,25	1			\$4,251																\$4,25
Totals, Unescala	ated								\$0	\$6,089	\$0 \$4,432	\$4,251	\$0 \$8,136	\$0	\$3,720	\$0	\$0	\$0	\$0 \$	18,619	\$0	\$0 \$8,1	36 \$8,5	02	\$0	\$0	\$0	\$61,88
Totals, Escalate	d (3.0% i	inflation, compounded annually)							\$0	\$6,271	\$0 \$4,843	\$4,784	\$0 \$9,715	\$0	\$4,712	\$0	\$0	\$0	\$0 \$	27,342	\$0	\$0 \$13,0	57 \$14,0	52	\$0	\$0	\$0	\$84,777

^{*} Markup/LocationFactor (1.107) has been included in unit costs.

Indian Hills Elementary School / Portable Classroom #30

Uniformat Co	odeID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	/Unit	Unit Cost *Su	btotal 2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039 Deficiency Re	pair Estimate
B1015	143419	Exterior Stair/Ramp Rails, Wood, Refinish	10	7	3	20	LF	\$1.66	\$33			\$33										\$33								\$67
B2011	143423	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories, Replace	30	27	3	1278	SF	\$8.30 \$	10,611			\$10,611																		\$10,611
B2011	143424	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	0	10	1278	SF	\$3.32	64,244										\$4,244										\$4,244	\$8,488
B2021	143425	Single-Pane Exterior Window, 24 SF, Replace	30	17	13	2	EA	\$1,881.90	3,764													\$3,764								\$3,764
C3025	143414	Interior Floor Finish, Carpet Commercial Standard, Replace	10	3	7	960	SF	\$8.30	7,970						\$	\$7,970										\$7,970				\$15,941

https://www.assetcalc.net/Reports/ReplacementReserve.aspx

Uniformat Co	deID	Cost Description	Lifespan (EUL)	(EAge	RUL	Quanti	tyUnit	Unit Cost	*Subtota	12019	2020	2021	2022 2	023	2024	2025	2026 2	027	2028	2029	2030	2031	2032	2033	2034	203	5 2036	2037	2038	2039	Deficiency Repair Estimate
C3032	1434171	Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	17	8	960	SF	\$3.8	7 \$3,720	0							\$3,	720													\$3,720
D3052	1434158	Heat Pump, Wall-Mounted, 3.5 to 4 Ton, Replace	20	19	1	1	EA	\$6,088.50	0 \$6,089	9	\$6,089																				\$6,089
D4019	1441196	Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	40	36	4	960	SF	\$3.3	2 \$3,18	В			\$3,	188																	\$3,188
D4031	1479789	Fire Extinguisher, Type ABC, up to 20 LB, Replace	10	4	6	1	EA	\$166.0	5 \$160	3						\$166										\$166	5				\$332
D5022	1434157	Light Fixture, 150 WATT, Replace	20	17	3	1	EA	\$188.1	9 \$188	В			\$188																		\$188
D5022	1434226	Light Fixture, 150 WATT, Replace	20	3	17	1	EA	\$188.1	9 \$18	В																	\$188				\$188
D5029	1434110	Lighting System, Interior, Medium Density & Standard Fixtures, Replace	ce 20	3	17	960	SF	\$8.86	6 \$8,50	2																	\$8,502				\$8,502
D5037	1479721	Fire Alarm System, Standard Addressable, Install	20	16	4	960	SF	\$4.4	3 \$4,25	1			\$4,2	251																	\$4,251
Totals, Unesc	alated									\$0	\$6,089	\$0	\$10,832 \$7,4	139	\$0	\$166	\$7,970 \$3,	720	\$0 \$	1,244	\$0	\$0	\$3,797	\$0	\$0	\$166	\$16,660	\$0	\$0	\$4,244	\$65,328
Totals, Escal	ated (3.0%	inflation, compounded annually)								\$0	\$6,271	\$0	\$11,836 \$8,	373	\$0	\$198	\$9,803 \$4,	712	\$0 \$	5,704	\$0	\$0	\$5,576	\$0	\$0	\$266	\$27,537	\$0	\$0	\$7,666	\$87,942

10/22/2019

Indian	Hillo.	Elementary	Cobool /	Dortoblo	Classroom	#21
IIIulali	TIIIS	Elementary	30110017	Fortable	Classiconi	#31

Jniformat Co	deID Cost Desc	cription	Lifespan (EUL)E	EAge	RUL	Quantity	Unit	Unit Cost *	Subtotal 20	19	2020	2021	2022	2023	2024	2025	2026 2	2027	2028 2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039 Def	iciency Repair Estima
B1015	1445659 Exterior S	stair/Ramp Rails, Wood, Refinish	10	7	3	20	LF	\$1.66	\$33				\$33									\$33								\$
B2011	1445657 Exterior W	Vall, Wood Shakes/Shingles, 1-2 Stories, Replace	30	27	3	1278	SF	\$8.30	\$10,611				\$10,611																	\$10,6
B2011	1445658 Exterior W	Vall, any Painted Surface, 1-2 Stories, Prep & Paint	10	0	10	1278	SF	\$3.32	\$4,244										\$4,244										\$4,244	\$8,4
B2021	1445660 Single-Pa	ne Exterior Window, 24 SF, Replace	30	17	13	2	EA	\$1,881.90	\$3,764													\$3,764								\$3,76
C3025	1445655 Interior Flo	oor Finish, Carpet Commercial Standard, Replace	10	3	7	960	SF	\$8.30	\$7,970								\$7,970									\$7,970				\$15,94
C3032	1445654 Interior Ce	eiling Finish, Suspended Acoustical Tile (ACT), Replace	25	17	8	960	SF	\$3.87	\$3,720								\$3,	,720												\$3,72
D3052	1434136 Heat Pum	np, Wall-Mounted, 3.5 to 4 Ton, Replace	20	19	1	1	EA	\$6,088.50	\$6,089		\$6,089																			\$6,08
D4019	1445663 Sprinkler	System, Full Retrofit, Low Density/Complexity, Renovate	40	36	4	960	SF	\$3.32	\$3,188					\$3,188																\$3,18
D4031	1479793 Fire Exting	guisher, Type ABC, up to 20 LB, Replace	10	4	6	1	EA	\$166.05	\$166							\$166									\$166					\$33
D5022	1445656 Light Fixtu	ure, 150 WATT, Replace	20	17	3	1	EA	\$188.19	\$188				\$188																	\$18
D5022	1445652 Light Fixtu	ure, 150 WATT, Replace	20	3	17	1	EA	\$188.19	\$188																	\$188				\$18
D5029	1445651 Lighting S	System, Interior, Medium Density & Standard Fixtures, Replace	20	3	17	960	SF	\$8.86	\$8,502																	\$8,502				\$8,50
D5037	1479723 Fire Alarm	n System, Standard Addressable, Install	20	16	4	960	SF	\$4.43	\$4,251					\$4,251																\$4,25
Totals, Unes	calated									\$0	\$6,089	\$0	\$10,832	\$7,439	\$0	\$166	\$7,970 \$3,	,720	\$0 \$4,244	\$0	\$0	\$3,797	\$0	\$0	\$166	\$16,660	\$0	\$0	\$4,244	\$65,32
Totals, Escal	ated (3.0% inflation, c	compounded annually)								\$0	\$6,271	\$0	\$11,836	\$8,373	\$0 :	\$198	\$9,803 \$4,	,712	\$0 \$5,704	\$0	\$0	\$5,576	\$0	\$0	\$266	\$27,537	\$0	\$0	\$7,666	\$87,94

* Markup/LocationFactor (1.107) has been included in unit costs.

Indian Hills Elementary School / Portable Classroom #32

Uniformat Code	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	/Unit	Unit Cost *	Subtotal 2	019 2020	2021	2022	2023	2024 20	25 20	26 20	027 2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039 Deficiency Re	apair Estimat
B1015 1	445672 Exterior Stair/Ramp Rails, Wood, Refinish	10	7	3	20	LF	\$1.66	\$33			\$33									\$33								\$6
B2011 1	445670 Exterior Wall, Wood Shakes/Shingles, 1-2 Stories, Replace	30	27	3	1278	SF	\$8.30	\$10,611			\$10,611																	\$10,61
B2011 1	445671 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	0	10	1278	SF	\$3.32	\$4,244									\$4,244										\$4,244	\$8,488
B2021 1	445673 Single-Pane Exterior Window, 24 SF, Replace	30	17	13	2	EA	\$1,881.90	\$3,764												\$3,764								\$3,764
C3025 1	445668 Interior Floor Finish, Carpet Commercial Standard, Replace	10	3	7	960	SF	\$8.30	\$7,970						\$7,9	70									\$7,970				\$15,941
C3032 1	445667 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	17	8	960	SF	\$3.87	\$3,720							\$3,7	720												\$3,720
D3052 1	434199 Heat Pump, Wall-Mounted, 3.5 to 4 Ton, Replace	20	19	1	1	EA	\$6,088.50	\$6,089	\$6,089																			\$6,089
D4019 1	445676 Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	40	36	4	960	SF	\$3.32	\$3,188				\$3,188																\$3,188
D4031 1	479790 Fire Extinguisher, Type ABC, up to 20 LB, Replace	10	4	6	1	EA	\$166.05	\$166					\$1	66									\$166					\$332
D5022 1	445669 Light Fixture, 150 WATT, Replace	20	17	3	1	EA	\$188.19	\$188			\$188																	\$188
D5029 1	445664 Lighting System, Interior, Medium Density & Standard Fixtures, Replace	e 20	3	17	960	SF	\$8.86	\$8,502																\$8,502				\$8,502
D5037 1	479725 Fire Alarm System, Standard Addressable, Install	20	16	4	960	SF	\$4.43	\$4,251				\$4,251																\$4,251
Totals, Unescalat	ted								\$0 \$6,089	\$0	\$10,832	\$7,439	\$0 \$1	66 \$7,9	70 \$3,7	720 \$0	\$4,244	\$0	\$0	\$3,797	\$0	\$0	\$166	\$16,472	\$0	\$0	\$4,244	\$65,139
Totals, Escalated	I (3.0% inflation, compounded annually)								\$0 \$6,271	\$0	\$11,836	\$8,373	\$0 \$1	98 \$9,8	03 \$4,7	712 \$0	\$5,704	\$0	\$0	\$5,576	\$0	\$0	\$266	\$27,226	\$0	\$0	\$7,666	\$87,631

* Markup/LocationFactor (1.107) has been included in unit costs.

Indian Hills Elementary School / Portable Classroom #33

I IIIulali Hills	Elementary School / Portable Classicom #33																								
Uniformat Co	odeID Cost Description	Lifespan (EUL)EA	lge RL	JL Q	uantityU	nit Unit Cost *Subtota	al 2019 202	20 2021	2022	2023 202	4 2025	2026	2027	2028	2029 2	030 203	1 2032	2033	2034	2035	2036	2037	2038	2039 Deficiency	Repair Estimate
B1015	1445685 Exterior Stair/Ramp Rails, Wood, Refinish	10	7	3	20	LF \$1.66 \$3	3		\$33								\$33								\$67
B2011	1445683 Exterior Wall, Wood Shakes/Shingles, 1-2 Stories, Replace	30	27	3	1278	SF \$8.30 \$10,61	1	\$1	10,611																\$10,611
B2011	1445684 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	0	10	1278	SF \$3.32 \$4,24	4							\$	4,244								\$4	4,244	\$8,488
B2021	1445686 Single-Pane Exterior Window, 24 SF, Replace	30	17	13	2	EA \$1,881.90 \$3,76	4										\$3,764								\$3,764
C3025	1445681 Interior Floor Finish, Carpet Commercial Standard, Replace	10	3	7	960	SF \$8.30 \$7,97	0				,	\$7,970									\$7,970				\$15,941

https://www.assetcalc.net/Reports/ReplacementReserve.aspx

7/9

Uniformat Cod	eID Cost Description	Lifespan (EUL	.)EAge	RUL	Quantity	/Unit	Unit Cost *	Subtotal 2019	202	0 2021	2022	2023	2024	2025	2026 2	027	2028 2029	2030	2031	2032	2033	2034	203	5 2036	203	37 203	3 2039 Deficiency	Repair Estimate
C3032	1445680 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	17	8	960	SF	\$3.87	\$3,720							\$3,7	720												\$3,720
D3052	1434272 Heat Pump, Wall-Mounted, 3.5 to 4 Ton, Replace	20	19	1	1	EA	\$6,088.50	\$6,089	\$6,08	9																		\$6,089
D4019	1445689 Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	40	36	4	960	SF	\$3.32	\$3,188				\$3,188																\$3,188
D4031	1479791 Fire Extinguisher, Type ABC, up to 20 LB, Replace	10	4	6	1	EA	\$166.05	\$166						\$166									\$166	3				\$332
D5022	1445682 Light Fixture, 150 WATT, Replace	20	17	3	1	EA	\$188.19	\$188			\$188																	\$188
D5022	1445678 Light Fixture, 150 WATT, Replace	20	3	17	1	EA	\$188.19	\$188																\$188				\$188
D5029	1445677 Lighting System, Interior, Medium Density & Standard Fixtures, Replace	€ 20	3	17	960	SF	\$8.86	\$8,502																\$8,502				\$8,502
D5037	1479727 Fire Alarm System, Standard Addressable, Install	20	16	4	960	SF	\$4.43	\$4,251				\$4,251																\$4,251
Totals, Unesca	lated								\$0 \$6,08	9 \$0	\$10,832	\$7,439	\$0	\$166	\$7,970 \$3,	720	\$0 \$4,244	\$0	\$0	\$3,797	\$0	\$0	\$160	\$16,660	\$	0 \$0	\$4,244	\$65,328
Totals, Escala	red (3.0% inflation, compounded annually)								\$0 \$6,27	1 \$0	\$11,836	\$8,373	\$0	\$198	\$9,803 \$4,	712	\$0 \$5,704	\$0	\$0	\$5,576	\$0	\$0	\$260	\$27,537	\$	0 \$0	\$7,666	\$87,942

Indian H	ille Elomo	ntary Scho	ol / Dorto	hla Clace	200m #31

Uniformat Code	PID Cost Description	Lifespan (EUL)EAge	RUL	Quantit	/Unit	Unit Cost *Subtotal2	019 2020	2021 2022	2023 20	24 2	025 202	6 202	7 20:	28 2029	2030	2031	2032	2033	2034	203	5 2036	2037	2038	2039 Deficie	ncy Repair Estimat
B1015	1445698 Exterior Stair/Ramp Rails, Wood, Refinish	10	7	3	20	LF	\$1.66 \$33		\$33									\$33								\$67
B2011	1445696 Exterior Wall, Wood Shakes/Shingles, 1-2 Stories, Replace	30	27	3	1278	SF	\$8.30 \$10,611		\$10,611																	\$10,611
B2011	1445697 Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	0	10	1278	SF	\$3.32 \$4,244								\$4,244										\$4,244	\$8,488
B2021	1445699 Single-Pane Exterior Window, 24 SF, Replace	30	17	13	2	EA	\$1,881.90 \$3,764											\$3,764								\$3,764
C3025	1445694 Interior Floor Finish, Carpet Commercial Standard, Replace	10	3	7	960	SF	\$8.30 \$7,970					\$7,97	0									\$7,970				\$15,941
C3032	1445693 Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	17	8	960	SF	\$3.87 \$3,720						\$3,72	0												\$3,720
D3052	1434289 Heat Pump, Wall-Mounted, 3.5 to 4 Ton, Replace	20	19	1	1	EA	\$6,088.50 \$6,089	\$6,089																		\$6,089
D4019	1445702 Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	40	36	4	960	SF	\$3.32 \$3,188			\$3,188																\$3,188
D4031	1479792 Fire Extinguisher, Type ABC, up to 20 LB, Replace	10	4	6	1	EA	\$166.05 \$166				\$	166									\$166	3				\$332
D5019	1479728 Full Electrical System Upgrade, Low Density/Complexity, Replace	40	32	8	960	SF	\$14.39 \$13,815						\$13,81	5												\$13,815
D5022	1445695 Light Fixture, 150 WATT, Replace	20	17	3	1	EA	\$188.19 \$188		\$188																	\$188
D5029	1445690 Lighting System, Interior, Medium Density & Standard Fixtures, Repla	ice 20	3	17	960	SF	\$8.86 \$8,502															\$8,502				\$8,502
D5037	1479729 Fire Alarm System, Standard Addressable, Install	20	16	4	960	SF	\$4.43 \$4,251			\$4,251																\$4,251
Totals, Unescal	lated							\$0 \$6,089	\$0 \$10,832	\$7,439	\$0 \$	166 \$7,97	0 \$17,53	5 \$	\$0 \$4,244	\$0	\$0	\$3,797	\$0	\$0	\$160	\$16,472	\$0	\$0	\$4,244	\$78,955
Totals, Escalate	ed (3.0% inflation, compounded annually)							\$0 \$6,271	\$0 \$11,836	\$8,373	\$0 \$ ²	198 \$9,80	3 \$22,21	3 \$	\$0 \$5,704	\$0	\$0	\$5,576	\$0	\$0	\$260	\$27,226	\$0	\$0	\$7,666	\$105,132

* Markup/LocationFactor (1.107) has been included in unit costs.

Indian Hills Elementary School / Site

Uniformat CodeI	Cost Description	Lifespan (EUL)E	EAge	RUL	Quantity	Unit	Unit Cost *	Subtotal	2019	2020 202	1 202	2 2023	2024	2025 2	026	2027	2028	2029 203	0 203	1 2032	2033	3 2034	203	5 2036	2037	2038	2039 Defici	iency Repair Estimate
B1015 1	1441193 Exterior Stairs, Masonry, Replace	50	32	18	20	SF	\$44.28	\$886																	\$886			\$886
D2018 1	434203 Drinking Fountain, Outside/Site Style, Replace	15	10	5	5	EA	\$3,985.20	\$19,926					\$19,926													9	\$19,926	\$39,852
D5012 1	434138 Secondary Transformer, 150 kVA, Replace	30	28	2	1	EA	\$22,140.00	\$22,140		\$22,140)																	\$22,140
D5012 1	434187 Main Distribution Panel-400 AMP, 400 AMP, Replace	30	26	4	1	EA	\$6,642.00	\$6,642				\$6,642																\$6,642
D5012 1	434294 Building/Main Switchboard, 600 AMP, Replace	40	32	8	1	EA	\$49,815.00	\$49,815							\$49	9,815												\$49,815
G2022 1	434281 Parking Lots, Asphalt Pavement, Seal & Stripe	5	3	2	40985	SF	\$0.50	\$20,417		\$20,417	,			\$20,4	117				\$20,417					\$20,417				\$81,667
G2031 1	434144 Pedestrian Pavement, Sidewalk, Concrete Large Areas, Replace	50	32	18	26562	SF	\$9.96	\$264,637																	\$264,637			\$264,637
G2035 1	434107 Exterior Stairs & Ramps, Concrete (per LF of Nosing), Replace	50	32	18	200	LF	\$46.49	\$9,299																	\$9,299			\$9,299
G2041 1	434201 Fences & Gates, Chain Link, 6' High, Replace	40	32	8	3316	LF	\$23.25	\$77,087							\$77	7,087												\$77,087
G2041 1	434196 Fences & Gates, Metal Tube, 6' High, Replace	40	32	8	450	LF	\$44.28	\$19,926							\$19	9,926												\$19,926
G2044 1	434133 Signage, Property, Monument/Pylon, Replace/Install	20	17	3	1	EA	\$10,516.50	\$10,517			\$10,517																	\$10,517
G2044 1	480139 Signage, Property, Monument/Pylon, Replace	20	9	11	1	EA	\$10,516.50	\$10,517										\$10,51	7									\$10,517
G2045 1	434182 Site Furnishings, Picnic Table, Plastic-Coated Concrete, Replace	25	21	4	15	EA	\$1,549.80	\$23,247				\$23,247																\$23,247
G2045 1	434273 Site Furnishings, Picnic Table, Plastic-Coated Metal, Replace	25	9	16	6	EA	\$1,549.80	\$9,299															\$9,299	Э				\$9,299
G2047 1	434236 Play Surfaces & Sports Courts, Asphalt, Replace	25	25	0	2998	SF	\$7.20	\$21,572	\$21,572																			\$21,572
G2047 1	434255 Play Surfaces & Sports Courts, Asphalt, Seal & Stripe	5	3	2	30375	SF	\$0.50	\$15,098		\$15,098	3			\$15,0	98				\$15,098	1				\$15,098				\$60,391
G2047 1	434150 Sports Apparatus, Basketball Backstop, Replace	25	22	3	8	EA	\$10,516.50	\$84,132			\$84,132	!																\$84,132
G2047 1	434146 Play Structure, Swing Set only, 4 Seats, Replace	20	16	4	3	EA	\$2,767.50	\$8,303				\$8,303																\$8,303
G2047 1	443305 Play Surfaces & Sports Courts, Poured-in-place Rubber, Replace	20	16	4	2325	SF	\$23.25	\$54,049				\$54,049																\$54,049
G2047 1	434108 Play Surfaces & Sports Courts, Poured-in-place Rubber, Replace	20	15	5	6640	SF	\$23.25	\$154,360					\$154,360															\$154,360
G2047 1	434100 Play Structure, Swing Set only, 4 Seats, Replace	20	14	6	1	EA	\$2,767.50	\$2,768						\$2,768														\$2,768
G2047 1	1434118 Play Structure, Medium, Replace	20	4	16	1	EA	\$22,140.00	\$22,140															\$22,140	J				\$22,140
G2047 1	434216 Play Structure, Large, Replace	20	4	16	1	EA	\$38,745.00	\$38,745															\$38,74	5				\$38,745
G2048 1	434106 Flagpole, Metal, Replace	30	25	5	1	EA	\$2,767.50	\$2,768					\$2,768															\$2,768

Uniformat Co	deID	Cost Description	L	Lifespan (EUL)	EAge	RUL	Quantit	yUnit	Unit Cost	* Subtota	2019	20)20 202 ⁻	1 2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035 2036	2037	7 2038	2039 Defi	ciency Repair Estimate
G2049	1443	Dumpster Accessories, Enclosures, Concrete Block (CMU), 8' High, Re	place	40	25	15	50	LF	\$177.	12 \$8,85	6															\$8,856					\$8,856
G2057	1434	Irrigation System, , Replace/Install		25	32	0	45000	SF	\$3.8	\$174,35	3 \$174,35	53																			\$174,353
G4021	1434	Site Pole Light, 1000 WATT, Replace/Install		20	3	17	3	EA	\$4,649.4	40 \$13,94	-8																\$13,948				\$13,948
P000X	1480	80140 Engineer, Civil, Landscaping		0	32	0	1	EA	\$7,749.0	00 \$7,74	9 \$7,74	49																			\$7,749
Totals, Unesc	alated	1									\$203,67	74	\$0 \$57,654	\$94,649	\$92,241 \$	177,054	\$2,768	\$35,514	\$146,828	\$0	\$0	\$10,517 \$	5,514	\$0	\$0	\$8,856 \$70	0,184 \$49,463	\$274,822	\$0	\$19,926	\$1,279,662
Totals, Escal	ated (3.0	3.0% inflation, compounded annually)									\$203,67	74	\$0 \$61,166	\$103,425	103,818 \$	205,254	\$3,305	\$43,678	\$185,997	\$0	\$0	\$14,557 \$	0,635	\$0	\$0	\$13,797 \$112	2,624 \$81,754	\$467,865	\$0	\$35,989	\$1,687,538

Indian Hills Elementary School / Site Restrooms

Uniformat Code	eID	Cost Description	Lifespan (EUL)EAge	RUL	Quant	ityUnit	Unit Cost	*Subtotal 2019	9 2	020 20	21 20:	22 2023	2024	2025	2026	2027	2028	2029	2030	2031	2032 2033	2034	2035	2036	2037	2038 2039 Def	ficiency Repair Estimat
B2011	1434191	Exterior Wall, any Painted Surface, 1-2 Stories, Prep & Paint	10	0	10	100	B SF	\$3.3	2 \$3,348									\$	\$3,348								\$3,348	\$6,69
B2011	1434313	Exterior Wall, Wood Shakes/Shingles, 1-2 Stories, Replace	30	16	14	1008	3 SF	\$8.3	\$8,369													\$8,369						\$8,36
B3011	1434278	Roof, Single-Ply TPO/PVC Membrane, Replace	20	16	4	528	SF	\$18.8	2 \$9,936				\$9,936															\$9,93
C1031	1434306	Toilet Partitions, Plastic/Laminate, Replace	20	16	4	6	EA	\$830.2	5 \$4,982				\$4,982															\$4,982
C3012	1434299	Interior Wall Finish, Laminated Paneling (FRP), Replace	30	16	14	100	B SF	\$17.7	1 \$17,854													\$17,854						\$17,854
C3024	1434179	Interior Floor Finish, Linoleum, Replace	15	2	13	528	SF	\$3.8	7 \$2,046													\$2,046						\$2,04
C3032	1434225	Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	25	16	9	528	SF	\$3.8	7 \$2,046								\$2	2,046										\$2,04
D2011	1434232	Toilet, Commercial Water Closet, Replace	30	16	14	8	EA	\$1,439.1	\$11,513													\$11,513						\$11,51
D2012	1434285	Urinal, Standard, Replace	30	16	14	2	EA	\$1,217.7	\$2,435													\$2,435						\$2,43
D2014	1434178	Sink/Lavatory, Wall-Hung, Vitreous China, Replace	30	16	14	6	EA	\$1,660.5	\$9,963													\$9,963						\$9,96
D4019	1441195	Sprinkler System, Full Retrofit, Low Density/Complexity, Renovate	e 40	36	4	528	SF	\$3.3	2 \$1,753				\$1,753															\$1,75
D5022	1434175	Light Fixture, 100 WATT, Replace	20	9	11	4	EA	\$188.1	\$753											\$753								\$75
D5037	1479731	Fire Alarm System, Standard Addressable, Install	20	16	4	528	SF	\$4.4	3 \$2,338				\$2,338															\$2,338
Totals, Unescal	lated									\$0	\$0	\$0 \$	\$19,009	\$0	\$0	\$0	\$0 \$:	2,046	\$3,348	\$753	\$0	\$2,046 \$50,134	\$0	\$0	\$0	\$0	\$0 \$3,348	\$80,68
Totals, Escalate	ed (3.0% i	inflation, compounded annually)								\$0	\$0	\$0 \$	\$0 \$21,395	\$0	\$0	\$0	\$0 \$:	2,669	\$4,499	\$1,042	\$0	\$3,004 \$75,832	\$0	\$0	\$0	\$0	\$0 \$6,046	\$114,488

* Markup/LocationFactor (1.107) has been included in unit costs.

Appendix F: Equipment Inventory List

D20 PLUMBING											
Index ID	UFCode	Component	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1 1434170		Water Heater	10 GAL	Indian Hills Elementary School / Main Building	Main Building Supply Closet	Bradford White	RE110U6	MM37046421	2004		
2 1434283 3 1434148		Water Heater Water Heater	50 GAL 6 GAL	Indian Hills Elementary School / Main Building Indian Hills Elementary School / Main Building	Main Building Main Building Exterior Utility Closet	A. O. Smith	RE350T6-1NCWW ELJF 6 910	PJ40244161 MM95-0075199-S06	2002		
	D2023	Water neater	0 GAL	Indian miles Elementary School / Main building	Main Bullaing Exterior Outry Closet	A. O. Silliui	ELJF 6 9 10	WIWI95-0075199-500	2006		
D30 HVAC											
Index ID	UFCode	Component	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1 143422	D3042	Exhaust Fan	75 CFM	Indian Hills Elementary School / Main Building	Main Building Roof	Greenheck	Illegible	Illegible	2010		
2 143415		Exhaust Fan	75 CFM	Indian Hills Elementary School / Main Building	Main Building Roof	Greenheck	Illegible	Illegible	2010		
3 143426		Exhaust Fan	75 CFM	Indian Hills Elementary School / Main Building	Main Building Roof	Greenheck	Illegible	Illegible	2010		
4 143418		Exhaust Fan	75 CFM	Indian Hills Elementary School / Main Building	Main Building Roof	Greenheck	Illegible	Illegible	2010		
5 143424		Exhaust Fan	75 CFM	Indian Hills Elementary School / Main Building	Main Building Roof	Greenheck	Illegible	Illegible	2010		
6 1434169 7 1434269		Exhaust Fan Exhaust Fan	75 CFM 75 CFM	Indian Hills Elementary School / Main Building	Main Building Roof	Greenheck	Illegible	Illegible	2010		
8 143427		Exhaust Fan	75 CFM	Indian Hills Elementary School / Main Building	Main Building Roof	Greenheck Greenheck	Illegible Illegible	Illegible	2010		
9 143423		Exhaust Fan	75 CFM	Indian Hills Elementary School / Main Building Indian Hills Elementary School / Main Building	Main Building Roof Main Building Roof	Greenheck	Illegible	Illegible Illegible	2010		
10 143425		Exhaust Fan	75 CFM	Indian Hills Elementary School / Main Building	Main Building Roof	Greenheck	Illegible	Illegible	2010		
11 143426		Heat Pump [#18]	3.5 TON	Indian Hills Elementary School / Portable Classroom #18	Portable Building 18 Exterior	Bard Manufacturing Company	W42H1-A04VP4XXX EHWH04-A04	Illegible	2010		
12 143418		Heat Pump [#19]	3.5 TON	Indian Hills Elementary School / Portable Classroom #19	Portable Building 19 Exterior	Bard Manufacturing Company	W42H1-A04VP4XXX EHWH04-A04	Illegible			
13 144555		Heat Pump [#20]	3.5 TON	Indian Hills Elementary School / Portable Classroom #20	Portable Building 20 Exterior	Bard Manufacturing Company	W42H1-A04VP4XXX EHWH04-A04	Illegible			
14 144557	D3052	Heat Pump [#21]	3.5 TON	Indian Hills Elementary School / Portable Classroom #21	Portable Building 21 Exterior	Bard Manufacturing Company	W42H1-A04VP4XXX EHWH04-A04	Illegible			
15 144558		Heat Pump [#22]	3.5 TON	Indian Hills Elementary School / Portable Classroom #22	Portable Building 22 Exterior	Bard Manufacturing Company	W42H1-A04VP4XXX EHWH04-A04	Illegible			
16 144559		Heat Pump [#23]	3.5 TON	Indian Hills Elementary School / Portable Classroom #23	Portable Building 23 Exterior	Bard Manufacturing Company	W42H1-A04VP4XXX EHWH04-A04	Illegible			
17 144561		Heat Pump [#24]	3.5 TON	Indian Hills Elementary School / Portable Classroom #24	Portable Building 24 Exterior	Bard Manufacturing Company	W42H1-A04VP4XXX EHWH04-A04	Illegible			
18 143419		Heat Pump [#26]	3.5 TON	Indian Hills Elementary School / Portable Classroom #26	Portable Building 26	Bard Manufacturing Company	Illegible	Illegible			
19 1434119		Heat Pump [#27]	3.5 TON	Indian Hills Elementary School / Portable Classroom #27	Portable Building 27 Exterior	Bard Manufacturing Company	W42H1-A04VP4XXX EHWH42-A10	Inaccessible			
20 143427	D3052	Heat Pump [#28]	3.5 TON	Indian Hills Elementary School / Portable Classroom #28	Portable Building 28 Exterior	Bard Manufacturing Company	WH421-A10VX4XXX EHW42-A10	126C971093949 02			
21 143414		Heat Pump [#29]	3.5 TON	Indian Hills Elementary School / Portable Classroom #29	Portable Building 29 Exterior	Bard Manufacturing Company	HH421-A10V4XXX EHWH42-A10	126C971094469- 02			
22 143415	D3052	Heat Pump [#30]	3.5 TON	Indian Hills Elementary School / Portable Classroom #30	Portable Building 30 Exterior	Bard	WH421-A10VX4XXX EHWH42-A10	126J991366272-02			
23 143413	D3052	Heat Pump [#31]	3.5 TON	Indian Hills Elementary School / Portable Classroom #31	Portable Building 31 Exterior	Bard Manufacturing Company	WH421-A10VX4XXX EHWH42-A10	126J991369359-02			
24 143419	D3052	Heat Pump [#32]	3.52 TON	Indian Hills Elementary School / Portable Classroom #32	Portable Building 32 Exterior	Bard Manufacturing Company	WH421-A10VX4XXX	126J991369361 02			
25 143427	D3052	Heat Pump [#33]	3.5 TON	Indian Hills Elementary School / Portable Classroom #33	Portable Building 33 Exterior	Bard Manufacturing Company	WH421-A10UX4XXX	126F011629292-02			
26 143428	D3052	Heat Pump [#34]	3.5 TON	Indian Hills Elementary School / Portable Classroom #34	Portable Building 34 Exterior	Bard Manufacturing Company	WH421-A10VX4XXX	126F011635285-02			
27 143424	D3052	Packaged Unit (RTU)	10 TON	Indian Hills Elementary School / Main Building	Main Building Roof	ICP	PGE120L250AA-	G034530525			
28 143416	D3052	Packaged Unit (RTU)	12.5 TON	Indian Hills Elementary School / Main Building	Main Building Roof	Trane	YCD150D4LOAA	309100583D			
29 143410	D3052	Packaged Unit (RTU)	7.5 TON	Indian Hills Elementary School / Main Building	Main Building Roof	ICP	PGD090L200A	L0040 54781			
30 1434117	D3052	Packaged Unit (RTU)	7.5 TON	Indian Hills Elementary School / Main Building	Main Building Roof	ICP	YSC090A4ELA0000	807103095L			
31 143415	D3052	Packaged Unit (RTU)	7.5 TON	Indian Hills Elementary School / Main Building	Main Building Roof	Trane	Illegible	Illegible			
32 143412	D3052	Packaged Unit (RTU)	7.5 TON	Indian Hills Elementary School / Main Building	Main Building Roof	Trane	Illegible	Illegible			
33 143427	D3052	Packaged Unit (RTU)	7.5 TON	Indian Hills Elementary School / Main Building	Main Building Roof	ICP	YSC090A4ELA0000	7371025221			
34 143424	D3052	Packaged Unit (RTU)	7.5 TON	Indian Hills Elementary School / Main Building	Main Building Roof	ICP	PGE090L224AA	G041350468			
35 143425	D3052	Packaged Unit (RTU)	7.5 TON	Indian Hills Elementary School / Main Building	Main Building Roof	ICP	PGE090L 224AA	G034011188			
36 143425		Packaged Unit (RTU)	7.5 TON	Indian Hills Elementary School / Main Building	Main Building Roof	ICP	YSC090A4ELAD000	Illegible			
37 143416		Packaged Unit (RTU) [ACT RM 15]	4 TON	Indian Hills Elementary School / Main Building	Main Building Roof	Trane	4YCZ6048A4120CA	12084JDX9H	2012		
38 143423		Packaged Unit (RTU) [HALL 10-13]	3 TON	Indian Hills Elementary School / Main Building	Main Building Roof	Trane	4YCZ6036A1096BA	12094HGY9H	2012		
39 143421		Packaged Unit (RTU) [HALL 14-17]	4 TON	Indian Hills Elementary School / Main Building	Main Building Roof	Trane	4YCZ6048A4120CA	11193LLU9H	2012		
40 143425		Packaged Unit (RTU) [HALL 1-5]	3 TON	Indian Hills Elementary School / Main Building	Main Building Roof	Trane	4YCZ6036A1096BA	12094HG19H	2012		
41 1434303		Packaged Unit (RTU) [HALL 6-9]	3 TON	Indian Hills Elementary School / Main Building	Main Building Roof	Trane	4YCZ6036A1096BA	12094HG49H	2012		
42 1434170		Packaged Unit (RTU) [RM-10]	4 TON	Indian Hills Elementary School / Main Building	Main Building Roof Main Building Roof	Trane	4YCZ6048A4120CA	11333HR19H	2012		
43 143421 ⁻ 44 143428 ⁻		Packaged Unit (RTU) [RM-12]	4 TON 4 TON	Indian Hills Elementary School / Main Building Indian Hills Elementary School / Main Building		Trane Trane	4YCZ6048A4120CA 4YCZ6048A4120CA	11325HDT9H 11325HDW9H	2012		
45 143429		Packaged Unit (RTU) [RM-14] Packaged Unit (RTU) [RM-17]	4 TON	Indian Hills Elementary School / Main Building	Main Building Roof Main Building Roof	Trane	4YCZ6048A4120CA 4YCZ6048A4120CA	11192J7L9H	2012		
46 143419		Packaged Unit (RTU) [RM-3]	4 TON	Indian Hills Elementary School / Main Building	Main Building Roof	Trane	4YCZ6048A4120CA	12085JFM9H	2012		
47 143431		Packaged Unit (RTU) [RM-4]	4 TON	Indian Hills Elementary School / Main Building	Main Building Roof	Trane	4YCZ6048A4120CA	12085JFG9H	2012		
48 1434308		Packaged Unit (RTU) [RM-5]	4 TON	Indian Hills Elementary School / Main Building	Main Building Roof	Trane	4YCZ6048A4120CA	12085JFP9H	2012		
49 143415		Packaged Unit (RTU) [RM-6]	4 TON	Indian Hills Elementary School / Main Building	Main Building Roof	Trane	4YCZ6048A4120CA 4YCZ6048A4120CA	12085JFS9H	2012		
50 143409		Packaged Unit (RTU) [RM-7]	4 TON	Indian Hills Elementary School / Main Building	Main Building Roof	Trane	4YCZ6048A4120CA	12075HJX9H	2012		
51 143418		Packaged Unit (RTU) [RM-8]	4 TON	Indian Hills Elementary School / Main Building	Main Building Roof	Trane	4YCZ6048A4120CA	12075HJ49H	2012		
52 143420		Packaged Unit (RTU) [RM-9]	4 TON	Indian Hills Elementary School / Main Building	Main Building Roof	Trane	4YCZ6048A4120CA	11333HR09H	2012		
53 143425		Packaged Unit (RTU) [RSP]	3 TON	Indian Hills Elementary School / Main Building	Main Building Roof	Trane	4YCZ6036A1096BA	12094HG39H	2012		
D40 FIRE PRO		- , , , , , ,	-	,	5						
				0.4%				0.11			
Index ID	UFCode	Component	Capacity	Building (44)	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1 143421		Fire Extinguisher		Indian Hills Elementary School / Portable Classroom #18	Portable Building 18				2015		
2 143428		Fire Extinguisher		Indian Hills Elementary School / Main Building	Main Building				2015		25
3 144563		Fire Extinguisher		Indian Hills Elementary School / Portable Classroom #27	Portable Building 27				2015		
4 147979	P D4031	Fire Extinguisher		Indian Hills Elementary School / Portable Classroom #34	Portable Building 34				2015		

10/22/2019					inventory - AssetCALC						
5 1479789	D4031	Fire Extinguisher		Indian Hills Elementary School / Portable Classroom #30	Portable Building 30				2015		
6 1434102	D4031	Fire Extinguisher		Indian Hills Elementary School / Portable Classroom #28	Portable Building 28				2015		
7 1445590	D4031	Fire Extinguisher		Indian Hills Elementary School / Portable Classroom #23	Portable Building 23				2015		
8 1479791	D4031	Fire Extinguisher		Indian Hills Elementary School / Portable Classroom #33	Portable Building 33				2015		
9 1479790	D4031	Fire Extinguisher		Indian Hills Elementary School / Portable Classroom #32	Portable Building 30				2015		
10 1445639	D4031	Fire Extinguisher		Indian Hills Elementary School / Portable Classroom #29	Portable Building 29				2015		
11 1445562	D4031	Fire Extinguisher		Indian Hills Elementary School / Portable Classroom #21	Portable Building 21				2015		
12 1445576	D4031	-							2015		
		Fire Extinguisher		Indian Hills Elementary School / Portable Classroom #22	Portable Building 22						
13 1445548	D4031	Fire Extinguisher		Indian Hills Elementary School / Portable Classroom #20	Portable Building 20				2015		
14 1479793	D4031	Fire Extinguisher		Indian Hills Elementary School / Portable Classroom #31	Portable Building 31				2015		
15 1445534	D4031	Fire Extinguisher		Indian Hills Elementary School / Portable Classroom #19	Portable Building 19				2015		
16 1445604	D4031	Fire Extinguisher		Indian Hills Elementary School / Portable Classroom #24	Portable Building 24				2015		
17 1434132	D4031	Fire Extinguisher		Indian Hills Elementary School / Portable Classroom #26	Portable Building 26				2015		
D50 ELECTRICAL	L										
Index ID	UFCode	Component	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1 1434266	D5012	Building/Main Switchboard	600 AMP	Indian Hills Elementary School / Main Building	Main Building Electrical room	Square D	49-88640-1		1987		
2 1434294	D5012	Building/Main Switchboard [DB-1]	600 AMP	Indian Hills Elementary School / Site	Site	Square D	10553768-001		1987		
3 1434135	D5012	Main Distribution Panel-225 AMP [HB]	225 AMP	Indian Hills Elementary School / Main Building	Main Building	Square D	49-88640-03		1987		
4 1434105	D5012	· · ·	225 AMP		•	Square D	49-88640-03		1987		
		Main Distribution Panel-225 AMP [HP]		Indian Hills Elementary School / Main Building	Main Building	•		20			
5 1434187	D5012	Main Distribution Panel-400 AMP	400 AMP	Indian Hills Elementary School / Site	Site	Challenger	3SB40(42-42)R	3R	1987		
6 1434138	D5012	Secondary Transformer	150 kVA	Indian Hills Elementary School / Site	Site	Powersmiths	Esaver-80R-150-480-208	46318	2016		
7 1434298	D5012	Secondary Transformer		Indian Hills Elementary School / Site	Site	Powersmiths	Esaver-80R-45-480-208	46314	2016		
8 1434274	D5012	Secondary Transformer [T1/PNL LA]	45 kVA	Indian Hills Elementary School / Main Building	Main Building Roof		Esaver-80R-45-480-208	46317	2016		
9 1434134	D5012	Secondary Transformer [T2/PNL LB]	45 kVA	Indian Hills Elementary School / Main Building	Main Building Roof		Esaver-80R-45-480-208	46316	2016		
10 1434143	D5012	Secondary Transformer [T3/PNL LC]	45 kVA	Indian Hills Elementary School / Main Building	Main Building Roof		Esaver-80R-45-480-208	46315	2016		
11 1434175	D5022	Light Fixture	100 WATT	Indian Hills Elementary School / Site Restrooms	Site Restroom Exterior				2010		4
12 1434141	D5022	Light Fixture	100 WATT	Indian Hills Elementary School / Main Building	Main Building Exterior				2016		15
13 1434157	D5022	Light Fixture	150 WATT	Indian Hills Elementary School / Portable Classroom #30	Portable Building 30 Exterior				2002		
14 1445568	D5022	Light Fixture	150 WATT	Indian Hills Elementary School / Portable Classroom #21	Portable Building 21 Exterior				2016		
15 1445633	D5022	Light Fixture	150 WATT	Indian Hills Elementary School / Portable Classroom #27	Portable Building 27 Exterior				2016		
16 1445656	D5022	Light Fixture	150 WATT	Indian Hills Elementary School / Portable Classroom #31	Portable Building 31 Exterior				2002		
17 1434214	D5022	Light Fixture	150 WATT	Indian Hills Elementary School / Portable Classroom #18	Portable Building 18 Exterior				2016		
18 1445669	D5022	Light Fixture	150 WATT	Indian Hills Elementary School / Portable Classroom #32	Portable Building 32 Exterior				2002		
19 1434260	D5022	Light Fixture	150 WATT	Indian Hills Elementary School / Portable Classroom #26	Portable Building 26 Exterior				2016		
		-		•	· · · · · · · · · · · · · · · · · · ·				2016		
	D5022	Light Fixture	150 WATT	Indian Hills Elementary School / Portable Classroom #30	Portable Building 30						
21 1445652	D5022	Light Fixture	150 WATT	Indian Hills Elementary School / Portable Classroom #31	Portable Building 31				2016		
22 1445695	D5022	Light Fixture	150 WATT	Indian Hills Elementary School / Portable Classroom #34	Portable Building 34 Exterior				2002		
23 1445582	D5022	Light Fixture	150 WATT	Indian Hills Elementary School / Portable Classroom #22	Portable Building 22 Exterior				2016		
24 1445682	D5022	Light Fixture	150 WATT	Indian Hills Elementary School / Portable Classroom #33	Portable Building 33 Exterior				2002		
25 1445678	D5022	Light Fixture	150 WATT	Indian Hills Elementary School / Portable Classroom #33	Portable Building 33				2016		
26 1445596	D5022	Light Fixture	150 WATT	Indian Hills Elementary School / Portable Classroom #23	Portable Building 23 Exterior				2016		
27 1445540	D5022	Light Fixture	150 WATT	Indian Hills Elementary School / Portable Classroom #19	Portable Building 19 Exterior				2016		
28 1434152	D5022	Light Fixture	150 WATT	Indian Hills Elementary School / Portable Classroom #28	Portable Building 28 Exterior				2002		
29 1445647	D5022	Light Fixture	150 WATT	Indian Hills Elementary School / Portable Classroom #29	Portable Building 29 Exterior				2002		
30 1445554	D5022	Light Fixture	150 WATT	Indian Hills Elementary School / Portable Classroom #20	Portable Building 20 Exterior				2016		
31 1445610	D5022	Light Fixture	150 WATT	Indian Hills Elementary School / Portable Classroom #24	Portable Building 24 Exterior				2016		
32 1434120	D5022	Light Fixture	250 WATT	Indian Hills Elementary School / Main Building	Main Building Exterior				2015		10
33 1434123	D5037	Fire Alarm Control Panel		Indian Hills Elementary School / Main Building	Main Building Electrical room	Honeywell	5820XL		2010		
34 1434174	D5092	Emergency Light		Indian Hills Elementary School / Main Building	Main Building				2010		12
35 1434125	D5092	Exit Sign Light Fixture		Indian Hills Elementary School / Main Building	Main Building				2012		30
E10 EQUIPMENT				· · · · · · · · · · · · · · · · · · ·	-						
				- W.							
Index ID	UFCode	Component	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1 1434282	E1093	Commercial Dairy Cooler/Wells		Indian Hills Elementary School / Main Building	Main Building Kitchen	True Manufacturing Co	TMC -49	9282846	2010		
2 1434245	E1093	Commercial Food Warmer		Indian Hills Elementary School / Main Building	Main Building Kitchen	Cres Cor	Inaccessible	Inaccessible	1987		
3 1434115	E1093	Commercial Food Warmer		Indian Hills Elementary School / Main Building	Main Building Kitchen	Auto-Shaam	Inaccessible	Inaccessible	1987		
4 1434151	E1093	Commercial Food Warmer		Indian Hills Elementary School / Main Building	Main Building Kitchen				1987		
5 1434140	E1093	Commercial Freezer, 2-Door Reach-In		Indian Hills Elementary School / Main Building	Main Building Kitchen	Beverage-Air Corporation	EF48-1AS	6226806	2006		
6 1434194	E1093	Commercial Garbage Disposal, 1 to 3 HP		Indian Hills Elementary School / Main Building	Main Building Kitchen	InSinkErator	SS-100-18	175707	2017		
7 1434312	E1093	Commercial Refrigerator, 1-Door Reach-In		Indian Hills Elementary School / Main Building	Main Building Kitchen	True Manufacturing Co	T-23	8562545	2006		
G40 OTHER											
	LIES :			D 715							
Index ID	UFCode	Component	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1 1434265	G4021	Site Pole Light	1000 WATT	Indian Hills Elementary School / Site	Site				2016		3

10/22/2019